

SW 3-41-1-W5

CENTRAL REGION GEOHAZARD RISK ASSESMENT SITE INSPECTION FORM



HIGHWAY & KM PREVIOUS SITE NUMBER AND NAME INSPECTION DATE INSPECTION DATE C20 H771:02 Pavement May 12, 2004 LEGAL DESCRIPTION NAD 83 COORDINATES

E 698635

N 5820026

May 27, 2005 1

RISK ASSESMENT

CF:

PF: 9

9 TOTAL:

SUMMARY OF SITE INSTRUMENTATION:		INSPECTED BY:	
		ENCHAR	
N 1		ENVOIVE	
None		Stor M. MARCH	
		SE S AD	
		(21년 - 옷~) [2]	
LAST READING DATE:		Ŷ	
PRIMARY SITE ISSUE:			
THIMAITI ONE IOOOE.			
	Pavement distress/Frost Heave		
APPROXIMATE DIMENSIONS:			
	Fall 0000 (Dhasa 1 Ditah ra grading and a	ulu out in stall stiens)	
DATE OF ANY REMEDIAL ACTION:	Fall 2003 (Phase 1 – Ditch re-grading and culvert installation)		

YES X X	NO	Patch over new culvert	YES	NO X
		Patch over new culvert		Y
X				^
Х				
~		Minor ditch erosion is occurring	Х	
Х		The previously observed areas of standing water are now draining		Х
Х				Х
			edial ad	ction.
	X and p	X and photog	are now draining X and photographs	X







