


SITE NUMBER AND NAME <b>C14 H771:04</b>		HIGHWAY & KM	PREVIOUS INSPECTION DATE May 15, 2007	INSPECTION DATE <b>June 26, 2008</b>
LEGAL DESCRIPTION NW 34-45-1-W5	NAD 83 COORDINATES N 5868190 E 696622		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION:  1 Standpipe – dry at 7.6 m  LAST READING DATE:	INSPECTED BY: 
PRIMARY SITE ISSUE: Slope Instability/Culvert Distress	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Slope repaired using launched soil nails in summer 2007.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Pavement marked for patching.		X
Slope Movement	X		Slope nailed in June 2007. No movement is apparent.		X
Erosion		X			X
Seepage		X			X
Culvert Distress	X		Culvert is flowing. No significant changes to instability downstream of outlet.		X

<b>COMMENTS</b>
Refer to previous reports and attached photos.

Site C14 H771:04 Slide  
June 26, 2008



