


SITE NUMBER AND NAME C14 H771:04		HIGHWAY & KM	PREVIOUS INSPECTION DATE June 26, 2008	INSPECTION DATE June 5, 2009
LEGAL DESCRIPTION NW 34-45-1-W5	NAD 83 COORDINATES N 5868190 E 696622		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION: 1 Standpipe – dry at 7.6 m LAST READING DATE:	INSPECTED BY: 
PRIMARY SITE ISSUE: Slope Instability/Culvert Distress	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Slope repaired using launched soil nails in summer 2007.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Thin asphalt pavement patch was applied since the last inspection; some reflective cracking is appearing.	X	
Slope Movement	X		Slope nailed in June 2007. No movement is apparent.		X
Erosion		X			X
Seepage		X			X
Culvert Distress	X		Culvert is flowing. No significant changes to instability downstream of outlet.		X

COMMENTS
Refer to previous reports and photos.