


SITE NUMBER AND NAME H834:02 Frost Heave		HIGHWAY & KM 12	PREVIOUS INSPECTION DATE	INSPECTION DATE May 15, 2007
LEGAL DESCRIPTION	NAD 83 COORDINATES		RISK ASSESMENT PF: 9 CF: 3 TOTAL: 27	

SUMMARY OF SITE INSTRUMENTATION: None		INSPECTED BY: 
LAST READING DATE:		
PRIMARY SITE ISSUE: Frost Heave		
APPROXIMATE DIMENSIONS: Approximately 300 m long section.		
DATE OF ANY REMEDIAL ACTION:		

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Pavement distress due to frost heave. Cracks up to 50 mm wide were observed.		X
Slope Movement		X			X
Erosion		X			X
Seepage		X			X
Culvert Distress		X			X

COMMENTS
Refer to attached photographs.
It does not appear that drainage of the site can be improved and so insulation or material replacement remediation methods must be adopted.
It is recommended that the site be inspected in January / February 2008 to determine the extent of the heaving area.









