


SITE NUMBER AND NAME C50 H834:02 Frost Heave		HIGHWAY & KM 10 km N of H26	PREVIOUS INSPECTION DATE March 3, 2009	INSPECTION DATE June 5, 2009
LEGAL DESCRIPTION 6-48-18-W4	NAD 83 COORDINATES N 5886820 E 390560		RISK ASSESMENT PF: 9 CF: 4 TOTAL: 36	

SUMMARY OF SITE INSTRUMENTATION: None		INSPECTED BY: 
LAST READING DATE:		
PRIMARY SITE ISSUE: Uneven pavement due to frost heave and soft subgrade		
APPROXIMATE DIMENSIONS: 2.7 km long section of highway		
DATE OF ANY REMEDIAL ACTION:		

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		About 12 significant dips are present along road section.		X
Slope Movement					
Erosion					
Seepage					
Culvert Distress					

COMMENTS
The pavement distress areas should be marked out by the maintenance contract inspector in the winter and then inspected in the summer to determine if the distress still exists. This would determine if the distress is actually due to frost heave.