


SITE NUMBER AND NAME C40 H841:02 Slide		HIGHWAY & KM 11.7	PREVIOUS INSPECTION DATE Oct 11, 2005	INSPECTION DATE May 15, 2006
LEGAL DESCRIPTION 16-28-20-W4	NAD 83 COORDINATES N 5694845 E 376882		RISK ASSESMENT PF: 9 CF: 4 TOTAL: 36	

SUMMARY OF SITE INSTRUMENTATION: None		INSPECTED BY: 
LAST READING DATE:		
PRIMARY SITE ISSUE: Slope failure on east slope		
APPROXIMATE DIMENSIONS: 15 m wide (from highway edge down to culvert)		
DATE OF ANY REMEDIAL ACTION: Slope repaired Nov 2005 (Ledcor)		

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress					
Slope Movement					
Erosion					
Seepage					
Culvert Distress					

COMMENTS
Refer to previous callout report, construction report and attached photos
Repair work appears to have been successful, except that the slope seeding does not appear completed.











