

Slide Name: (GP 13) SH 722:02 Red Willow Creek
Inspection Date: N/A
Inspection By: N/A

1.0 BACKGROUND

Refer to EBA 2002 and earlier reports for site conditions and details of risk assessment. Some previous instrumentations were observed at this site during the 2000 annual site visit. No new instruments have been installed since 1996 (the onset of Regional Geotechnical Assignment). Attempts to locate information from previous instrumentation have not been successful.

2.0 OBSERVATIONS

- The site was not inspected in 2003 and 2004 annual inspections.
- Refer to previous observations as no obvious site deterioration was reported by MCI.

3.0 RISK ASSESSMENT

PF (5) * CF (3) = 15

Risk rating cannot be changed from the assessment in 2001.

4.0 ACTION

- Inspection of this site should be made in 2005 to observe any site deterioration.
- Maintenance forces are requested to record details of patch events (amount of settlement and quantity of patching) and submit the details for assessment.



Based on 1995 Aerial Photograph



Figure 1
Site Plan