

Bridge Culvert Inspection				
Bridge File Number	70256 -1 Bridge Culvert		Form Type	CUL1
Year Built	1986		Lot No.	2
Bridge or Town Name	HATTONFORD		Inspector Name	Kris Bosters
Located Over	TRIBUTARY TO PADDLE RIVER, 8.11.84.30.33, WATERCRS-ST		Inspector Class	BR CLS A
Located On	751:02 C1 29.574		Assistant Name	Brian Cote
Water Body Cl./Year			Assistant Class	BR CLS B
Navigabil. Cl./Year			Inspection Date	18-Apr-2013
Legal Land Location	NW SEC 22 TWP 56 RGE 11 W5M		Data Entry By	Lisa Fairhurst
Longitude, Latitude	-115:33:39, 53:51:32		Data Entry Date	24-Apr-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA12		Review Date	21-Apr-2013
Clear Roadway/Skew	9.5 / 20 deg. (RHF)		Dept. Reviewer Name	Brent Herrick
AADT/Year	200 / 2012 (A)		Dept. Review Date	01-May-2013
Road Classification	RCU-209-110		Follow-Up By	
Detour Length (km)	50			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1500	SP	51.2	152X51	2.8	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone		Gas	
Power	1 line OH, 30m East of c/l.		Municipal
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	Culvert installed on a curve. Limited sight distance, no passing.
Vertical Alignment		7	7	
Roadway Width (m)	9.500			
Embankment		7	7	
Sideslope ( __:1)	3.0			
(Height of Cover(m) : 6.5)				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>6</b>	<b>6</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		W		BF tag installed at crown.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	N	Snow covered. Debris appears to be lodged at inlet
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	50			
Scour Protection		7	N	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>500</b> )				
Scour/Erosion		7	N	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>6</b>	<b>6</b>	GR carried forward
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm):				<b>Rise (mm): 1500, Type: SP</b> )
Barrel Last Accessible Date	19-Nov-2009			Not accessible. Viewed from ends and shape appears OK
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		7	N	1.4%
Measured Rise (mm)	1479			
Measured At Ring No.	4			
Sag (mm)	21			
Percent Sag	1			
Sidewall		7	N	1.5%
Measured Span (mm)	1522			
Measured At Ring No.	4			
Deflection (mm)	22			
Percent Deflection	2			
Floor		8	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	N	
Separation (mm)	0			
Longitudinal Seams		8	N	1N
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		7	N	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	Yes			(700mm at outlet. Nov 19/2009)

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1500, Type: SP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type : )				
Waterway Adequacy		6	5	Scour pool forming d/s
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
<b>Barrel General Rating</b>		<b>7</b>	<b>N</b>	Last rated 7 on Nov 19/2009
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	N	
Heaving (mm)	0			
Invert Above/Below Stream Bed		BELOW		
Above/Below (mm)	400			
Scour Protection		5	N	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 500)				
Scour/Erosion		5	N	Scour pool appears to be forming d/s through snow
Beavers (Y/N)		No		
<b>Downstream End General Rating</b>		<b>5</b>	<b>5</b>	GR carried forward from Nov 19/2009
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		8	8	
HWM (m below Top of Culvert)	0.0			Drift at crown of upstream invert.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading		DEGRADING		
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2013						
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>77.8/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>70.3/57.0</b>	Est. Repl. Yr	2040	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Kris Bosters		Previous Assistant's Name	Sara Wadlow			
Next Inspection Date	18-Jul-2016		Previous Inspection Date	19-Nov-2009			
Inspection Cycle (Default) (months)	39						
Comment							