

| Bridge Culvert Inspection |  |                     |                |
|---------------------------|--|---------------------|----------------|
| Bridge File Number        | 71417 -2 Bridge Culvert                              | Form Type           | CULM           |
| Year Built                | 2011   | Lot No.             | 4              |
| Bridge or Town Name       | BAWLF  | Inspector Name      | Owen Salava    |
| Located Over              | TRIBUTARY TO DRIEDMEAT CREEK,<br>5.40.3, WATERCRS-ST | Inspector Class     | BR CLS A       |
| Located On                | 13:12 C1 18.137                                      | Assistant Name      |                |
| Water Body Cl./Year       |  | Assistant Class     |                |
| Navigabil. Cl./Year       |  | Inspection Date     | 27-Jun-2012    |
| Legal Land Location       | NW SEC 35 TWP 45 RGE 18 W4M                          | Data Entry By       | Marcia Chavez  |
| Longitude, Latitude       | -112:31:06, 52:55:49                                 | Data Entry Date     | 15-Jul-2012    |
| Road Authority            | Alberta Transportation (AIT)                         | Reviewer Name       | John O'Brien   |
| Contract Main. Area       | CMA16  | Review Date         | 05-Jul-2012    |
| Clear Roadway/Skew        | / 30 deg. (RHF)                                      | Dept. Reviewer Name | Andrew Smikles |
| AADT/Year                 | 3,150 / 2011 (A)                                     | Dept. Review Date   | 19-Jul-2012    |
| Road Classification       | RAU-211.8-110  | Follow-Up By        |                |
| Detour Length (km)        | 5  |                     |                |

**Bridge Culvert Information**

|                          |                             |      |                |      |        |               |                    |       |
|--------------------------|-----------------------------|------|----------------|------|--------|---------------|--------------------|-------|
| Number of Culverts       | 2                           |      |                |      |        |               |                    |       |
| Pipe #                   | Barrel                      | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1                        | MAIN                        | -    | 2740           | SP   | 45.72  | 152X51        | 3.0                | ROUND |
| 2                        | MAIN                        | -    | 2740           | SP   | 45.72  | 152X51        | 3.0                | ROUND |
| Special Features         |                             |      |                |      |        |               |                    |       |
| Special Features Comment | BF tag installed on N side. |      |                |      |        |               |                    |       |

**Utilities (Located at)**

|                     |               |               |    |
|---------------------|---------------|---------------|----|
| Utility Attachments |               |               |    |
| Telephone           | N ROW.        | Gas           |    |
| Power               | 1 wire 40m N. | Municipal     |    |
| Others              |               | Problem (Y/N) | No |
| Remarks             |               |               |    |

**Approach Road / Embankment**

|  | Last     | Now      | Explanation of Condition                   |
|--|----------|----------|--|
| Horizontal Alignment                             | 7        | 7        | Approach 100m W.<br>Middle of shallow sag. |
| Vertical Alignment                               | 7        | 7        |  |
| Roadway Width (m)                                | 11.000   |          |  |
| Embankment                                       | 7        | 7        |  |
| Sideslope (__:1)                                 | 4.0      |          |  |
| (Height of Cover(m) : 1)                         |          |          |  |
| Guardrail (Y/N)                                  | No       |          |  |
| <b>Approach Road / Embankment General Rating</b> | <b>7</b> | <b>7</b> |  |

**Upstream End**

| Culvert Component                             | Last  | Now | Explanation of Condition |
|---|-------|-----|--------------------------|
| (Pipe # : 1, Span Type: )                     |       |     |                          |
| Direction                                     | N     |     |                          |
| End Treatment (Concrete, Steel, Others, None) | STEEL |     |                          |
| Headwall                                      | X     | X   |                          |
| Collar  | X     | X   |                          |
| Wingwalls                                     | X     | X   |                          |
| (Shape : )                                    |       |     |                          |

| Upstream End  |             |          |          |                          |
|---|-------------|----------|----------|--------------------------|
| Culvert Component   |             | Last     | Now      | Explanation of Condition |
| (Pipe # : 1, Span Type: )   |             |          |          |                          |
| Cutoff Wall   |             | X        | X        |                          |
| Bevel End   |             | 9        | 9        |                          |
| Heaving (mm)  | 0           |          |          |                          |
| Invert Above/Below Stream Bed   | BELOW       |          |          |                          |
| Above/Below (mm)  | 500         |          |          |                          |
| Scour Protection  |             | 7        | 7        | Not keyed in.            |
| (Type : RIP RAP)  |             |          |          |                          |
| (Avg. Rock Size(mm) : 250)  |             |          |          |                          |
| Scour/Erosion   |             | 7        | 7        |                          |
| Beavers (Y/N)   | No          |          |          |                          |
| <b>Upstream End General Rating</b>  |             | <b>7</b> | <b>7</b> |                          |
| Bridge Culvert Barrel   |             |          |          |                          |
| Culvert Component   |             | Last     | Now      | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2740, Type: SP) |             |          |          |                          |
| Barrel Last Accessible Date   | 27-Jun-2012 |          |          |                          |
| <b>Special Features</b>   |             |          |          |                          |
| Special Feature   |             |          |          |                          |
| (Type : )   |             |          |          |                          |
| Special Feature   |             |          |          |                          |
| (Type : )   |             |          |          |                          |
| Roof  |             | 9        | 9        |                          |
| Measured Rise (mm)  | 2735        |          |          |                          |
| Measured At Ring No.  | 7           |          |          |                          |
| Sag (mm)  | 5           |          |          |                          |
| Percent Sag   | 0           |          |          |                          |
| Sidewall  |             | 9        | 9        |                          |
| Measured Span (mm)  | 2770        |          |          |                          |
| Measured At Ring No.  | 7           |          |          |                          |
| Deflection (mm)   | 30          |          |          |                          |
| Percent Deflection  | 1           |          |          |                          |
| Floor   |             | 9        | 9        |                          |
| Bulge (mm)  | 0           |          |          |                          |
| Measured At Ring No.  |             |          |          |                          |
| Abrasion (Y/N)  | No          |          |          |                          |
| Circumferential Seams   |             | 9        | 9        |                          |
| Separation (mm)   | 0           |          |          |                          |
| Longitudinal Seams  |             | 9        | 9        |                          |
| Total No. of Cracked Rings  | 0           |          |          |                          |
| Total No. of Rings with Two Cracked Seams   |             |          |          |                          |
| Min. Remaining Steel Between Cracks (mm)  |             |          |          |                          |
| Proper Lap (Y/N)  | Yes         |          |          |                          |
| Longitudinal Stagger (Y/N)  | Yes         |          |          | 2N                       |
| Coating   |             | 9        | 9        |                          |
| Corrosion By Soil (Y/N)   | No          |          |          |                          |
| Corrosion By Water (Y/N)  | No          |          |          |                          |

| Bridge Culvert Barrel   |     |          |          |                          |
|---|-----|----------|----------|--------------------------|
| Culvert Component   |     | Last     | Now      | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2740, Type: SP) |     |          |          |                          |
| Camber POS/ZERO/NEG   | POS |          |          |                          |
| Ponding (Y/N)   | Yes |          |          | 0.6m deep.               |
| Fish Passage Adequacy   |     | 8        | 8        |                          |
| Baffle  |     | X        | X        |                          |
| (Type : )   |     |          |          |                          |
| Waterway Adequacy   |     | 8        | 8        |                          |
| Icing (Y/N)   | No  |          |          |                          |
| Silting (Y/N)   | No  |          |          |                          |
| Drift (Y/N)   | No  |          |          |                          |
| <b>Barrel General Rating</b>  |     | <b>9</b> | <b>9</b> |                          |

| Bridge Culvert Barrel   |             |      |     |                          |
|---|-------------|------|-----|--------------------------|
| Culvert Component   |             | Last | Now | Explanation of Condition |
| (Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2740, Type: SP) |             |      |     |                          |
| Barrel Last Accessible Date   | 27-Jun-2012 |      |     |                          |
| <b>Special Features</b>   |             |      |     |                          |
| Special Feature   |             |      |     |                          |
| (Type : )   |             |      |     |                          |
| Special Feature   |             |      |     |                          |
| (Type : )   |             |      |     |                          |
| Roof  |             | 9    | 9   |                          |
| Measured Rise (mm)  | 2750        |      |     |                          |
| Measured At Ring No.  | 8           |      |     |                          |
| Sag (mm)  | 0           |      |     |                          |
| Percent Sag   | 0           |      |     |                          |
| Sidewall  |             | 9    | 9   |                          |
| Measured Span (mm)  | 2760        |      |     |                          |
| Measured At Ring No.  | 8           |      |     |                          |
| Deflection (mm)   | 20          |      |     |                          |
| Percent Deflection  | 1           |      |     |                          |
| Floor   |             | 9    | 9   |                          |
| Bulge (mm)  | 0           |      |     |                          |
| Measured At Ring No.  |             |      |     |                          |
| Abrasion (Y/N)  | No          |      |     |                          |
| Circumferential Seams   |             | 9    | 9   |                          |
| Separation (mm)   | 0           |      |     |                          |
| Longitudinal Seams  |             | 9    | 9   |                          |
| Total No. of Cracked Rings  | 0           |      |     |                          |
| Total No. of Rings with Two Cracked Seams   |             |      |     |                          |
| Min. Remaining Steel Between Cracks (mm)  |             |      |     |                          |
| Proper Lap (Y/N)  | Yes         |      |     |                          |
| Longitudinal Stagger (Y/N)  | Yes         |      |     | 2N                       |
| Coating   |             | 9    | 9   |                          |
| Corrosion By Soil (Y/N)   | No          |      |     |                          |
| Corrosion By Water (Y/N)  | No          |      |     |                          |

| Bridge Culvert Barrel   |     |          |          |                          |
|---|-----|----------|----------|--------------------------|
| Culvert Component   |     | Last     | Now      | Explanation of Condition |
| (Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2740, Type: SP) |     |          |          |                          |
| Camber POS/ZERO/NEG   | POS |          |          |                          |
| Ponding (Y/N)   | Yes |          |          | 0.6m                     |
| Fish Passage Adequacy   |     | 8        | 8        |                          |
| Baffle  |     | X        | X        |                          |
| (Type : )   |     |          |          |                          |
| Waterway Adequacy   |     | 8        | 8        |                          |
| Icing (Y/N)   | No  |          |          |                          |
| Silting (Y/N)   | No  |          |          |                          |
| Drift (Y/N)   | No  |          |          |                          |
| <b>Barrel General Rating</b>  |     | <b>9</b> | <b>9</b> |                          |

| Downstream End                                |       |          |          |                          |
|---|-------|----------|----------|--------------------------|
| Culvert Component                             |       | Last     | Now      | Explanation of Condition |
| (Pipe # : 2, Span Type: )                     |       |          |          |                          |
| Direction                                     |       | S        |          |                          |
| End Treatment (Concrete, Steel, Others, None) | STEEL |          |          |                          |
| Headwall                                      |       | X        | X        |                          |
| Collar  |       | X        | X        |                          |
| Wingwalls                                     |       | X        | X        |                          |
| (Shape : )                                    |       |          |          |                          |
| Cutoff Wall                                   |       | X        | X        |                          |
| Bevel End                                     |       | 9        | 9        |                          |
| Heaving (mm)                                  | 0     |          |          |                          |
| Invert Above/Below Stream Bed                 | BELOW |          |          |                          |
| Above/Below (mm)                              | 600   |          |          |                          |
| Scour Protection                              |       | 7        | 7        |                          |
| (Type : RIP RAP)                              |       |          |          |                          |
| (Avg. Rock Size(mm) : 250)                    |       |          |          |                          |
| Scour/Erosion                                 |       | 7        | 7        |                          |
| Beavers (Y/N)                                 | No    |          |          |                          |
| <b>Downstream End General Rating</b>          |       | <b>7</b> | <b>7</b> |                          |

| Structure Usage                           |      |      |     |                          |
|---|------|------|-----|--------------------------|
|   |      | Last | Now | Explanation of Condition |
| <b>Channel (U/S and D/S)</b>              |      |      |     |                          |
| Alignment                                 |      | 8    | 8   | Rail bridge 30m u/s.     |
| Bank Stability                            |      | 8    | 8   |                          |
| HWM (m below Top of Culvert)              |      |      |     | HWM not visible.         |
| Drift (Y/N)                               | No   |      |     |                          |
| Channel Bottom Degrading/Aggrading        | NONE |      |     |                          |
| Beavers (Y/N)                             | No   |      |     |                          |
| (Fish Compensation Measure 1 : Fish Pool) |      |      |     |                          |
| (Fish Compensation Measure 2 : NONE)      |      |      |     |                          |

| <b>Structure Usage</b>        |  |             |            |                                 |
|-------------------------------|--|-------------|------------|---------------------------------|
|                               |  | <b>Last</b> | <b>Now</b> | <b>Explanation of Condition</b> |
| <b>Channel General Rating</b> |  | <b>8</b>    | <b>8</b>   |                                 |

| Maintenance Recommendations                       |                    |  |                           |               |           |                   |    |
|---|--------------------|--|---------------------------|---------------|-----------|-------------------|----|
| Inspector Recommendations                         | Year               | Inspector Comments                       | Department Comments       | Target Year   | Est. Cost | Cat #             |    |
| SHOTCRETE REPAIRS                                 |                    |  |                           |               |           |                   |    |
| PLACE ADDITIONAL RIP RAP                          |                    |  |                           |               |           |                   |    |
| REMOVE DRIFT ACCUMULATION                         |                    |  |                           |               |           |                   |    |
| INSTALL CONCRETE/STEEL LINING                     |                    |  |                           |               |           |                   |    |
| INSTALL STRUTS                                    |                    |  |                           |               |           |                   |    |
| INSTALL CONCRETE COLLAR/CUTOFF                    |                    |  |                           |               |           |                   |    |
| REPAIR SEAMS                                      |                    |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                    |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                    |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                    |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                    |  |                           |               |           |                   |    |
| <b>Structural Condition Rating (Last/Now) (%)</b> | <b>100.0/100.0</b> | <b>Sufficiency Rating (Last/Now) (%)</b> | <b>91.0/91.0</b>          | Est. Repl. Yr | 2060      | Maint. Req. (Y/N) | No |
| Special Comments for Next Inspection              |                    |  | Department Comments       |               |           |                   |    |
| Maintenance Reviewed By                           |                    |  | Date                      |               |           | Estimated Total   | 0  |
| Proposed Long-Term Strategy                       |                    |  |                           |               |           |                   |    |
| On 3-Year Program (Y/N)                           |                    |  |                           |               |           |                   |    |
| Proposed Action                                   |                    |  |                           |               |           |                   |    |
| Previous Inspector's Name                         | Wade Nanninga      |  | Previous Assistant's Name |               |           |                   |    |
| Next Inspection Date                              | 27-Mar-2014        |  | Previous Inspection Date  | 16-Mar-2012   |           |                   |    |
| Inspection Cycle (Default) (months)               | 21                 |  |                           |               |           |                   |    |
| Comment   |                    |  |                           |               |           |                   |    |