

Bridge Culvert Inspection			
Bridge File Number	71575 -1 Bridge Culvert	Form Type	CUL1
Year Built	1972	Lot No.	4
Bridge or Town Name	HIGH RIVER	Inspector Name	Jon Davies
Located Over	TRIBUTARY TO TONGUE CREEK, 2.13.27.5.2, WATERCRS-ST	Inspector Class	BR CLS B
Located On	543:02 C1 19.288	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	24-Jan-2013
Legal Land Location	SE SEC 16 TWP 19 RGE 29 W4M	Data Entry By	Anne Roberts
Longitude, Latitude	-113:57:35, 50:36:06	Data Entry Date	21-Feb-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA27	Review Date	03-Feb-2013
Clear Roadway/Skew	8.3 /	Dept. Reviewer Name	Tim Davies
AADT/Year	2,520 / 2011 (A)	Dept. Review Date	04-Mar-2013
Road Classification	RLU-209-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2100	MP	29.6	68X13	3.5	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	South ditch	Gas		
Power	3 Wire - North	Municipal		
Others	Fibre optics North ROW	Problem (Y/N)	No	
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Hill to west poor sight distance
Vertical Alignment		6	6	
Roadway Width (m)	8.300			
Embankment		6	6	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 2)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		S		SOUTH
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		7	7	Rock covered by grass in bevel area.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 350)				
Scour/Erosion		8	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 2100 , Type: MP)				
Barrel Last Accessible Date	24-Jan-2013			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	7	
Measured Rise (mm)	2060			
Measured At Ring No.	4			
Sag (mm)	40			
Percent Sag	2			
Sidewall		7	6	
Measured Span (mm)	2210			
Measured At Ring No.	4			
Deflection (mm)	110			
Percent Deflection	5			
Floor		7	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	5	1st u/s coupler is bolted-Poor alignment R4 to D/S bevel 250 mm separation at floor, no infiltration.
Separation (mm)	250			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		6	6	Superficial corrosion on floor
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2100, Type: MP)				
Fish Passage Adequacy		X	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Siltting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	6	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		NORTH
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	6	
Heaving (mm)	300			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	300			
Scour Protection		8	6	Rock filled scour hole
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 350)				
Scour/Erosion		8	6	
Beavers (Y/N)	No			
Downstream End General Rating		7	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	Turns 90 deg. at fence line d/s.
Bank Stability		8	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/66.7	Sufficiency Rating (Last/Now) (%)	78.0/71.6	Est. Repl. Yr	2023	Maint. Req'd. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Rex Davidson		Previous Assistant's Name				
Next Inspection Date	24-Apr-2016		Previous Inspection Date	27-Nov-2009			
Inspection Cycle (Default) (months)	39						
Comment							