

Bridge Culvert Inspection				
Bridge File Number	72350 -1 Bridge Culvert		Form Type	CUL1
Year Built	1995		Lot No.	2
Bridge or Town Name	IRON SPRINGS		Inspector Name	Jason Rusu
Located Over	LNI - IRRIGATION C, WATERCRS-IC		Inspector Class	BR CLS A
Located On	25:02 C1 35.944		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	09-Dec-2011
Legal Land Location	SW SEC 29 TWP 11 RGE 20 W4M		Data Entry By	Anne Roberts
Longitude, Latitude	-112:42:16, 49:55:53		Data Entry Date	17-Jan-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA25		Review Date	26-Dec-2011
Clear Roadway/Skew	11 / -30 deg. (LHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	830 / 2010 (A)		Dept. Review Date	18-Jan-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	3			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	3000	2400	PCB	34.2			RECTANGLE
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments				
Telephone	SOUTH ROW		Gas	
Power	3 WIRE NORTH ROW		Municipal	
Others	Supernet fibre North ditch		Problem (Y/N)	No
Remarks				

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	
Vertical Alignment		8	8	
Roadway Width (m)	11.000			
Embankment		8	8	
Sideslope ( _ :1)	2.0			
(Height of Cover(m) : <b>0.9</b> )				
Guardrail (Y/N)	Yes			
<b>Approach Road / Embankment General Rating</b>		<b>8</b>	<b>8</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		X	X	Because of skew and length of barrel the box extends into the channel reducing entrance efficiencies
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		7	N	Snow covered
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>350</b> )				
Scour/Erosion		7	N	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>7</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3000, Rise (mm): 2400, Type: PCB)				
Barrel Last Accessible Date	09-Dec-2011			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		N	7	
Measured Rise (mm)	2400			
Measured At Ring No.	1			
Sag (mm)	0			
Percent Sag				
Sidewall		N	7	
Measured Span (mm)	3000			
Measured At Ring No.	1			
Deflection (mm)	0			
Percent Deflection				
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	6	Foam added to all circumferential seams
Separation (mm)	25			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		X	X	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
<b>(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 3000, Rise (mm): 2400, Type: PCB)</b>				
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		9	9	
Icing (Y/N)	No			
Siltting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>N</b>	<b>7</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		X	X	Because of the skew and length of barrel, the box extends into the channel reducing exit efficiencies and contributing to corner eddy currents.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		7	N	Snow covered
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>400</b> )				
Scour/Erosion		7	N	Snow covered
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>7</b>	<b>N</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		9	9	
Bank Stability		5	3	SW ditch drainage erosion contributing to bank instability
HWM (m below Top of Culvert)				(HWM 1.4) 27-may-2008
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>9</b>	<b>3</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2012	Place 2.5 m 3 class 2 rip rap at SW ditch drainage outlet.					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>74.0/78.3</b>	Est. Repl. Yr	2046	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Rusu		Previous Assistant's Name				
Next Inspection Date	09-Sep-2013		Previous Inspection Date	06-Jun-2010			
Inspection Cycle (Default) (months)	21						
Comment							