

Bridge Culvert Inspection			
Bridge File Number	07265 -2 Bridge Culvert	Form Type	CUL1
Year Built	2010	Lot No.	3
Bridge or Town Name	BLUFFTON	Inspector Name	Owen Salava
Located Over	2ND ORDER TRIBUTARY TO BATTLE RIVER, 5.60.1, WATERCRS-ST	Inspector Class	BR CLS A
Located On	771:03 C1 18.295	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	05-Feb-2013
Legal Land Location	NW SEC 22 TWP 44 RGE 1 W5M	Data Entry By	Marcia Chavez
Longitude, Latitude	-114:04:27, 52:48:27	Data Entry Date	22-Feb-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA18	Review Date	13-Feb-2013
Clear Roadway/Skew		Dept. Reviewer Name	Chris Black
AADT/Year	250 / 2011 (A)	Dept. Review Date	14-Mar-2013
Road Classification	RAU-209-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	3353	SP	48	152X51	4.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	W side of road.	Gas		
Power	15m W of c/l - 3 wire o/h.	Municipal		
Others		Problem (Y/N)	No	
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	7% hill to N; limited sight distance.
Vertical Alignment		5	5	
Roadway Width (m)	7.000			
Embankment		N	7	Snow covered.
Sideslope (__:1)	2.0			Estimated.
(Height of Cover(m) : 4.5)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		5	5	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		8	8	
Collar		N	N	Snow covered.
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		N	N	Ice covered.

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	Silt fence at u/s.
Heaving (mm)	200			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	150			
Scour Protection		N	N	Snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	N	Snow covered.
Beavers (Y/N)	No			
Upstream End General Rating		8	8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3353, Type: SP)				
Barrel Last Accessible Date	05-Feb-2013			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	Could not measure due to ice.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		8	8	Span at R11=3405=52mm=1.6%.
Measured Span (mm)	3405			
Measured At Ring No.	11			
Deflection (mm)	52			1.6%
Percent Deflection	2			
Floor		N	N	Ice covered.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	8	
Separation (mm)	0			
Longitudinal Seams		8	8	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			2N
Longitudinal Stagger (Y/N)	Yes			
Coating		8	8	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3353, Type: SP)				
Fish Passage Adequacy		8	8	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	8	Silt fence at outlet.
Heaving (mm)	100			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	200			
Scour Protection		N	N	Snow covered.
(Type : RIP RAP)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	N	Snow covered.
Beavers (Y/N)	No			
Downstream End General Rating		8	8	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5	6	
Bank Stability		5	6	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	Yes			Construction silt fence still in place.
Channel Bottom Degrading/Aggrading				Unknown
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Remove u/s & d/s silt fence.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	86.2/86.8	Est. Repl. Yr	2060	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Saly		Previous Assistant's Name				
Next Inspection Date	05-May-2016		Previous Inspection Date	24-Nov-2011			
Inspection Cycle (Default) (months)	39						
Comment							