

Bridge Inspection									
Bridge File Number	73631 -1 Bridge				Form Type	PCS			
Year Built/Year Supstr	1974/1974				Lot No.	4			
Bridge or Town Name	WILD HORSE				Inspector Name	Jason Rusu			
Located Over	TRIBUTARY TO SAGE CREEK, 29.6, WATERCRS-ST				Inspector Class	BR CLS A			
Located On	41:02 C1 13.975				Assistant Name				
Water Body Cl./Year					Assistant Class				
Navigabil. Cl./Year					Inspection Date	15-Jan-2012			
Legal Land Location	NE SEC 7 TWP 2 RGE 2 W4M				Data Entry By	Alyssa Boynton			
Longitude, Latitude	-110:15:07, 49:06:44				Data Entry Date	01-Mar-2012			
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Garry Roberts			
Contract Main. Area	CMA23				Review Date	24-Jan-2012			
Clear Roadway/Skew	11 /				Dept. Reviewer Name	Tim Davies			
AADT/Year	150 / 2010 (A)				Dept. Review Date	11-Mar-2012			
Road Classification	RLU-209G-90				Follow-Up By				
Detour Length (km)	27								
Allowable Load (t):	Single	CS1 28		Semi	CS2 49		Train	CS3 62	
Design Loading:	HS25							----> On Critical Spans ---->Critical Member	
								----> Primary Span	
Posting Information									
Required Load Posting (t)	Single			Semi			Truck Train		
Posted Loading (t)	Single			Semi			Truck Train		
Posted:	Lane	NB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Posted:	Lane	SB	At Junction (Y/N)	No	In Advance (Y/N)	No	At Bridge (Y/N)	No	
Remarks	Not required								
Hazard Marker At Bridge (Y/N)	Yes								
Remarks									
Other Sign Types									
Utilities (Located at)									
Utility Attachments									
Telephone	West ditch.				Gas				
Power					Municipal				
Others					Problem (Y/N)	No			
Remarks									
Approach Road									
			Last	Now	Explanation of Condition				
Horizontal Alignment			8	8	In sag curve, good sight distance				
Vertical Alignment			7	7					
Roadway Width (m)	9.200				NE approach road void in ACP 70mm deep, 150mm wide				
Approach Bump			7	4					
Guardrail (Y/N)	Yes								
Guardrail			7	7	Not thriebeam				
Length (m)	12.000								
Current Standard (Y/N)	No								
Termination Type	TURNED DOWN								
Drainage			7	7					
<b>Approach Road General Rating</b>			<b>7</b>	<b>7</b>					

Superstructure					
Bridge Component		Last	Now	Explanation of Condition	
(Primary Span : <b>VH, 3 Spans, Lengths(m): 6.1-6.1-6.1, A-Ident Number: )</b>					
<b>Special Features</b>					
Special Feature			X		
(Type : )					
Special Feature			X		
(Type : )					
Wearing Surface/Deck Top Detail Ratings					
	N (%)	1 (%)	2 (%)	3 (%)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0.0	0.0	0.0	0.0	
Wearing Surface			4	4	Cold patch/seal joint cracks @ both ends
(Material Type : <b>ACP</b> )					
(Thickness(mm) : <b>50</b> )					
Lateral Connection Problem (Y/N)		No			
Deck Top			N	N	
Deck Rideability			8	7	
Deck Joints			N	N	ANGLES @ ENDS OF GIRDERS
Bump (Y/N)		Yes			
Deck Drainage			7	7	
Drains Clogged (Y/N)		No			
Curbs/Median			6	6	
(Curb Type : <b>Standard</b> )					
Scaling (Percent Area)		1			
Bridge Rail			8	7	2 LAYER
(Type : <b>GALVANIZED STEEL FLEX BEAM</b> )					
Bridge Rail Posts			8	7	
(Type : <b>GALVANIZED POST STEEL;GALVANIZED POST STEEL</b> )					
Bridge Rail/Posts Coating			8	7	
(Type : <b>GALVANIZED</b> )					
Sidewalk			X	X	
Girder Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0	0	0	0	
Girders			4	4	Wide Crack in sound concrete both legs S1G12, S1G8, S1G6 2 GIRDRS SPALLS @ WEBS @ LOW COVER REBAR-1 @ EA END SPAN in one leg Wide cracks in sound concrete 1 leg S1G7, S1G9, S1G13, S1G2, S1G5, S3G4, S3G11
Last Complete Inspection Date		15-Jan-2012			
Cracking (Y/N)		Yes			
Spalling (Percent Area)		2			
Lift or Connector Pocket Grouted (Y/N)		Yes			
(Number Of Girders : <b>39</b> )					
<b>Span Alignment Problems</b>					
Vertical (Y/N)		Yes			West Side North Span - minor
Horizontal (Y/N)		No			
<b>Superstructure General Rating</b>			<b>4</b>	<b>4</b>	

Substructure					
Bridge Component		Last	Now	Explanation of Condition	
<b>Abutments</b>					
(Extended Backwall Piles (Y/N) : <b>N</b> )					
(Extended Backwall Piles Spacing(mm) : )					
(Total Number of Caps/Corbels : <b>1:1</b> )					
Bearing Seats/Caps/Corbels Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0	0	0	0	
Bearing Seats/Caps/Corbels			7	7	
(Type : <b>STEEL</b> )					
(Depth(mm) : <b>309</b> )					
(Width(mm) : <b>309</b> )					
Backwalls/Breastwalls			7	7	
Greatest Height (m)		1.40			
Wingwalls			5	5	
(Total Number of Bearing Piles : <b>9:9</b> )					
Piles Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>	18	0	0	0	
<b>Now</b>	18	0	0	0	
Piles			N	N	
Paint/Coating			X	X	
Abutment Stability			6	6	
Scour/Erosion			7	7	
<b>Piers/Bents</b>					
(Type : <b>PIER-COLUMN</b> )					
(Total Number of Caps/Corbels : <b>1:1</b> )					
Bearing Seats/Caps/Corbels Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0	0	0	0	
Bearing Seats/Caps/Corbels			7	7	
(Type : <b>STEEL</b> )					
(Depth(mm) : <b>309</b> )					
(Width(mm) : <b>309</b> )					
(Total Number of Bearing Piles : <b>9:9</b> )					
Piles Detail Ratings					
	N (count)	1 (count)	2 (count)	3 (count)	
<b>Last</b>	0	0	0	0	
<b>Now</b>	0	0	0	0	
Pier Shaft/Piles			5	5	
Greatest Height (m)		2.60			
Bracing/Struts/Sheathing			7	6	
Nose Plate			X	X	
Paint/Coating			X	X	
(Colour Description : )					
(Colour Code : )					

Substructure				
Bridge Component		Last	Now	Explanation of Condition
Pier Stability		7	7	
Scour		7	7	
Debris (Y/N)	No			
<b>Substructure General Rating</b>		<b>5</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel</b>				
(U/S Direction : <b>W</b> )				DRY STREAMBED
(D/S Direction : <b>E</b> )				
Alignment		7	7	SOME SPARSE CLASS 2 @ TOE.
Bank Stability		7	7	
HWM (m below Top of Curb)	3.0			No visible HWM.
Drift (Y/N)	No			
Slope Protection		7	7	
(Type : <b>NATURAL; NATURAL</b> )				
Guidebank/Spurs		X	X	
Adequacy of Opening		8	8	
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
REPAIR/REPLACE BRIDGE RAIL							
SEAL CURBS							
PATCH DECK							
OVERLAY DECK							
STRAIGHTEN/REPLACE MEMBERS							
WASHING							
SHOTCRETE REPAIRS							
CORE TIMBER CAPS/CORBELS							
REPAIR/REPLACE TIMBER CAPS							
REPAIR ABUTMENT SCOUR/EROSION							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL STRUTS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>50.0/50.0</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>65.0/64.9</b>	Est. Repl. Yr	2023	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Rusu		Previous Assistant's Name				
Next Inspection Date	15-Oct-2013		Previous Inspection Date	06-Aug-2010			
Inspection Cycle (Default) (months)	21						
Comment							