

Bridge Culvert Inspection			
Bridge File Number	73895 -2 Bridge Culvert	Form Type	CUL1
Year Built	2001	Lot No.	4
Bridge or Town Name	MANYBERRIES	Inspector Name	Jon Davies
Located Over	IRRIGATION CREEK, 11.1.1, WATERCRS-ST	Inspector Class	BR CLS B
Located On	889:02 C1 5.901	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	24-Jun-2012
Legal Land Location	NW SEC 6 TWP 6 RGE 5 W4M	Data Entry By	Lauren Korte
Longitude, Latitude	-110:40:43, 49:26:54	Data Entry Date	26-Jul-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA24	Review Date	09-Jul-2012
Clear Roadway/Skew	6.5 /	Dept. Reviewer Name	Tim Davies
AADT/Year	100 / 2011 (A)	Dept. Review Date	30-Jul-2012
Road Classification	RCU-208-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2400	MP	38	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	West ROW.	Gas		
Power	West ROW and crossing 50m South.	Municipal		
Others	Fibre optic cable East ROW.	Problem (Y/N)	No	
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	
Vertical Alignment		8	8	
Roadway Width (m)	8.000			
Embankment		8	8	
Sideslope (__:1)	4.0			
(Height of Cover(m) : 1.9)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		8	8	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction				East.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
Upstream End General Rating		8	8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2400, Type: MP)				
Barrel Last Accessible Date	24-Jun-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	Shape is excellent.
Measured Rise (mm)	2410			
Measured At Ring No.	1			
Sag (mm)	10			
Percent Sag	1			
Sidewall		8	8	Inward.
Measured Span (mm)	2392			
Measured At Ring No.	1			
Deflection (mm)	8			
Percent Deflection	1			
Floor		8	8	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	7	
Separation (mm)	40			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		8	8	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2400, Type: MP)				
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction				West.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	7	
Heaving (mm)	50			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		8	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		8	7	
Beavers (Y/N)	No			
Downstream End General Rating		8	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	NONE			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	9	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	87.8/88.3	Est. Repl. Yr	2046	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	24-Sep-2015		Previous Inspection Date	14-Jun-2009			
Inspection Cycle (Default) (months)	39						
Comment							