Bridge Culvert Inspection													
Bridge File Number 73917 -1 Bridge Culvert			ulvert			Form Type		CUL1					
Year Built 1987			-			Lot No.		4					
Bridge or Town Name COCH			OCHRANE				Inspector N	ame	Garry Roberts				
Located Over TRAIL-			RAIL-ANIMAL, OVER SP				Inspector C	Inspector Class BR CLS A					
Located On		1A:06 C	06 C1 8.759				Assistant N	ame					
Water Body Cl.					Assistant C	lass							
Navigabil. Cl./Y	ear						Inspection I	Date	29-Aug-2012				
Legal Land Loc	ation	SE SEC	2 18 TWP 2	26 RGE 4 W5	М		Data Entry	Ву	Lauren Korte				
Longitude, Latitude -114:32			:24, 51:13:	07			Data Entry Date 28-Sep-2012						
Road Authority Alberta			Transporta	tion (AIT)			Reviewer N	Reviewer Name Tom Carey					
Contract Main. Area CMA28							Review Date 04-Sep-2012						
Clear Roadway	/Skew	11.6 /					Dept. Reviewer Name Tim Davies						
AADT/Year		3,890 / 2	2011 (A)				Dept. Review Date 02-Oct-2012						
Road Classifica	ation	RAU-21	0-110				Follow-Up By						
Detour Length	(km)	15											
Bridge Culvert	Inform	ation											
Number of Culv	/erts		1										
Pipe #	Barrel		Span	Rise (or	Rise (or Dia.)		Len	gth	Corr. Profile	PI./Slab Thickness	Shape		
1	MAIN		-	2200		MP	30		125X26	2.8	ROUND		
Special Feature	es												
Special Feature	es Comr	ment											
					De	otin a la							
Required Vert.	Clearan	co Posti	ng (m)		PO	sung n	nformation						
Posted Vertical Clearance (Y/N) In Advance (Y/N) Lane SB On Bridge (m) In Advance (Y/N)													
Remarks Not required. Utilities (Located at)													
Utility Attachme	ents												
Telephone													
Power	North	row.					Municipal	/unicipal					
Others							Problem (Y	/N) No					
Remarks							·						
				A	pproad	ch Road	d / Embankn	nent					
					Last	Now	Explanatio		tion				
Horizontal Aligr	nment				7	7	On grade, hill to East. Limited sight distance.						
Vertical Alignme	ent				6	6							
Roadway Width	n (m)		11.600										
Embankment	Embankment				7	7							
Sideslope (<u>.</u> :1)		4.0										
(Height of Co	ver(m) :	2.6)											
Guardrail (Y/N)			Yes										
Approach Road / Embankment General Rating		6	6										
Upstream End													
Culvert Component			Now		Explanation of Condition								
Direction							North end.						
End Treatment (Concrete, Steel, NONE Others, None)													
Headwall				X	X								
Collar				X	Х								

Alberta Transportation

	Upstream End									
Culvert Component		Last	Now	Explanation of Condition						
Wingwalls			X							
(Shape :)										
Cutoff Wall		Х	X							
Bevel End		Х	X							
Heaving (mm)	0									
Invert Above/Below Stream Bed	BELOW									
Above/Below (mm)	400									
Scour Protection		7	7							
(Туре :)										
(Avg. Rock Size(mm) :)										
Scour/Erosion		7	7							
Beavers (Y/N)	No									
Upstream End General Rating		7	7							
		Brid	lge Cu	lvert Barrel						
Culvert Component		Last	Now	Explanation of Condition						
(Pipe # : 1, Primary Span, Locat	tion Code: MAIN, Spa	n (mm):	, Rise (mm): 2200, Type: MP)						
Barrel Last Accessible Date	29-Aug-2012									
Special Features										
Special Feature										
(Type:)		1								
Special Feature										
(Туре :)										
Roof		8	8	Estimate.						
Measured Rise (mm)										
Measured At Ring No.										
Sag (mm)	20									
Percent Sag										
Sidewall		8	8							
Measured Span (mm)	2220									
Measured At Ring No.	3									
Deflection (mm)	20									
Percent Deflection	1									
Floor		N	N	100mm deep gravel.						
Bulge (mm)										
Measured At Ring No.										
Abrasion (Y/N)										
Circumferential Seams		8	5	Minor soil infiltration at seam between R3 and R4, East haunch.						
Separation (mm) 30			-							
Longitudinal Seams			X							
Total No. of Cracked Rings										
Total No. of Rings with Two Cracked Seams										
Min. Remaining Steel Between Cracks (mm)										
Proper Lap (Y/N)										
Longitudinal Stagger (Y/N)										
Coating		7	7							
Corrosion By Soil (Y/N)	No									
Corrosion By Water (Y/N)	No									

Alberta Transportation

Bridge Inspection & Maintenance System (Web 2005)

73917 -1 Bridge Culvert

		Brid	dqe Cu	Ivert Barrel				
Culvert Component		Last Now						
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Spa			, Rise (mm): 2200, Type: MP)				
Camber POS/ZERO/NEG	ZERO							
Ponding (Y/N)	No							
Fish Passage Adequacy		X	X					
Baffle		X	Х					
(Туре:)								
Waterway Adequacy		X	Х					
Icing (Y/N)	No							
Silting (Y/N)	No							
Drift (Y/N)	No							
Barrel General Rating	1	8	8					
		П	ownst	ream End				
Culvert Component			Now	Explanation of Condition				
Direction				South.				
End Treatment (Concrete, Steel, Others, None)	NONE							
Headwall		X	Х					
Collar		X	X					
Wingwalls		X	X					
(Shape :)			~					
Cutoff Wall			X					
Bevel End		X	Х					
Heaving (mm)								
Invert Above/Below Stream Bed	BELOW							
Above/Below (mm)	300							
Scour Protection		7	7					
(Type : RIP RAP)								
(Avg. Rock Size(mm) : 200)								
Scour/Erosion		7	7					
Beavers (Y/N)	eavers (Y/N) No							
Downstream End General Ratin	ng	7	7					
		S	Structu	re Usage				
			Now	Explanation of Condition				
Grade Separation								
Road Alignment			Х					
Roadway Surface			7					
(Type : GRAVEL)								
Icing (Y/N) No								
Traffic Safety Features		X	X					
Туре								
Lighting		X	X					
Barrel Leakage (Y/N) No								

Structure Usage									
		Last	Now	Explanation of Condition					
Drainage			6						
Structure In Use (Y/N) Yes									
Grade Separation General Rati	ng	6	6						

Maintenance Recommendations												
Inspector Recommendations		Year	Inspector Comments		Department Comr	Target Year	Est. Cost	Cat #				
SHOTCRETE REPAIRS												
PLACE ADDITIONAL RIP RAP												
REMOVE DRIFT ACCUMULATION												
INSTALL CONCRETE/STEEL LINING												
INSTALL STRUTS												
INSTALL CONCRETE COLLAR/CUTO	FF											
REPAIR SEAMS												
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
Structural Condition Rating (Last/No (%)	w)	88.9/88.9	9 Sufficiency Rating (Last/N (%)	low)	87.3/87.3	/87.3 Est. Repl. Yr 2035		Maint. Reqd. (Y/N)		No		
Special Comments for Next Inspection					Department Comments							
Maintenance Reviewed By					Date		E	Estimated Total	0			
Proposed Long-Term Strategy												
On 3-Year Program (Y/N)												
Proposed Action												
Previous Inspector's Name Ga		Roberts		Previous								
Next Inspection Date 2		29-May-2014			Previous Inspection Date 24-Nov-2010							
Inspection Cycle (Default) (months) 21												
Comment												