

Bridge Culvert Inspection			
Bridge File Number	74008 -1 Bridge Culvert	Form Type	CUL1
Year Built	1985	Lot No.	4
Bridge or Town Name	TRIANGLE	Inspector Name	Brian Pientsch
Located Over	TRIBUTARY TO LITTLE SMOKY RIVER, 8.10.58.7.16, WATERCRS-ST	Inspector Class	BR CLS A
Located On	747:02 C1 21.647	Assistant Name	Lisbeth Medina
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	30-Nov-2010
Legal Land Location	NW SEC 28 TWP 72 RGE 19 W5M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-116:52:23, 55:16:20	Data Entry Date	03-Jan-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA06	Review Date	20-Dec-2010
Clear Roadway/Skew	10 /	Dept. Reviewer Name	David Morrison
AADT/Year	490 / 2009 (A)	Dept. Review Date	31-Mar-2011
Road Classification	RCU-210-110	Follow-Up By	
Detour Length (km)	26		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1829	SP	61.6	152X51	3.0	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	15m along West ditch.	Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	8	8	In gentle sag curve, passing both directions.
Vertical Alignment	7	7	
Roadway Width (m)	10.000		
Embankment	7	7	
Sideslope ( __:1)	5.0		
(Height of Cover(m) : 5)			
Guardrail (Y/N)	No		
<b>Approach Road / Embankment General Rating</b>	<b>7</b>	<b>7</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	E		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	7	South side pushing in approx 200mm.
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			(92/04/27)
Above/Below (mm)	300			
Scour Protection		N	7	Rock along sides of bevel and top of culvert only-seams to be placed to control previous erosion along sides of bevel.
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>500</b> )				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>1829</b> , Type: <b>SP</b> )				
Barrel Last Accessible Date	14-Dec-2001			Shape of barrel looks adequate as viewed from u/s end. Thin ice -600mm to crown from 2nd ring.
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		6	6	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		6	6	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		N	N	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		5	5	(Superficial rust, bottom half, above ice line.) Viewed from ends.
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1829, Type: SP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		4	5	
Baffle		N	N	
(Type : )				
Waterway Adequacy		7	7	Minor drift at the u/s end.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
<b>Barrel General Rating</b>		<b>6</b>	<b>N</b>	GR 6-24-Jul-2007
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		N	7	Rated based on 50% visibility.
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	700			
Scour Protection		8	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		8	7	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>8</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		7	7	
Bank Stability		7	6	
HWM (m below Top of Culvert)				HWM not visible. Minor drift at u/s invert.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

<b>Structure Usage</b>				
		<b>Last</b>	<b>Now</b>	<b>Explanation of Condition</b>

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>66.7/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>65.3/65.1</b>	Est. Repl. Yr	2030	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Brian Pientsch		Previous Assistant's Name	Tim Miskiman			
Next Inspection Date	28-Feb-2014		Previous Inspection Date	24-Jul-2007			
Inspection Cycle (Default) (months)	39						
Comment							