

Bridge Culvert Inspection				
Bridge File Number	07410 -1 Bridge Culvert		Form Type	CULM
Year Built	1949		Lot No.	1
Bridge or Town Name	COUTTS		Inspector Name	Jason Rusu
Located Over	TRIBUTARY TO MILK RIVER, 1.11, WATERCRS-ST		Inspector Class	BR CLS A
Located On	500:02 C1 18.654		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	08-Jun-2012
Legal Land Location	SE SEC 18 TWP 1 RGE 13 W4M		Data Entry By	Kelsey Roberts
Longitude, Latitude	-111:43:41, 49:01:41		Data Entry Date	16-Jul-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA24		Review Date	10-Jun-2012
Clear Roadway/Skew	7.3 /		Dept. Reviewer Name	Tim Davies
AADT/Year	110 / 2011 (A)		Dept. Review Date	17-Jul-2012
Road Classification			Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information

Number of Culverts	3							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1200	MP	14.6			ROUND
2	MAIN	-	1200	MP	14.6			ROUND
3	MAIN	-	1200	MP	14.6			ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	South Row	Gas	
Power	North row	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	8	8	Residential access east side
Vertical Alignment	8	8	
Roadway Width (m)	8.000		
Embankment	7	7	height of cover 3.6
Sideslope (__:1)	2.0		
(Height of Cover(m) : 3.6)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	8	8	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)			
Direction	N		North 1st west pipe
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		6	6	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	50			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		5	5	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Barrel Last Accessible Date				Both west pipes are 1/2 full
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	N	Viewed from ends West pipe appears as negative sag at Mid-span.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		N	N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Coating		N	N	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	5	
Icing (Y/N)	No			
Siltting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		N	N	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		5	5	
Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		N		2nd pipe from west
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	3	Bevel end is completely detached
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		5	3	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Barrel Last Accessible Date				Not bridge sized - water too high
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		N	N	
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		N	N	
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		N	N	
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		N	N	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Coating		X	N	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		5	N	
(Type :)				
Waterway Adequacy		X	5	
Icing (Y/N)	No			
Siltting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		5	N	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		5	5	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Span Type: Secondary Span)				
Direction		N		3rd pipe from west
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Span Type: Secondary Span)				
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	4	Uncoupled from barrel
Heaving (mm)	50			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		5	4	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Barrel Last Accessible Date	08-Jun-2012			Nor bridge sized
Special Features				
Special Feature				3rd pipe 75mm East of West pipes 1&2.
(Type :)				
Special Feature				
(Type :)				
Roof		N	3	at D/S 1/3 with negative sag and 200mm diameter hole in roof.
Measured Rise (mm)	1068			
Measured At Ring No.				
Sag (mm)	132			
Percent Sag	11			
Sidewall		N	4	at D/S 1/3
Measured Span (mm)	1325			
Measured At Ring No.				
Deflection (mm)	125			
Percent Deflection	10			
Floor		N	5	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	N	
Separation (mm)				
Longitudinal Seams		X	5	Riveted Pipe
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1200, Type: MP)				
Coating		N	N	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	5	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		5	3	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Span Type: Secondary Span)				
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		5	5	

Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5	5	Bend u/s
Bank Stability		5	5	
HWM (m below Top of Culvert)				No visible HWM
Drift (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Channel Bottom Degrading/Aggrading	NONE			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS	2012	Re-fasten bevel ends to barrel					
OTHER ACTION	2012	Schedule replacement.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/33.3	Sufficiency Rating (Last/Now) (%)	56.5/44.8	Est. Repl. Yr	2020	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	08-Sep-2015		Previous Inspection Date	17-Jun-2009			
Inspection Cycle (Default) (months)	39						
Comment							