					Bridg	ge Culve	ert Insp	ection					
Bridge File Number 74182 -1 Bridge Culvert						Гуре	CUL1	CUL1					
Year Built 1953						Lot No.		4	4				
Bridge or Town Name PINCHER CREE						Inspector Name		Jason Rusu					
Located Over TRAIL-ANIMAL, OVER SP			>		Inspec	tor Class	BR CLS A						
Located On 6:04 C1 20.758						Assista	ant Name						
Water Body Cl./Year						Assista	ant Class						
Navigabil. Cl./Year						Inspection Date		30-Oct-2011					
Legal Land Location NE SEC 17 TWP 4 RGE 29 W4M				/4M		Data Entry By		Erin Roberts					
Longitude, Latitude -113:52:02, 49:18:06						Data Entry Date		29-Nov-2011					
Road Authority Alberta Transportation (AIT)						Reviewer Name		Garry Roberts					
Contract Main. Area CMA26						Review Date		12-Nov-2011	-				
Clear Roadway	/Skew	9.8 /					Dept. F	Dept. Reviewer Name Tim Davies					
AADT/Year		1,010 /	2010 (A)				Dept. Review Date		01-Dec-2011				
Road Classifica		RAU-2					Follow-Up By						
Detour Length ((km)	8											
Bridge Culvert		ation											
Number of Culv	erts/		1										
Pipe #	Barrel		Span	Rise (d	or Dia.)	Dia.) Type		Length	Corr. Profile	PI./Slab Thickness	Shape		
1	MAIN		1980	1980		BP		21.3					
Special Feature	es												
Special Feature	es Comn	nent											
Deguired Vert	Claaran	oo Doot	ing (m)		Po	sting Ir	normat	ion					
Required Vert. Posted Vertical													
Posted: Lane			Bridge (m)	In A	dvance	(V/NI)	1	ane SB	On Bridge (m)	In Advor	nce (Y/N)		
Remarks	Not red		blidge (III)	III A	uvance	(1/11)	L	arie Sb	On Bridge (III)	III Auvai	ice (1/N)		
Remarks	Not let	ч.			114	ilities (L	oostod	(ot)					
Utility Attachme	ante				Οι	IIIues (L	-ocateu	al)					
Telephone	West	ditch					Gas						
Power	VVCSCC	aitori.					Munici	nal					
Others						m (Y/N) No							
Remarks							1 TODIC	111 (1714) 140					
rtomanto					Approa	ch Road	d / Emb	ankment					
					Last	Now		nation of Con	dition				
Horizontal Align	nment				4	4	Sharp	Sharp curve to North, posted 85km/hr.					
Horizontal Alignment Vertical Alignment		6	6	Hill to	Hill to South. Steep grade to NW.								
Roadway Width (m) 9.800													
Embankment					6	6							
Sideslope (·1)		3.0										
(Height of Co		1 2)	0.0										
Guardrail (Y/N)		1.2)	Yes										
Approach Roa	ıd / Emb	ankme	nt General	Rating	4	4							
						Upstre	am End						
Culvert Compo	onent				Last	Now		nation of Con	dition				
Direction								West.					
End Treatment Others, None)	(Concre	ete, Stee	el, CONCR	ETE				Medium scaling to 25% exposing the rebar. Rebar had insufficient cover. One 300mm spalled area.					
Headwall					4	4							

74182 -1 Bridge Culvert

			Upstre	am End
Culvert Component		Last	Now	Explanation of Condition
Collar		Х	Х	
Wingwalls		6	6	
(Shape:)		1	1	
Cutoff Wall		Х	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		7	7	
(Type:)				
(Avg. Rock Size(mm):)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
		Brid	dae Cu	lvert Barrel
Culvert Component			Now	Explanation of Condition
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN. Spa			
Barrel Last Accessible Date	30-Oct-2011		,	,,
Special Features	ı			
Special Feature				
(Type:)				
Special Feature				
(Type:)				
Roof		7	7	
Measured Rise (mm)	1980			
Measured At Ring No.	1			
Sag (mm)	0			
Percent Sag				
Sidewall		7	7	Narrow Vertical cracks in wall (typical).
Measured Span (mm)	1980			
Measured At Ring No.	1			
Deflection (mm)	0			
Percent Deflection				
Floor		6	6	Longitudinal cracks along entire length of floor.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	5	Minor soil infiltration 150mm high @ South @ center seam.
Separation (mm)	20			J
Longitudinal Seams		Х	Х	
Total No. of Cracked Rings	0			1
Total No. of Rings with Two	0			
Cracked Seams Min. Remaining Steel	0			
Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)	I			

		Brid	dge Cu	Ivert Barrel
Culvert Component				Explanation of Condition
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Spa	ın (mm): 1980	, Rise (mm): 1980, Type: BP)
Coating		Х	Х	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		Х	Х	
Baffle		Х	Х	
(Type:)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
		D	ownstr	ream End
Culvert Component		Last	Now	Explanation of Condition
Direction				East end.
End Treatment (Concrete, Steel, Others, None)	CONCRETE			
Headwall		5	5	Wide cracks and minor spalling
Collar		Х	Х	
Wingwalls		6	6	
(Shape:)				
Cutoff Wall		Х	Х	
Bevel End		Х	Х	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	50			
Scour Protection		Х	X	
(Type:)				
(Avg. Rock Size(mm):)				
Scour/Erosion		Х	Х	
Beavers (Y/N)	No			
Downstream End General Ratio	ng	5	5	
		5	Structu	re Usage
			Now	Explanation of Condition
Grade Separation				
Road Alignment		Х	Х	
Roadway Surface		7	7	Sparse gravel 25mm deep.
(Type:)				
Icing (Y/N)	No			
Traffic Safety Features		Х	Х	
Туре				

Structure Usage								
		Last	Now	Explanation of Condition				
Lighting		X	X					
Barrel Leakage (Y/N) No								
Drainage		7	7					
Structure In Use (Y/N) Yes								
Grade Separation General Rating			7					

		Maintena	nce Recommendation	S					
Inspector Recommendations	Year	Inspector Comments	Dep	artment Comm	ents		Target Year	Est. Cost	Cat #
SHOTCRETE REPAIRS									
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL CONCRETE/STEEL LINING	3								
INSTALL STRUTS									
INSTALL CONCRETE COLLAR/CUT	OFF								
REPAIR SEAMS									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/N (%)	low) 77.8/77	7.8 Sufficiency Rating (%)	(Last/Now) 67.6/6	67.6	Est. Repl. Yr	2030	Maint. Red	qd. (Y/N)	No
Special Comments for Next Inspection			Dep	artment nments					
Maintenance Reviewed By			Date	Э		E	stimated Total	0	
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name	Garry Roberts		Previous Assis	tant's Name					
Next Inspection Date	30-Jul-2013		Previous Inspe	ction Date	19-Oct-2009				
Inspection Cycle (Default) (months)	21		<u>.</u>						
Comment									