

Bridge Culvert Inspection				
Bridge File Number	74212 -2 Bridge Culvert		Form Type	CUL1
Year Built	2005		Lot No.	4
Bridge or Town Name	CHERRILL		Inspector Name	Eric Carcoux
Located Over	TRIBUTARY TO COYOTE CK, 8.11.84.40.2, WATERCRS-ST		Inspector Class	BR CLS A
Located On	43:20 R1 4.300;43:20 L1 4.291		Assistant Name	Brian Cote
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	26-Aug-2011
Legal Land Location	SW SEC 1 TWP 56 RGE 5 W5M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-114:36:51, 53:48:12		Data Entry Date	27-Sep-2011
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Arnold Assenheimer
Contract Main. Area	CMA12		Review Date	26-Sep-2011
Clear Roadway/Skew	12.4 /		Dept. Reviewer Name	Brent Herrick
AADT/Year	6,380 / 2010 (A)		Dept. Review Date	28-Sep-2011
Road Classification	RAU-213.4-120		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1800	MP	81	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	South r/w.		Gas	
Power	3 lines OH.--r/w		Municipal	
Others	Pipeline 60m East. Railroad at South boundry.		Problem (Y/N)	No
Remarks				

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Horizontal curve to West.
Vertical Alignment	9	9	
Roadway Width (m)	12.400		WBL & EBL 12.4m each.
Embankment	8	8	6:1 in median.
Sideslope (__:1)	4.0		
(Height of Cover(m) : 3.8)			
Guardrail (Y/N)	Yes		
Approach Road / Embankment General Rating	7	7	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	S		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	450			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
Upstream End General Rating		8	8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 1800 , Type: MP)				
Barrel Last Accessible Date	11-Nov-2009			Not accessible
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	8	Shape looks good from ends.
Measured Rise (mm)	1785			
Measured At Ring No.	2			
Sag (mm)	15			
Percent Sag	1			
Sidewall		8	8	
Measured Span (mm)	1813			
Measured At Ring No.	2			
Deflection (mm)	13			
Percent Deflection	1			
Floor		8	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	N	
Separation (mm)	0			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		8	8	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	N	GR 8-11-Nov-2009
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	450			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
Downstream End General Rating		8	8	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	Bend D/S.
Bank Stability		8	8	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/55.6	Sufficiency Rating (Last/Now) (%)	82.8/64.8	Est. Repl. Yr	2055	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Melanie Johnson		Previous Assistant's Name				
Next Inspection Date	26-May-2013		Previous Inspection Date	11-Nov-2009			
Inspection Cycle (Default) (months)	21						
Comment							