

Bridge Culvert Inspection			
Bridge File Number	74295 -1 Bridge Culvert	Form Type	CUL1
Year Built	1954	Lot No.	
Bridge or Town Name	WEMBLEY	Inspector Name	Eric Carcoux
Located Over	TRIBUTARY TO BEAVERLODGE RIVER, 8.10.58.18.8.1.3, WATERCRS-ST	Inspector Class	BR CLS A
Located On	43:02 C1 5.408	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	29-Apr-2013
Legal Land Location	SW SEC 31 TWP 71 RGE 9 W6M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-119:22:23, 55:11:15	Data Entry Date	29-Apr-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	
Contract Main. Area	CMA05	Review Date	
Clear Roadway/Skew	12.3 /	Dept. Reviewer Name	
AADT/Year	7,430 / 2012 (A)	Dept. Review Date	
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2014	2226	SPE	76.2	152X51	3.0	ELLIPSE
Special Features		STORM WATER DRAIN						
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	
Remarks			

Approach Road / Embankment				
	Last	Now	Explanation of Condition	
Horizontal Alignment	7			
Vertical Alignment	8			
Roadway Width (m)				
Embankment	7			
Sideslope (__:1)				
(Height of Cover(m) : 11.5)				
Guardrail (Y/N)				
Approach Road / Embankment General Rating	7			

Upstream End				
Culvert Component	Last	Now	Explanation of Condition	
Direction	N			
End Treatment (Concrete, Steel, Others, None)				
Headwall	X			
Collar	X			
Wingwalls	X			
(Shape :)				
Cutoff Wall	X			

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		3		
Heaving (mm)				
Invert Above/Below Stream Bed				
Above/Below (mm)				
Scour Protection		4		
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		4		
Beavers (Y/N)				
Upstream End General Rating		3		

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2014, Rise (mm): 2226, Type: SPE)				
Barrel Last Accessible Date				
Special Features				
Special Feature		6		
(Type : STORM WATER DRAIN)				
Special Feature				
(Type :)				
Roof		N		
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		3		
Measured Span (mm)				
Measured At Ring No.				
Deflection (mm)				
Percent Deflection				
Floor		3		
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		6		
Separation (mm)				
Longitudinal Seams		4		
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		3		
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				
Camber POS/ZERO/NEG				
Ponding (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2014, Rise (mm): 2226, Type: SPE)				
Fish Passage Adequacy		3		
Baffle		X		
(Type :)				
Waterway Adequacy		4		
Icing (Y/N)				
Siltng (Y/N)				
Drift (Y/N)				
Barrel General Rating		3		
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)				
Headwall		X		
Collar		X		
Wingwalls		N		
(Shape :)				
Cutoff Wall		X		
Bevel End		4		
Heaving (mm)				
Invert Above/Below Stream Bed				
Above/Below (mm)				
Scour Protection		4		
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 500)				
Scour/Erosion		4		
Beavers (Y/N)				
Downstream End General Rating		4		
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5		
Bank Stability		4		
HWM (m below Top of Culvert)				
Drift (Y/N)				
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)				
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4		

Maintenance Recommendations						
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #
SHOTCRETE REPAIRS						
PLACE ADDITIONAL RIP RAP						
REMOVE DRIFT ACCUMULATION						
INSTALL CONCRETE/STEEL LINING						
INSTALL STRUTS						
INSTALL CONCRETE COLLAR/CUTOFF						
REPAIR SEAMS						
OTHER ACTION						
OTHER ACTION						
OTHER ACTION						
OTHER ACTION						
Structural Condition Rating (Last/Now) (%)	33.3/	Sufficiency Rating (Last/Now) (%)	26.1/	Est. Repl. Yr		Maint. Req. (Y/N)
Special Comments for Next Inspection			Department Comments			
Maintenance Reviewed By			Date		Estimated Total	0
Proposed Long-Term Strategy						
On 3-Year Program (Y/N)						
Proposed Action						
Previous Inspector's Name	Brian Pientsch		Previous Assistant's Name	Brian Cote		
Next Inspection Date	29-Jan-2015		Previous Inspection Date	04-Jul-2011		
Inspection Cycle (Default) (months)	21					
Comment						