

Bridge Culvert Inspection			
Bridge File Number	74682 -1 Bridge Culvert	Form Type	CUL1
Year Built	1957	Lot No.	3
Bridge or Town Name	CARBON	Inspector Name	Owen Salava
Located Over	TRIBUTARY TO KNEEHILLS CREEK, 3.46.9, WATERCRS-ST	Inspector Class	BR CLS A
Located On	21:14 C1 17.666	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	18-Sep-2012
Legal Land Location	NW SEC 6 TWP 30 RGE 23 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-113:14:20, 51:32:31	Data Entry Date	03-Oct-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA20	Review Date	27-Sep-2012
Clear Roadway/Skew	9.9 / 0 deg.	Dept. Reviewer Name	Andrew Smikles
AADT/Year	2,490 / 2011 (A)	Dept. Review Date	16-Oct-2012
Road Classification	RAU-210-110	Follow-Up By	
Detour Length (km)	5		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1724	1901	SPE	53.6	152X51	2.8	ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments				
Telephone	West r/w.	Gas		
Power		Municipal		
Others	Fibre optic E r/w.	Problem (Y/N)	No	
Remarks				

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	Curves both ends - good sight distance.
Vertical Alignment		7	7	No passing SB.
Roadway Width (m)	9.900			
Embankment		7	7	Wide transverse cracks 5m North & South of pipe - sealed.
Sideslope (__:1)	3.0			
(Height of Cover(m) : 5.1)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	6	
Heaving (mm)	150			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		4	4	430 mm of bevel exposed, piping evident (photo). Well vegetated but insufficient under pipe to prevent piping.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		4	4	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Barrel Last Accessible Date	18-Sep-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	
Measured Rise (mm)	1860			
Measured At Ring No.	8			
Sag (mm)	41			
Percent Sag	2			
Sidewall		7	7	
Measured Span (mm)	1755			
Measured At Ring No.	8			
Deflection (mm)	31			1.8%
Percent Deflection	1			
Floor		N	N	Under water.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	5	Missing bolt on 9th circumferential seam at floor North side bolt does not line up between plates - minor.
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		N	5	Pitting on floor.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	POS			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Fish Passage Adequacy		4	4	Hanging D/S end (photo).
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		6	6	Showing signs of superficial rust.
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	600			
Scour Protection		3	3	All riprap washed out of scour hole d/s creating rock dam (photo).
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		3	3	5 m dia x 1.0 m dp scour hole - photo. Some undermining of bevel for 1m.
Beavers (Y/N)	No			
Downstream End General Rating		3	3	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	Vertical shallow banks D/S degraded at s/b. Cut banks.
Bank Stability		5	5	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP	2012	10m3 @ D/S. Class 1, redistribute existing rock into scour hole.					
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	61.0/61.1	Est. Repl. Yr	2023	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	18-Jun-2014		Previous Inspection Date	10-Nov-2010			
Inspection Cycle (Default) (months)	21						
Comment							