

| Bridge Culvert Inspection |   |  |                     |                    |
|---------------------------|---|--|---------------------|--------------------|
| Bridge File Number        | 75022 -1 Bridge Culvert                         |  | Form Type           | CUL1               |
| Year Built                | 1991  |  | Lot No.             | 4                  |
| Bridge or Town Name       | WHITEMUD CRE                                    |  | Inspector Name      | Brian Pientsch     |
| Located Over              | WABATANISK CREEK, 8.10.58.7.8.1,<br>WATERCRS-ST |  | Inspector Class     | BR CLS A           |
| Located On                | 676:04 C1 17.094                                |  | Assistant Name      | Lisbeth Medina     |
| Water Body Cl./Year       |   |  | Assistant Class     |                    |
| Navigabil. Cl./Year       |   |  | Inspection Date     | 02-Feb-2011        |
| Legal Land Location       | SW SEC 20 TWP 74 RGE 22 W5M                     |  | Data Entry By       | Theresa Lacusta    |
| Longitude, Latitude       | -117:21:37, 55:25:29                            |  | Data Entry Date     | 01-Mar-2011        |
| Road Authority            | Alberta Transportation (AIT)                    |  | Reviewer Name       | Arnold Assenheimer |
| Contract Main. Area       | CMA03   |  | Review Date         | 22-Feb-2011        |
| Clear Roadway/Skew        | 9 / 35 deg. (RHF)                               |  | Dept. Reviewer Name | Steve Pasquan      |
| AADT/Year                 | 190 / 2010 (A)                                  |  | Dept. Review Date   | 15-Nov-2011        |
| Road Classification       | RCU-209-110                                     |  | Follow-Up By        |                    |
| Detour Length (km)        | 3   |  |                     |                    |

**Bridge Culvert Information**

|                          |        |      |                |      |        |               |                    |       |
|--------------------------|--------|------|----------------|------|--------|---------------|--------------------|-------|
| Number of Culverts       | 1      |      |                |      |        |               |                    |       |
| Pipe #                   | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1                        | MAIN   | -    | 6860           | SP   | 91.4   | 152X51        | 6.0                | ROUND |
| Special Features         |        |      |                |      |        |               |                    |       |
| Special Features Comment |        |      |                |      |        |               |                    |       |

**Utilities (Located at)**

|                     |                    |  |               |    |
|---------------------|--------------------|--|---------------|----|
| Utility Attachments |                    |  |               |    |
| Telephone           | West r/w           |  | Gas           |    |
| Power               | 2 wire OH East r/w |  | Municipal     |    |
| Others              |                    |  | Problem (Y/N) | No |
| Remarks             |                    |  |               |    |

**Approach Road / Embankment**

|  |        | Last     | Now      | Explanation of Condition |
|--|--------|----------|----------|--------------------------|
| Horizontal Alignment                             |        | 8        | 8        | In sag - no passing.     |
| Vertical Alignment                               |        | 5        | 5        |                          |
| Roadway Width (m)                                | 10.000 |          |          |                          |
| Embankment                                       |        | 7        | 6        |                          |
| Sideslope ( __:1)                                | 3.0    |          |          |                          |
| (Height of Cover(m) : 3.5)                       |        |          |          |                          |
| Guardrail (Y/N)                                  | No     |          |          |                          |
| <b>Approach Road / Embankment General Rating</b> |        | <b>5</b> | <b>5</b> |                          |

**Upstream End**

| Culvert Component                             |          | Last | Now | Explanation of Condition |
|---|----------|------|-----|--------------------------|
| Direction                                     |          | W    |     |                          |
| End Treatment (Concrete, Steel, Others, None) | CONCRETE |      |     |                          |
| Headwall                                      |          | 7    | 6   |                          |
| Collar  |          | 7    | N   | Under snow               |
| Wingwalls                                     |          | X    | X   |                          |
| (Shape : )                                    |          |      |     |                          |
| Cutoff Wall                                   |          | N    | N   |                          |

| Upstream End  |             |          |          |  |
|---|-------------|----------|----------|--|
| Culvert Component   |             | Last     | Now      | Explanation of Condition                               |
| Bevel End   |             | 7        | 7        |  |
| Heaving (mm)  | 0           |          |          |  |
| Invert Above/Below Stream Bed   | BELOW       |          |          |  |
| Above/Below (mm)  | 300         |          |          |  |
| Scour Protection  |             | 7        | 7        |  |
| (Type : <b>RIP RAP</b> )  |             |          |          |  |
| (Avg. Rock Size(mm) : <b>500</b> )  |             |          |          |  |
| Scour/Erosion   |             | 7        | 7        |  |
| Beavers (Y/N)   | No          |          |          |  |
| <b>Upstream End General Rating</b>  |             | <b>7</b> | <b>7</b> |  |
| Bridge Culvert Barrel   |             |          |          |  |
| Culvert Component   |             | Last     | Now      | Explanation of Condition                               |
| (Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>6860</b> , Type: <b>SP</b> ) |             |          |          |  |
| Barrel Last Accessible Date   | 02-Feb-2011 |          |          | Too wide/tall to measure. Shape looks good.            |
| <b>Special Features</b>   |             |          |          |  |
| Special Feature   |             |          |          |  |
| (Type : )   |             |          |          |  |
| Special Feature   |             |          |          |  |
| (Type : )   |             |          |          |  |
| Roof  |             | 7        | 7        | (1/2 7043, 1/2 7110mm, 7095 (2.7% inward - 2004/09/16) |
| Measured Rise (mm)  |             |          |          |  |
| Measured At Ring No.  |             |          |          | Measurements not taken due to ice on floor.            |
| Sag (mm)  | 0           |          |          |  |
| Percent Sag   |             |          |          |  |
| Sidewall  |             | 7        | 7        |  |
| Measured Span (mm)  |             |          |          |  |
| Measured At Ring No.  |             |          |          |  |
| Deflection (mm)   | 0           |          |          |  |
| Percent Deflection  |             |          |          |  |
| Floor   |             | 7        | N        | Under ice.   |
| Bulge (mm)  | 0           |          |          |  |
| Measured At Ring No.  |             |          |          |  |
| Abrasion (Y/N)  | No          |          |          |  |
| Circumferential Seams   |             | 7        | 7        |  |
| Separation (mm)   |             |          |          |  |
| Longitudinal Seams  |             | 7        | 7        |  |
| Total No. of Cracked Rings  | 0           |          |          |  |
| Total No. of Rings with Two Cracked Seams   |             |          |          |  |
| Min. Remaining Steel Between Cracks (mm)  |             |          |          |  |
| Proper Lap (Y/N)  | Yes         |          |          |  |
| Longitudinal Stagger (Y/N)  | Yes         |          |          | 1N stagger   |
| Coating   |             | 4        | N        | Pitting 1.5m wide strip of floor.-23-Oct-2007          |
| Corrosion By Soil (Y/N)   | No          |          |          | Under ice  |
| Corrosion By Water (Y/N)  | Yes         |          |          | Superficial rust above ice level.                      |
| Camber POS/ZERO/NEG   | POS         |          |          |  |

| Bridge Culvert Barrel   |           |          |          |  |
|---|-----------|----------|----------|--|
| Culvert Component   |           | Last     | Now      | Explanation of Condition   |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 6860, Type: SP) |           |          |          |  |
| Ponding (Y/N)   | No        |          |          |  |
| Fish Passage Adequacy   |           | 3        | 4        | Outlet above S.B.-23-Oct-2007<br>Snoe cover  |
| Baffle  |           | X        | X        |  |
| (Type : )   |           |          |          |  |
| Waterway Adequacy   |           | 8        | 8        |  |
| Icing (Y/N)   | No        |          |          |  |
| Silting (Y/N)   | No        |          |          |  |
| Drift (Y/N)   | No        |          |          |  |
| <b>Barrel General Rating</b>  |           | <b>7</b> | <b>7</b> |  |
| Downstream End  |           |          |          |  |
| Culvert Component   |           | Last     | Now      | Explanation of Condition   |
| Direction   |           | E        |          |  |
| End Treatment (Concrete, Steel, Others, None)   | CONCRETE  |          |          |  |
| Headwall  |           | 7        | 7        |  |
| Collar  |           | 7        | 7        |  |
| Wingwalls   |           | X        | X        |  |
| (Shape : )  |           |          |          |  |
| Cutoff Wall   |           | N        | N        |  |
| Bevel End   |           | 8        | 8        | Rate based on 60% visibility.  |
| Heaving (mm)  | 0         |          |          |  |
| Invert Above/Below Stream Bed   | ABOVE     |          |          | Snow cover   |
| Above/Below (mm)  | 150       |          |          |  |
| Scour Protection  |           | 4        | N        | Concrete missing 8m D/S south bank<br>2m x 1.5m.-23-Oct-2007<br>Gabions underneath and riprap.-23-Oct-2007<br>Snow cover |
| (Type : <b>CONCRETE</b> )   |           |          |          |  |
| (Avg. Rock Size(mm) : )   |           |          |          |  |
| Scour/Erosion   |           | 6        | N        |  |
| Beavers (Y/N)   | No        |          |          |  |
| <b>Downstream End General Rating</b>  |           | <b>6</b> | <b>4</b> | GR carried fwd.  |
| Structure Usage   |           |          |          |  |
|   |           | Last     | Now      | Explanation of Condition   |
| <b>Channel (U/S and D/S)</b>  |           |          |          |  |
| Alignment   |           | 6        | 6        |  |
| Bank Stability  |           | 5        | 5        |  |
| HWM (m below Top of Culvert)  |           |          |          | HWM not visible<br>Log across inlet.   |
| Drift (Y/N)   | Yes       |          |          |  |
| Channel Bottom Degrading/Aggrading  | DEGRADING |          |          |  |
| Beavers (Y/N)   | Yes       |          |          |  |
| (Fish Compensation Measure 1 : <b>NONE</b> )  |           |          |          |  |
| (Fish Compensation Measure 2 : <b>NONE</b> )  |           |          |          |  |

| <b>Structure Usage</b>        |  |             |            |                                 |
|-------------------------------|--|-------------|------------|---------------------------------|
|                               |  | <b>Last</b> | <b>Now</b> | <b>Explanation of Condition</b> |
| <b>Channel General Rating</b> |  | <b>5</b>    | <b>5</b>   |                                 |

| Maintenance Recommendations                       |                  |  |                           |               |           |                   |    |
|---|------------------|--|---------------------------|---------------|-----------|-------------------|----|
| Inspector Recommendations                         | Year             | Inspector Comments                       | Department Comments       | Target Year   | Est. Cost | Cat #             |    |
| SHOTCRETE REPAIRS                                 |                  |  |                           |               |           |                   |    |
| PLACE ADDITIONAL RIP RAP                          |                  |  |                           |               |           |                   |    |
| REMOVE DRIFT ACCUMULATION                         |                  |  |                           |               |           |                   |    |
| INSTALL CONCRETE/STEEL LINING                     |                  |  |                           |               |           |                   |    |
| INSTALL STRUTS                                    |                  |  |                           |               |           |                   |    |
| INSTALL CONCRETE COLLAR/CUTOFF                    |                  |  |                           |               |           |                   |    |
| REPAIR SEAMS                                      |                  |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                  |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                  |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                  |  |                           |               |           |                   |    |
| OTHER ACTION                                      |                  |  |                           |               |           |                   |    |
| <b>Structural Condition Rating (Last/Now) (%)</b> | <b>77.8/77.8</b> | <b>Sufficiency Rating (Last/Now) (%)</b> | <b>71.1/70.4</b>          | Est. Repl. Yr | 2036      | Maint. Req. (Y/N) | No |
| Special Comments for Next Inspection              |                  |  | Department Comments       |               |           |                   |    |
| Maintenance Reviewed By                           |                  |  | Date                      |               |           | Estimated Total   | 0  |
| Proposed Long-Term Strategy                       |                  |  |                           |               |           |                   |    |
| On 3-Year Program (Y/N)                           |                  |  |                           |               |           |                   |    |
| Proposed Action                                   |                  |  |                           |               |           |                   |    |
| Previous Inspector's Name                         | Eric Caroux      |  | Previous Assistant's Name |               |           |                   |    |
| Next Inspection Date                              | 02-May-2014      |  | Previous Inspection Date  | 23-Oct-2007   |           |                   |    |
| Inspection Cycle (Default) (months)               | 39               |  |                           |               |           |                   |    |
| Comment   |                  |  |                           |               |           |                   |    |