

Bridge Culvert Inspection				
Bridge File Number	75170 -1 Bridge Culvert		Form Type	CUL1
Year Built	1960		Lot No.	3
Bridge or Town Name	SCANDIA		Inspector Name	Jon Davies
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS B
Located On	36:06 C1 3.277		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	02-Jan-2012
Legal Land Location	SW SEC 17 TWP 15 RGE 15 W4M		Data Entry By	Alyssa Boynton
Longitude, Latitude	-112:02:15, 50:15:26		Data Entry Date	22-Feb-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA23		Review Date	20-Jan-2012
Clear Roadway/Skew	11.4 /		Dept. Reviewer Name	Tim Davies
AADT/Year	1,580 / 2010 (A)		Dept. Review Date	24-Feb-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	1800	CP	24.3			ROUND
Special Features								
Special Features Comment								

Posting Information										
Required Vert. Clearance Posting (m)										
Posted Vertical Clearance (Y/N)			No							
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)	In Advance (Y/N)
Remarks	Not required									

Utilities (Located at)			
Utility Attachments			
Telephone			Gas
Power			Municipal
Others	Fibre Optic Cable north ditch		Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	
Vertical Alignment		9	9	
Roadway Width (m)	10.700			
Embankment		5	5	Minor sloughing @ d/s Goes to less than 0.5-1 almost 90 deg @ d/s end @ pipe
Sideslope (___:1)	3.0			
(Height of Cover(m) : 1.3)				
Guardrail (Y/N)	Yes			Damage at NE turn down end.
<b>Approach Road / Embankment General Rating</b>		<b>8</b>	<b>8</b>	

Upstream End				
<b>Culvert Component</b>		Last	Now	Explanation of Condition
Direction		N		North.
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls (Shape : )		X	X	
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	25			
Scour Protection (Type : <b>NATURAL</b> ) (Avg. Rock Size(mm) : )		X	5	
Scour/Erosion		X	5	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>7</b>	<b>5</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: CP)				
Barrel Last Accessible Date	02-Jan-2012			
<b>Special Features</b>				
Special Feature (Type : )				
Special Feature (Type : )				
Roof		5	5	Damage to south end with top female bell lip knocked off.
Measured Rise (mm)	2000			
Measured At Ring No.	1			
Sag (mm)	0			
Percent Sag	0			
Sidewall		5	5	Hairline vertical & longit cracks. 1mm wide long cracks at every section East and West sidewall.
Measured Span (mm)	1830			
Measured At Ring No.				
Deflection (mm)	0			
Percent Deflection	0			
Floor		N	N	[10/13 units have rebar spalls on the floor] June 23 2010. Mostly dirt covered.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		6	4	Caulked with foam. Minor infiltration.
Separation (mm)	50			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		X	X	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: CP)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		X	7	Carries water flow to D/S slough.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>5</b>	<b>5</b>	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		South.
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		X	5	
(Type : NATURAL)				
(Avg. Rock Size(mm) : )				
Scour/Erosion		X	5	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>7</b>	<b>5</b>	

Structure Usage				
		Last	Now	Explanation of Condition
<b>Grade Separation</b>				
Road Alignment		X	X	
Roadway Surface		7	6	
(Type : )				
Average 50mm mud				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type				
Lighting		X	X	
Barrel Leakage (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Drainage		4	4	Ponds 300mm water
Structure In Use (Y/N)	Yes			
<b>Grade Separation General Rating</b>		<b>7</b>	<b>4</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2012	Replace 2 W beam sections at NE T.D. Reset 135 degree bracket post.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>71.9/60.0</b>	Est. Repl. Yr	2021	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	02-Oct-2013		Previous Inspection Date	22-Jun-2010			
Inspection Cycle (Default) (months)	21						
Comment							