

Bridge Culvert Inspection				
Bridge File Number	75210 -1 Bridge Culvert		Form Type	CUL1
Year Built/Lined	1960/1994		Lot No.	4
Bridge or Town Name	DUCHESS		Inspector Name	Jon Davies
Located Over	EID - IRRIGATION C, WATERCRS-IC		Inspector Class	BR CLS B
Located On	36:08 C1 5.048		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	11-Jan-2012
Legal Land Location	NE SEC 11 TWP 20 RGE 15 W4M		Data Entry By	Anne Roberts
Longitude, Latitude	-111:58:25, 50:40:53		Data Entry Date	27-Feb-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA23		Review Date	20-Jan-2012
Clear Roadway/Skew	12 / -16 deg. (LHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	1,850 / 2010 (A)		Dept. Review Date	11-Mar-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
2	MAIN FULL LINER	-	2400	MP	36	125X26	2.8	ROUND
Special Features		BARREL ELBOW						
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone		Gas	40m W
Power	HV X's road S & 1W 30m W		Municipal
Others	Water pipeline 40 m East		Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		8	7	Rises to north. No passing both N&S Limited sight distance.
Vertical Alignment		5	5	
Roadway Width (m)	11.000			
Embankment		7	6	4:1 @ road
Sideslope (__:1)	6.0			
(Height of Cover(m) : 1.5)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		5	5	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
Upstream End General Rating		8	8	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2 , Secondary Span, Location Code: MAIN , Span (mm): , Rise (mm): 2400 , Type: MP)				
Barrel Last Accessible Date	11-Jan-2012			
Special Features				
Special Feature			6	D/S bevel ring section has 5 degree elbow to North
(Type : BARREL ELBOW)				
Special Feature				
(Type :)				
Roof		8	8	
Measured Rise (mm)	2420			Est
Measured At Ring No.	2			
Sag (mm)	0			
Percent Sag	0			
Sidewall		8	8	
Measured Span (mm)	2400			
Measured At Ring No.	2			
Deflection (mm)	0			
Percent Deflection	0			
Floor		N	N	400mm dark ice covered
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		N	6	
Separation (mm)	70			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	5	Minor corrosion
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2400, Type: MP)				
Fish Passage Adequacy		X	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		8	8	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		8	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	7	
Beavers (Y/N)	No			
Downstream End General Rating		8	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		6	6	30 deg bend 5m u/s
Bank Stability		8	6	
HWM (m below Top of Culvert)	1.0			No HWM visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		6	6	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	88.9/88.9	Sufficiency Rating (Last/Now) (%)	86.2/85.0	Est. Repl. Yr	2039	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	11-Oct-2013		Previous Inspection Date	22-Jun-2010			
Inspection Cycle (Default) (months)	21						
Comment							