

Bridge Culvert Inspection			
Bridge File Number	75306 -1 Bridge Culvert	Form Type	CUL1
Year Built	1998	Lot No.	3
Bridge or Town Name	SUNNYSLOPE	Inspector Name	Dave Lam
Located Over	2ND ORDER TRIBUTARY TO KNEEHILLS CREEK, 3.46.22.1, WATERCRS-ST	Inspector Class	BR CLS A
Located On	806:04 C1 16.042	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	15-Jul-2011
Legal Land Location	NW SEC 9 TWP 31 RGE 25 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-113:30:04, 51:38:42	Data Entry Date	16-Aug-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA20	Review Date	28-Jul-2011
Clear Roadway/Skew	9 /	Dept. Reviewer Name	Andrew Smikles
AADT/Year	1,580 / 2010 (A)	Dept. Review Date	29-Aug-2011
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	3		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2000	MP	57	75X25	2.8	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	8	8	Bottom of sag, crest curve to North with limited sight distance. No passing NB.
Vertical Alignment	6	6	
Roadway Width (m)	9.000		
Embankment	5	6	Road over pipe previously paved over 2-3 times over the years - chipsealed. Small erosion channel developing on NE embankment - no problem @ this time.
Sideslope ( __:1) (Height of Cover(m) : 6.8)	3.0		
Guardrail (Y/N)	No		
<b>Approach Road / Embankment General Rating</b>	<b>6</b>	<b>6</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	E		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls (Shape : )	X	X	
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		5	5	Bottom & lower 1/3 of bevel is not buried in clay seal and is seceptible to piping even though it is armoured by rock - OK for now.
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>300</b> )				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>5</b>	<b>5</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)				
Barrel Last Accessible Date	11-Jul-2011			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	
Measured Rise (mm)	1985			Midspan. 0.8%.
Measured At Ring No.				
Sag (mm)	15			
Percent Sag	1			
Sidewall		8	8	
Measured Span (mm)	2005			Midspan. 0.3%
Measured At Ring No.				
Deflection (mm)	5			
Percent Deflection	0			
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	10			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	6	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type : )				
Waterway Adequacy		8	8	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>7</b>	<b>7</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		8	8	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>7</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				Unknown. Large slough at E end; backed-up at culvert opening.
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>7</b>	<b>7</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2011	Remove vegetation/blockage at u/s end to drain slough.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>77.8/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>77.4/77.2</b>	Est. Repl. Yr	2049	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Monitor embankment erosion with photos.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Dave Lam		Previous Assistant's Name				
Next Inspection Date	15-Oct-2014		Previous Inspection Date	17-Mar-2005			
Inspection Cycle (Default) (months)	39						
Comment							