

Bridge Culvert Inspection				
Bridge File Number	75399 -1 Bridge Culvert		Form Type	CUL1
Year Built	1961		Lot No.	4
Bridge or Town Name	PINE LAKE		Inspector Name	Owen Salava
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS A
Located On	42:08 C1 24.899		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	26-Nov-2012
Legal Land Location	NW SEC 28 TWP 36 RGE 25 W4M		Data Entry By	Marcia Chavez
Longitude, Latitude	-113:31:14, 52:07:27		Data Entry Date	13-Dec-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	John O'Brien
Contract Main. Area	CMA19		Review Date	04-Dec-2012
Clear Roadway/Skew	10.8 /		Dept. Reviewer Name	Andrew Smikles
AADT/Year	2,020 / 2011 (A)		Dept. Review Date	17-Dec-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	15			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	1724	1901	SPE	30.3	152X51	3.0	ELLIPSE
Special Features								
Special Features Comment								

Posting Information

Required Vert. Clearance Posting (m)											
Posted Vertical Clearance (Y/N)											
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)		In Advance (Y/N)
Remarks											

Utilities (Located at)

Utility Attachments											
Telephone	South r/w.					Gas					
Power	N side 3 wire 20m c/l.					Municipal					
Others						Problem (Y/N)	No				
Remarks											

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		9	9	No passing WB. Hill W side. Limited sight distance. Road over pipe is on uphill grade to West.
Vertical Alignment		6	6	
Roadway Width (m)	10.800			
Embankment		7	7	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 1.5)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	Sidewall bent on W side.
Heaving (mm)				
Invert Above/Below Stream Bed				
Above/Below (mm)	250			
Scour Protection		6	N	Takes some drainage.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		6	N	
Beavers (Y/N)	No			
Upstream End General Rating		6	6	GR carried forward from 12Apr2011.
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Barrel Last Accessible Date	26-Nov-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	Unable to measured due to concrete floor.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag	0			
Sidewall		6	5	Minor deformation at NW end (photo). See longit. seams.
Measured Span (mm)	1735			
Measured At Ring No.	8			
Deflection (mm)	11			
Percent Deflection	0			
Floor		N	N	Concrete & silt covered.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		5	5	Two seams at 5 o'clock have loose bolts with no ill affects.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SPE)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		5	6	
Icing (Y/N)	No			
Siltting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		5	5	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	350			
Scour Protection		6	6	Takes some drainage.
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
Downstream End General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		5	5	Floor is 350 mm above path but does not appear to have affected passage.
Roadway Surface		7	7	
(Type : CONCRETE)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type	None			

Structure Usage				
		Last	Now	Explanation of Condition
Lighting		X	X	
Barrel Leakage (Y/N)	No			
Drainage		8	8	
Structure In Use (Y/N)	No			Fence removed, N side. Lease site to S.
Grade Separation General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	52.8/56.2	Est. Repl. Yr	2031	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	26-Aug-2014		Previous Inspection Date	12-Apr-2011			
Inspection Cycle (Default) (months)	21						
Comment							