

Bridge Culvert Inspection				
Bridge File Number	75495 -1 Bridge Culvert		Form Type	CULM
Year Built	1960		Lot No.	4
Bridge or Town Name	STRATHMORE		Inspector Name	Jason Rusu
Located Over	WID - IRRIGATION C, WATERCRS-IC		Inspector Class	BR CLS A
Located On	21:12 C1 5.899		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	09-Aug-2012
Legal Land Location	NW SEC 35 TWP 24 RGE 24 W4M		Data Entry By	Lauren Korte
Longitude, Latitude	-113:15:39, 51:05:26		Data Entry Date	05-Sep-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA30		Review Date	19-Aug-2012
Clear Roadway/Skew	11.2 / -30 deg. (LHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	1,710 / 2011 (A)		Dept. Review Date	06-Sep-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information

Number of Culverts	2							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	1370	MP	16.5	68X13		ROUND
2	MAIN	-	1370	MP	16.5	68X13		ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	West Ditch.	Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	Intersection 500m North.
Vertical Alignment		8	8	
Roadway Width (m)	11.200			
Embankment		6	6	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 2)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		W		South pipe West end.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Cutoff Wall		X	X	
Bevel End		4	4	Extensive corrosion of lower portion of bevel.
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	200			
Scour Protection		5	5	Concrete bags. Ingrown.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1370, Type: MP)				
Barrel Last Accessible Date	11-Nov-2010			Water too deep to enter.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		4	N	Viewed from ends- both pipes still have circular shape. P.R 4.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag	7			
Sidewall		4	N	P.R 4.
Measured Span (mm)	1470			
Measured At Ring No.	2			
Deflection (mm)	100			
Percent Deflection	7			
Floor		N	N	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	N	P.R 5.
Separation (mm)	25			
Longitudinal Seams		5	N	P.R 5.
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		4	N	(Heavy scaling on sidewalls) 11-Nov-2010
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1370, Type: MP)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		4	4	G.R carried forward.

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		E		South pipe- East end.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		4	4	Extensive corrosion of lower portion.
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	200			
Scour Protection (Type : RIP RAP) (Avg. Rock Size(mm) : 300)		5	5	Ingrown.
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		4	4	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		W		North pipe- West end.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Bevel End		4	4	Heavy corrosion on lower 1/2.
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	200			
Scour Protection		5	5	Ingrown. And concrete bags.
(Type : RIP RAP) (Avg. Rock Size(mm) : 250)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		4	4	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1370, Type: MP)				
Barrel Last Accessible Date	11-Nov-2010			Viewed from ends- shape still circular.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		4	N	(9% sag)- 11-Nov-2010 P.R 4.
Measured Rise (mm)	1245			
Measured At Ring No.				
Sag (mm)	125			
Percent Sag	9			
Sidewall		5	N	P.R 5.
Measured Span (mm)	1455			
Measured At Ring No.				
Deflection (mm)	85			
Percent Deflection	6			
Floor		5	N	P.R 5.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		5	N	
Separation (mm)	25			
Longitudinal Seams		5	N	P.R 5.
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		4	N	P.R 4. (Heavy scaling throughout pipe) 11-Nov-2010
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1370, Type: MP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		4	4	G.R carried forward.
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		E		North pipe- East end.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		4	4	Extensive corrosion of bevel floor.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		5	5	and concrete bags. Ingrown.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				No visible HWM.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	AGGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	54.6/54.8	Est. Repl. Yr	2015	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Rusu		Previous Assistant's Name				
Next Inspection Date	09-May-2014		Previous Inspection Date	11-Nov-2010			
Inspection Cycle (Default) (months)	21						
Comment							