

Bridge Culvert Inspection			
Bridge File Number	75621 -1 Bridge Culvert	Form Type	CUL1
Year Built	1964	Lot No.	4
Bridge or Town Name	MENAIK	Inspector Name	Owen Salava
Located Over	TRIBUTARY TO MASKWA CREEK, 5.47.4.1.4, WATERCRS-ST	Inspector Class	BR CLS A
Located On	2:28 R1 10.676;2:28 L1 10.677	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	22-Feb-2013
Legal Land Location	SE SEC 12 TWP 44 RGE 26 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-113:38:37, 52:46:17	Data Entry Date	11-Mar-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA17	Review Date	27-Feb-2013
Clear Roadway/Skew	22.8 / -15 deg. (LHF)	Dept. Reviewer Name	Chris Black
AADT/Year	24,500 / 2011 (A)	Dept. Review Date	14-Mar-2013
Road Classification	RAD-412.4-120	Follow-Up By	
Detour Length (km)	1		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2019	2226	SPE	128.2	152X51	3.5,3.5,3.5	ELLIPSE
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		8	8	In sag of vertical curve.
Vertical Alignment		6	6	
Roadway Width (m)	22.800			
Embankment		6	6	SW embankment erosion due to channel misalignment.
Sideslope (__:1)	3.0			
(Height of Cover(m) : 12)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		5	5	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		5	N	Bevel projects 800mm from fill. Snow covered.
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		5	N	Snow covered.
Beavers (Y/N)	No			
Upstream End General Rating		5	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2019, Rise (mm): 2226, Type: SPE)				
Barrel Last Accessible Date	22-Feb-2013			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	Unable to measure due to ice.
Measured Rise (mm)	2160			
Measured At Ring No.	20			
Sag (mm)	66			(from unknown date)
Percent Sag	3			
Sidewall		6	6	Span @ R2 = 1992, 27mm. R10 = 2004, 15mm. R30 = 2031, 12mm. R40 = 2023, 4mm. R50 = 1993, 26mm.
Measured Span (mm)	2087			
Measured At Ring No.	20			
Deflection (mm)	68			
Percent Deflection	3			3.4%
Floor		6	N	Ice
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		5	5	Superficial corrosion @ longitudinal seams & waterline. Minor leakage through some bolt holes.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2019, Rise (mm): 2226, Type: SPE)				
Fish Passage Adequacy		6	6	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
Barrel General Rating		6	6	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		5	5	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		4	N	Snow covered; previous rating 4 on 13Jul2011.
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		4	4	15 x 6m scour hole 1m deep not creating a problem.
Beavers (Y/N)	No			
Downstream End General Rating		4	4	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		4	4	(U/S end does not line up with channel causing erosion @ SW embankment, minor. 13Jul2011) - Snow covered; looks OK, rating carried forward.
Bank Stability		5	5	
HWM (m below Top of Culvert)				No HWM visible.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	Yes			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		4	4	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	66.7/66.7	Sufficiency Rating (Last/Now) (%)	62.6/62.6	Est. Repl. Yr	2033	Maint. Req. (Y/N)	No
Special Comments for Next Inspection	No action for d/s scour at this time. Confirm alignment without snow.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	22-Nov-2014		Previous Inspection Date	13-Jul-2011			
Inspection Cycle (Default) (months)	21						
Comment							