

Bridge Culvert Inspection			
Bridge File Number	76065 -1 Bridge Culvert	Form Type	CUL1
Year Built	1964	Lot No.	4
Bridge or Town Name	WAINWRIGHT	Inspector Name	Jason Saly
Located Over	TRAIL-ANIMAL, OVER SP	Inspector Class	BR CLS A
Located On	41:18 C1 14.266	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	27-Nov-2012
Legal Land Location	NE SEC 17 TWP 46 RGE 6 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-110:50:06, 52:58:12	Data Entry Date	15-Jan-2013
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA15	Review Date	14-Dec-2012
Clear Roadway/Skew	10.5 /	Dept. Reviewer Name	Andrew Smikles
AADT/Year	1,220 / 2011 (A)	Dept. Review Date	17-Jan-2013
Road Classification	RAU-210-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1724	MP	21.3	68X13	3.5	ROUND
Special Features								
Special Features Comment								

Posting Information

Required Vert. Clearance Posting (m)										
Posted Vertical Clearance (Y/N)	No									
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)	In Advance (Y/N)
Remarks	Not required, cattlepass.									

Utilities (Located at)

Utility Attachments			
Telephone	W r.o.w.	Gas	
Power	2 wire OH 20m E of c/l.	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Located at midpoint of long S curve. Long blind crest curve for 200m N of site, no passing NB. Farm approach at NW.
Vertical Alignment		6	6	
Roadway Width (m)	10.500			
Embankment		7	N	Snow covered.
Sideslope (___:1)	3.0			
(Height of Cover(m) : 0.8)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	Crown has minor mower damage. Squared end.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		N	N	Snow covered.
(Type :)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	X	Snow covered.
Beavers (Y/N)	No			
Upstream End General Rating		6	6	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1724, Type: MP)				
Barrel Last Accessible Date	27-Nov-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		5	5	Minor mower damage East end including 1 puncture near U/S end. Rise could not be measured due to dirt on floor. Estimated
Measured Rise (mm)	1744			
Measured At Ring No.				
Sag (mm)	20			
Percent Sag	1			
Sidewall		7	7	Span at W end=1697=27mm Span at midpipe=1724=0mm Span at E end=1696=28mm=1.6%
Measured Span (mm)	1696			
Measured At Ring No.				
Deflection (mm)	28			
Percent Deflection	2			
Floor		N	N	Dirt on floor.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	6	
Separation (mm)	35			
Longitudinal Seams		7	7	Riveted seams.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		6	6	Minor
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1724, Type: MP)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		5	5	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	Squared end.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		N	N	Snow covered.
(Type :)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		N	X	Snow covered.
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		8	8	
Roadway Surface		8	8	
(Type : SOIL)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type	None			
Lighting		X	X	
Barrel Leakage (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Drainage		N	7	
Structure In Use (Y/N)	No			Fences to structure removed in both ditches.
Grade Separation General Rating		8	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	71.9/71.3	Est. Repl. Yr	2034	Maint. Reqd. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date		Estimated Total	0	
Proposed Long-Term Strategy	2008.01.21 Have signed cattlepass form so structure can be removed when appropriate. Brownlee & Associates						
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Saly		Previous Assistant's Name				
Next Inspection Date	27-Aug-2014		Previous Inspection Date	07-Mar-2011			
Inspection Cycle (Default) (months)	21						
Comment							