

Bridge Culvert Inspection				
Bridge File Number	77086 -1 Bridge Culvert		Form Type	CUL1
Year Built	1969		Lot No.	3
Bridge or Town Name	GRASSY LAKE		Inspector Name	Tom Carey
Located Over	SMR - IRRIGATION C, WATERCRS-IC		Inspector Class	BR CLS A
Located On	877:06 C1 6.438		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	14-Mar-2012
Legal Land Location	NW SEC 10 TWP 9 RGE 13 W4M		Data Entry By	Kelsey Roberts
Longitude, Latitude	-111:41:53, 49:43:39		Data Entry Date	08-Apr-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA24		Review Date	25-Mar-2012
Clear Roadway/Skew	8.5 /		Dept. Reviewer Name	Tim Davies
AADT/Year	280 / 2011 (A)		Dept. Review Date	17-Apr-2012
Road Classification	RCU-209-110		Follow-Up By	
Detour Length (km)	5			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	2134	1549	RPP	16.5	152X51	2.8	PIPE ARCH
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments				
Telephone	West ditch.		Gas	
Power	4 wires East ditch and 4 lines crossing road 20m North		Municipal	
Others			Problem (Y/N)	No
Remarks				

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Intersection 15m North.
Vertical Alignment		9	9	
Roadway Width (m)	8.000			
Embankment		N	7	
Sideslope ( __:1)	2.5			
(Height of Cover(m) : 0.5)				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>7</b>	<b>7</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		W		West invert.
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	N	(Heaved due to neg camber.) 2005/10/18 Covered in dirt
Heaving (mm)	150			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		N	5	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		N	7	
Beavers (Y/N)	No			Bevel filled in with 1.5m high dirt
<b>Upstream End General Rating</b>		<b>3</b>	<b>5</b>	General rating carried forward
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2134, Rise (mm): 1549, Type: RPP)				
Barrel Last Accessible Date	14-Mar-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		N	5	(1 ring from U/S - 1530mm. Centerline - 1496mm. 1 ring from D/S - 1545mm.)
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	53			
Percent Sag	3			
Sidewall		N	4	Crimping at R2 at North at bottom corrugations.
Measured Span (mm)	2160			
Measured At Ring No.	5			
Deflection (mm)	26			
Percent Deflection	1			
Floor		N	N	300mm mud, ice and water
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	7	
Separation (mm)	0			
Longitudinal Seams		N	4	20mm gap at roof plates at R2. Not a typical seam crack. Minor 10mm long crack vertically up from one bolt at R2 at southside. Goes from bolt to plate edge. Roof is staggered. Sidewall has no stagger.
Total No. of Cracked Rings	1			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		N	5	
Corrosion By Soil (Y/N)				
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			300mm.

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2134, Rise (mm): 1549, Type: RPP)				
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		N	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>4</b>	<b>4</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		N	N	Covered in dirt at floor and up around sides 500mm deep.
Heaving (mm)	100			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		N	5	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>4</b>	<b>4</b>	G.R. carried forward.
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		7	5	Aligns 90 degrees to pipe. No canal- is just used for ditch drainage now canal is filled in.
Bank Stability		N	7	
HWM (m below Top of Culvert)	1.0			No visible HWM (Feb. 16/09)
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>7</b>	<b>5</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Clean out dirt from ends if is to still be used as drainage pipe.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>44.4/44.4</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>62.0/56.4</b>	Est. Repl. Yr	2020	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection	Spoke with local farmer- peipe could be filled in, in future or just left as drainage pipe- in discussion with A.T. and MD 14 now. T. Carey Mar. 14/12		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tim Davies		Previous Assistant's Name				
Next Inspection Date	14-Jun-2015		Previous Inspection Date	16-Feb-2009			
Inspection Cycle (Default) (months)	39						
Comment							