

Bridge Culvert Inspection			
Bridge File Number	77633 -1 Bridge Culvert	Form Type	CUL1
Year Built	1964	Lot No.	4
Bridge or Town Name	BONNYVILLE	Inspector Name	Wade Nanninga
Located Over	TRAIL-ANIMAL, OVER SP	Inspector Class	BR CLS A
Located On	28:18 C1 12.543	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	09-Apr-2012
Legal Land Location	SW SEC 10 TWP 61 RGE 6 W4M	Data Entry By	Theresa Lacusta
Longitude, Latitude	-110:49:29, 54:15:29	Data Entry Date	08-May-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Eric Carcoux
Contract Main. Area	CMA08	Review Date	25-Apr-2012
Clear Roadway/Skew	11.1 /	Dept. Reviewer Name	Brent Herrick
AADT/Year	5,240 / 2011 (A)	Dept. Review Date	12-Jun-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	5		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1738	1920	MPE	21.7	68X13	3.5	ELLIPSE
Special Features								
Special Features Comment								

Posting Information

Required Vert. Clearance Posting (m)										
Posted Vertical Clearance (Y/N)	No									
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)	In Advance (Y/N)
Remarks	Not required.									

Utilities (Located at)

Utility Attachments			
Telephone	East & West r/w.	Gas	Plowed through river 40 m west.
Power	7 wires OH West r/w.	Municipal	
Others	Fibre optic cable West r/w.	Problem (Y/N)	No
Remarks	BF tag installed on top of West end roof.		

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	This site is approx 20m North of BF 08497. Curve & intersection to South. Blind crest curve to north.
Vertical Alignment		7	6	
Roadway Width (m)	11.000			
Embankment		7	7	
Sideslope (___:1)	2.0			
(Height of Cover(m) : 1)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		7	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		4	5	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		4	5	
Beavers (Y/N)	No			
Upstream End General Rating		4	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1738, Rise (mm): 1920, Type: MPE)				
Barrel Last Accessible Date	09-Apr-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		5	5	Crown at outlet torn by mower.
Measured Rise (mm)	1790			
Measured At Ring No.				
Sag (mm)	130			
Percent Sag	7			
Sidewall		5	5	Near c/l.
Measured Span (mm)	1830			
Measured At Ring No.				
Deflection (mm)	92			
Percent Deflection	5			
Floor		N	N	Dirt covered.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		5	5	
Separation (mm)	110			
Longitudinal Seams		5	5	Riveted.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			
Coating		6	7	Active at soil interface on outside at ends. Rust spots on roof. Lower 1/4 pitting rust.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1738, Rise (mm): 1920, Type: MPE)				
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		5	5	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		X	4	Scour from embankment flow at outlet.
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		X	4	
Beavers (Y/N)	No			
Downstream End General Rating		7	4	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		8	8	
Roadway Surface		8	8	
Quad tracks in barrel. Not used for animal trail.				
(Type : SOIL)				
Icing (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Traffic Safety Features		X	X	
Type				
Lighting		X	X	
Barrel Leakage (Y/N)	No			
Drainage		5	5	
Structure In Use (Y/N)	Yes			
Grade Separation General Rating		5	5	

Maintenance Recommendations															
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #									
SHOTCRETE REPAIRS															
PLACE ADDITIONAL RIP RAP															
REMOVE DRIFT ACCUMULATION															
INSTALL CONCRETE/STEEL LINING															
INSTALL STRUTS															
INSTALL CONCRETE COLLAR/CUTOFF															
REPAIR SEAMS															
OTHER ACTION															
OTHER ACTION															
OTHER ACTION															
OTHER ACTION															
<table border="1"> <tr> <td>Structural Condition Rating (Last/Now) (%)</td> <td>55.6/55.6</td> <td>Sufficiency Rating (Last/Now) (%)</td> <td>65.1/62.9</td> <td>Est. Repl. Yr</td> <td>2018</td> <td>Maint. Reqd. (Y/N)</td> <td>No</td> </tr> </table>								Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	65.1/62.9	Est. Repl. Yr	2018	Maint. Reqd. (Y/N)	No
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	65.1/62.9	Est. Repl. Yr	2018	Maint. Reqd. (Y/N)	No								
Special Comments for Next Inspection			Department Comments												
Maintenance Reviewed By			Date		Estimated Total	0									
Proposed Long-Term Strategy															
On 3-Year Program (Y/N)															
Proposed Action															
Previous Inspector's Name	Shane Hall		Previous Assistant's Name												
Next Inspection Date	09-Jan-2014		Previous Inspection Date	15-Jul-2010											
Inspection Cycle (Default) (months)	21														
Comment															