

Bridge Culvert Inspection				
Bridge File Number	77680 -1 Bridge Culvert		Form Type	CUL1
Year Built	1991		Lot No.	4
Bridge or Town Name	HUSSAR		Inspector Name	Jon Davies
Located Over	2ND ORDER TRIBUTARY TO CROWFOOT CREEK, 2.13.14.2.1, WATERCRS-ST		Inspector Class	BR CLS B
Located On	561:02 C1 23.142		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	23-Jan-2012
Legal Land Location	SE SEC 17 TWP 24 RGE 20 W4M		Data Entry By	Kelsey Roberts
Longitude, Latitude	-112:45:18, 51:02:17		Data Entry Date	08-Mar-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA30		Review Date	03-Feb-2012
Clear Roadway/Skew	12 / -15 deg. (LHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	700 / 2010 (A)		Dept. Review Date	11-Mar-2012
Road Classification	RCU-208-110		Follow-Up By	
Detour Length (km)	3			

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1800	MP	24	125X26	2.8	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments				
Telephone	SOUTH DITCH		Gas	
Power	3 WIRE O/H NORTH ROW		Municipal	
Others	Fibre Optics N. Ditch		Problem (Y/N)	No
Remarks				

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		8	7	Intersection at East
Vertical Alignment		7	6	
Roadway Width (m)	8.400			
Embankment		8	7	
Sideslope ( __:1)	4.0			
(Height of Cover(m) : 1.1)				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>7</b>	<b>7</b>	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		N		North
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		8	6	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	500			
Scour Protection		7	7	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>400</b> )				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>7</b>	<b>6</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>1800</b> , Type: <b>MP</b> )				
Barrel Last Accessible Date	23-Jan-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	
Measured Rise (mm)	1810			
Measured At Ring No.	2			
Sag (mm)	10			
Percent Sag	1			
Sidewall		8	8	
Measured Span (mm)	1790			
Measured At Ring No.	2			
Deflection (mm)	10			
Percent Deflection	1			
Floor		8	8	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	Tar at seams
Separation (mm)	25			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP)				
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>8</b>	<b>8</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		South
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		8	7	
Heaving (mm)	50			
Invert Above/Below Stream Bed		BELOW		
Above/Below (mm)	500			
Scour Protection		7	7	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : <b>300</b> )				
Scour/Erosion		7	7	
Beavers (Y/N)		No		
<b>Downstream End General Rating</b>		<b>7</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	CHANNEL IS UNDEFINED CULTIVATED FIELDS BOTH SIDES
Bank Stability		8	8	
HWM (m below Top of Culvert)				No visible HWM
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading		NONE		
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : <b>NONE</b> )				
(Fish Compensation Measure 2 : <b>NONE</b> )				
<b>Channel General Rating</b>		<b>8</b>	<b>8</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>88.9/88.9</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>82.4/81.4</b>	Est. Repl. Yr	2045	Maint. Req'd. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	William Reardon		Previous Assistant's Name				
Next Inspection Date	23-Apr-2015		Previous Inspection Date	28-Nov-2008			
Inspection Cycle (Default) (months)	39						
Comment							