Bridge Inspection & Maintenance System (Web 2005)

Bridge Culvert Inspection														
Bridge File Number 78111 -1 Bridge Culvert						Form Ty	/pe		CUL1	CUL1				
Year Built 1975					Lot No.			4						
Bridge or Town Name							Inspector Name		Wade Nanninga					
Located Over TRAIL-A			AIL-ANIMAL							BR CLS A				
Located On 770:04 0			:04 C1 6.926				Assista	Assistant Name						
Water Body Cl./Year							Assista	Assistant Class						
Navigabil. CI./Y	'ear						Inspecti	on Date		18-Oct-2012				
Legal Land Loc	ation	SW SE	SEC 26 TWP 49 RGE 3 W5M				Data Er	ntry By		Theresa Lacusta				
Longitude, Latitude -114:20			20:35, 53:15:17					try Date	;	24-Oct-2012				
Road Authority		Alberta	ta Transportation (AIT)				Reviewer Name		Eric Carcoux					
Contract Main. Area CMA11		11					Date		22-Oct-2012					
Clear Roadway	/Skew						Dept. R	ept. Reviewer Name Brent Herrick						
AADT/Year		820 / 20	2011 (A)				Dept. R	ot. Review Date 13-Nov-2012						
Road Classifica	ation	RCU-20	209-110				Follow-	Follow-Up By						
Detour Length	(km)	3												
Bridge Culvert	t Inform	nation												
Number of Culv	/erts		1											
Pipe #	Barrel		Span	Rise (or	Dia.)	Туре		Length		Corr. Profile	PI./Slab Thickness	Shape		
1	MAIN		-	2130		MP		24.38				ROUND		
Special Feature	es													
Special Feature	es Com	ment												
					D-	- (!]-								
Required Vert.	Clearer	non Donti	ng (m)		PO	sting in	nformatio	on						
Posted Vertical														
Posted: Lane		`) Bridge (m)	In Adv	/ance (`	V/NI)		ne SB	0	n Bridge (m)		nce (Y/N)		
Remarks				III Au		1/1 N)	Lc			II blidge (III)				
Remains					Uti	lities (L	_ocated	at)						
Utility Attachme	ents													
Telephone	W r/w	r/w Gas												
Power							Municip	al						
Others							Problem	n (Y/N)	No					
Remarks														
1				Α	pproac	h Road	d / Emba	nkment						
					Last	Now	Explana	ation of	Condi	tion				
Horizontal Aligr						7	_							
Vertical Alignm						7	_							
Roadway Width	ר (m)		8.600											
Embankment						7								
Sideslope (_:1)		3.0											
(Height of Cover(m) : 1.2)														
Guardrail (Y/N)			No											
Approach Road / Embankment General Rating				7										
Upstream End														
Culvert Component		Last	Now	Explana	ation of	Condi	tion							
Direction					W									
End Treatment (Concrete, Steel, NONE Others, None)					1									
Headwall				X										
Collar				X										

	Upstream End								
Culvert Component		Last	Now	Explanation of Condition					
Wingwalls			X						
(Shape :)									
Cutoff Wall			X						
Bevel End			X						
Heaving (mm)									
Invert Above/Below Stream Bed									
Above/Below (mm)									
Scour Protection			6						
(Type : NATURAL)									
(Avg. Rock Size(mm) :)			1						
Scour/Erosion			6						
Beavers (Y/N)	No								
Upstream End General Rating			6						
		Bric	lge Cu	lvert Barrel					
Culvert Component		Last	Now	Explanation of Condition					
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Spa	n (mm)):	, Rise (mm): 2130, Type: MP)					
Barrel Last Accessible Date	18-Oct-2012								
Special Features									
Special Feature									
(Type:)			-	-					
Special Feature									
(Type :) Roof			7						
Measured Rise (mm)			7						
Measured At Ring No.									
Sag (mm)									
Percent Sag									
Sidewall			7						
Measured Span (mm)	2050								
Measured Span (mm) 2050 Measured At Ring No.				CL					
Deflection (mm)									
Percent Deflection				1					
Floor			N	Floor covered in mud.					
Bulge (mm)									
Measured At Ring No.				1					
Abrasion (Y/N)									
Circumferential Seams			6						
Separation (mm) 50									
Longitudinal Seams			Х						
Total No. of Cracked Rings									
Total No. of Rings with Two Cracked Seams									
Min. Remaining Steel Between Cracks (mm)									
Proper Lap (Y/N)									
Longitudinal Stagger (Y/N)				1					
Coating			6						
Corrosion By Soil (Y/N)	No								
Corrosion By Water (Y/N)	No								

Alberta Transportation

Bridge Inspection & Maintenance System (Web 2005)

78111 -1 Bridge Culvert

Bridge Culvert Barrel								
Culvert Component		Last	Now	Explanation of Condition				
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Sp			, Rise (mm): 2130, Type: MP)				
Camber POS/ZERO/NEG	ZERO							
Ponding (Y/N)	No							
Fish Passage Adequacy			X					
Baffle			Х					
(Type :)								
Waterway Adequacy			Х					
Icing (Y/N)	No							
Silting (Y/N)	No			-				
Drift (Y/N)	No							
Barrel General Rating			7					
Culvert Compensat				ream End				
Culvert Component		Last E	Now	Explanation of Condition				
End Treatment (Concrete, Steel, Others, None)	NONE							
Headwall	1		X					
Collar			X					
Wingwollo			X					
Wingwalls			^					
(Shape :) Cutoff Wall			X					
Bevel End			Х					
Heaving (mm)								
Invert Above/Below Stream Bed								
Above/Below (mm)								
Scour Protection			6					
(Type : NONE)				-				
(Avg. Rock Size(mm) :)								
Scour/Erosion			6					
Beavers (Y/N)	No							
Downstream End General Ration	ng		6					
			Structu	re Usage				
				Explanation of Condition				
Grade Separation								
Road Alignment			7					
Roadway Surface			7					
(Туре:)								
Icing (Y/N)	No							
Traffic Safety Features			Х					
Туре								
Lighting			Х					
Barrel Leakage (Y/N) No			1					

Structure Usage								
				Explanation of Condition				
Drainage			5					
Structure In Use (Y/N) Yes								
Grade Separation General Rating			5					

Maintenance Recommendations												
Inspector Recommendations	Ye	ear	Inspector Comments	Department Con	nments	Target Year	Est. Cost	Cat #				
SHOTCRETE REPAIRS												
PLACE ADDITIONAL RIP RAP												
REMOVE DRIFT ACCUMULATION												
INSTALL CONCRETE/STEEL LINING												
INSTALL STRUTS												
INSTALL CONCRETE COLLAR/CUTO	FF											
REPAIR SEAMS												
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
OTHER ACTION												
Structural Condition Rating (Last/No (%)	w) /77	7.8	Sufficiency Rating (Last/Now) (%)	/79.7	/79.7 Est. Repl. Yr 2030		Maint. Re	qd. (Y/N)	No			
Special Comments for Next Inspection				Department Comments								
Maintenance Reviewed By				Date		E	Estimated Total	0				
Proposed Long-Term Strategy												
On 3-Year Program (Y/N)												
Proposed Action												
Previous Inspector's Name			Previ	ious Assistant's Name								
Next Inspection Date 18-		16	Previ	ious Inspection Date								
Inspection Cycle (Default) (months) 39												
Comment												