

Bridge Culvert Inspection			
Bridge File Number	78361 -1 Bridge Culvert	Form Type	CUL1
Year Built	1980	Lot No.	3
Bridge or Town Name	HIGHWOOD HOU	Inspector Name	Garry Roberts
Located Over	TRIBUTARY TO STORM CK, 2.13.27.42.3, WATERCRS-ST	Inspector Class	BR CLS A
Located On	40:10 C1 32.447	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	24-Jun-2011
Legal Land Location	SE SEC 31 TWP 18 RGE 7 W5M	Data Entry By	Alyssa Boynton
Longitude, Latitude	-114:57:01, 50:33:38	Data Entry Date	13-Jul-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Tom Carey
Contract Main. Area	CMA28	Review Date	28-Jun-2011
Clear Roadway/Skew	11 / 12 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	440 / 2010 (A)	Dept. Review Date	15-Jul-2011
Road Classification	RAU-209-110	Follow-Up By	
Detour Length (km)	50		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2317	2561	SPE	40	152X51	3.5	ELLIPSE
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	
Remarks	None visible.		

**Approach Road / Embankment**

		Last	Now	Explanation of Condition
Horizontal Alignment		5	5	At end of curve to the north and on steady downhill grade to the south.
Vertical Alignment		5	5	
Roadway Width (m)	11.000			
Embankment		6	6	
Sideslope ( __:1)	4.0			
(Height of Cover(m) : 2.5)				
Guardrail (Y/N)	Yes			NE, 1 post broken
Approach Road / Embankment General Rating		5	5	

**Upstream End**

Culvert Component		Last	Now	Explanation of Condition
Direction		E		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	7	CORROSION WITH SOME PITTING @ FLOOR
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		7	7	ROCK 200 TO 1000 mm
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>500</b> )				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>6</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): <b>2317</b> , Rise (mm): <b>2561</b> , Type: <b>SPE</b> )				
Barrel Last Accessible Date	24-Jun-2011			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	Inward
Measured Rise (mm)	2600			
Measured At Ring No.	3			
Sag (mm)	39			
Percent Sag	1			
Sidewall		8	8	INWARD
Measured Span (mm)	2280			
Measured At Ring No.	3			
Deflection (mm)	37			
Percent Deflection	1			
Floor		5	5	FLOOR DENTED 5 TO 20 mm THROUGHOUT
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	Yes			
Circumferential Seams		8	8	
Separation (mm)	0			
Longitudinal Seams		7	7	1N stagger
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	Yes			
Coating		5	4	Corrosion with some pitting on floor. Coating worn off on floor.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	POS			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2317, Rise (mm): 2561, Type: SPE)				
Fish Passage Adequacy		5	6	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	300			
Scour Protection		5	5	600 mm DP x 3 m DIAMETER. ROCK LINED SCOUR HOLE
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		7	5	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				No visible hwm.
Drift (Y/N)	No			
Channel Bottom Degradation/Aggradation				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations									
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #			
SHOTCRETE REPAIRS									
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL CONCRETE/STEEL LINING									
INSTALL STRUTS									
INSTALL CONCRETE COLLAR/CUTOFF									
REPAIR SEAMS									
OTHER ACTION	2011	Replace 160mmx200mmx1500mm TT guardrail post at NE- turndown section							
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>77.8/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>74.2/73.1</b>	Est. Repl. Yr	2030	Maint. Req'd. (Y/N)	Yes		
Special Comments for Next Inspection			Department Comments						
Maintenance Reviewed By			Date		Estimated Total	0			
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name						
Next Inspection Date	24-Mar-2013		Previous Inspection Date	05-Oct-2009					
Inspection Cycle (Default) (months)	21								
Comment									