

Bridge Culvert Inspection			
Bridge File Number	78508 -1 Bridge Culvert	Form Type	CUL1
Year Built	1979	Lot No.	4
Bridge or Town Name	MORLEY	Inspector Name	Jon Davies
Located Over	TRIBUTARY TO LITTLE JUMPINGPOUND CREEK, 2.13.43.3.2, WATERCRS-ST	Inspector Class	BR CLS B
Located On	68:04 C1 35.095	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	12-Sep-2012
Legal Land Location	SW SEC 7 TWP 25 RGE 5 W5M	Data Entry By	Lauren Korte
Longitude, Latitude	-114:41:58, 51:06:51	Data Entry Date	10-Oct-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA28	Review Date	21-Sep-2012
Clear Roadway/Skew	12.3 / 31 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	310 / 2011 (A)	Dept. Review Date	11-Oct-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	16		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2317	2561	SPE	45.1	152X51	3.0	ELLIPSE
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	East ROW.	Gas	
Power	West ROW.	Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	7	7	Crest curves North and South.
Vertical Alignment	5	5	
Roadway Width (m)	12.300		
Embankment	7	7	
Sideslope ( __:1)	3.0		
(Height of Cover(m) : 2.9)			
Guardrail (Y/N)	Yes		
<b>Approach Road / Embankment General Rating</b>	<b>5</b>	<b>5</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	W		West.
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	100			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		7	7	
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : <b>300</b> )				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>7</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2317, Rise (mm): 2561, Type: SPE)				
Barrel Last Accessible Date	12-Sep-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		7	7	
Measured Rise (mm)	2478			
Measured At Ring No.	4			
Sag (mm)	83			
Percent Sag	3			
Sidewall		7	7	
Measured Span (mm)	2390			
Measured At Ring No.	4			
Deflection (mm)	77			
Percent Deflection	3			
Floor		N	6	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		4	6	Superficial corrosion at water line and below.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2317, Rise (mm): 2561, Type: SPE)				
Fish Passage Adequacy		6	6	
Baffle		X	X	
(Type : )				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>7</b>	<b>7</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	300			
Scour Protection		6	6	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 400)				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>6</b>	<b>6</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		6	6	Bend on u/s end & d/s end.
Bank Stability		6	6	
HWM (m below Top of Culvert)	1.2			No visible HWM.
Drift (Y/N)	Yes			
Channel Bottom Degrading/Aggrading	DEGRADING			In Trees U/S & D/S.
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>77.8/77.8</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>75.2/75.1</b>	Est. Repl. Yr	2030	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	12-Jun-2014		Previous Inspection Date	07-Jan-2011			
Inspection Cycle (Default) (months)	21						
Comment							