

Bridge Culvert Inspection			
Bridge File Number	78564 -1 Bridge Culvert	Form Type	CUL1
Year Built	1985	Lot No.	4
Bridge or Town Name	LONGVIEW	Inspector Name	Garry Roberts
Located Over	2ND ORDER TRIBUTARY TO PEKISKO CREEK, 2.13.27.11.1.2.1, WATERCRS-ST	Inspector Class	BR CLS A
Located On	22:10 C1 30.243	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	06-Jun-2012
Legal Land Location	SW SEC 29 TWP 17 RGE 2 W5M	Data Entry By	Kelsey Roberts
Longitude, Latitude	-114:15:14, 50:27:40	Data Entry Date	09-Jul-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Tom Carey
Contract Main. Area	CMA27	Review Date	18-Jun-2012
Clear Roadway/Skew	10 / 5 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	1,850 / 2011 (A)	Dept. Review Date	12-Jul-2012
Road Classification	RAU-209-110	Follow-Up By	
Detour Length (km)	20		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1524	SP	48.2	152X51	3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power	East row and crosses south	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	6	6	located in curve. Local road intersection south
Vertical Alignment	6	6	
Roadway Width (m)	10.000		
Embankment	7	7	
Sideslope (__:1)	3.0		
(Height of Cover(m) : 5)			
Guardrail (Y/N)	Yes		West side only.
Approach Road / Embankment General Rating	6	6	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	W		West
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	Install damage @ S side-minor.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			Ingrown
Scour Protection (Type : RIP RAP)		7	7	
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 1524 , Type: SP)				
Barrel Last Accessible Date	06-Jun-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	
Measured Rise (mm)	1495			
Measured At Ring No.	7			
Sag (mm)	29			
Percent Sag	2			
Sidewall		7	7	
Measured Span (mm)	1525			
Measured At Ring No.	6			
Deflection (mm)	1			
Percent Deflection	0			
Floor		7	7	50% visible at U/S
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		5	5	Minor superficial corrosion
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1524, Type: SP)				
Fish Passage Adequacy		7	7	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			D/S last 1/3 covered with 200mm silt.
Silting (Y/N)	Yes			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		8	8	Ingrown
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5	5	Stream curves @ both ends.
Bank Stability		8	8	
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	76.7/73.0	Est. Repl. Yr	2069	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	06-Mar-2014		Previous Inspection Date	09-Oct-2010			
Inspection Cycle (Default) (months)	21						
Comment							