

Bridge Culvert Inspection			
Bridge File Number	78759 -1 Bridge Culvert	Form Type	CULM
Year Built	1980	Lot No.	3
Bridge or Town Name	MORLEY	Inspector Name	Jon Davies
Located Over	BYRANT CREEK, 2.13.43.4, WATERCRS-ST	Inspector Class	BR CLS B
Located On	68:04 C1 21.112	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	18-Sep-2012
Legal Land Location	SW SEC 16 TWP 24 RGE 6 W5M	Data Entry By	Lauren Korte
Longitude, Latitude	-114:46:57, 51:02:37	Data Entry Date	10-Oct-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA28	Review Date	21-Sep-2012
Clear Roadway/Skew	12.4 / 15 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	310 / 2011 (A)	Dept. Review Date	11-Oct-2012
Road Classification	RAU-211.8-110	Follow-Up By	
Detour Length (km)	16		

Bridge Culvert Information

Number of Culverts	3							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	2236	1626	RPP	39	152X51	4.0	PIPE ARCH
2	MAIN	-	1219	MP	27	68X13	2.8	ROUND
3	MAIN	-	1219	MP	27	68X13	2.8	ROUND
Special Features	BEAVR CTRL DEV							
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone		Gas	
Power		Municipal	
Others		Problem (Y/N)	No
Remarks	None observed.		

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	5	5	Located in curve.
Vertical Alignment	7	7	
Roadway Width (m)	12.400		
Embankment	7	6	
Sideslope (__:1)	4.0		
(Height of Cover(m) : 0.7)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	5	5	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)			
Direction	N		North.
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		6	6	Some minor damage along bevel. Grate welded across bevel - dislodged.
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		6	6	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
Upstream End General Rating		6	6	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2236, Rise (mm): 1626, Type: RPP)				
Barrel Last Accessible Date	18-Sep-2012			
Special Features				
Special Feature		4	4	Dislodged and plugged with drift @ u/s.
(Type : BEAVR CTRL DEV)				
Special Feature				
(Type :)				
Roof		5	5	
Measured Rise (mm)	1865			
Measured At Ring No.	6			
Sag (mm)	57			
Percent Sag	4			
Sidewall		6	6	
Measured Span (mm)	2270			
Measured At Ring No.	5			
Deflection (mm)	34			
Percent Deflection	2			
Floor		N	N	300mm water.
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		6	6	
Separation (mm)	6			
Longitudinal Seams		5	5	Rings 4, 5, 6, 7 & 8 Roof seams cusping - worst @ring #6 - 6mm. 1N stagger at roof seam only.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 2236, Rise (mm): 1626, Type: RPP)				
Coating		5	6	Superficial corrosion @ lower half.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		4	4	Restricted by drift across U/S bevel.
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			
Barrel General Rating		5	5	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Span Type: Primary Span)				
Direction		S		South.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		5	5	10m wide x 6m long x 0.5 deep scour hole with incomplete rock lining.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Downstream End General Rating		5	5	
Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Direction		N		West pipe - North end.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Span Type: Secondary Span)				
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	30			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		5	5	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1219, Type: MP)				
Barrel Last Accessible Date	18-Sep-2012			West Pipe.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	Midspan.
Measured Rise (mm)	1182			
Measured At Ring No.				
Sag (mm)	37			
Percent Sag	3			
Sidewall		7	7	Midspan.
Measured Span (mm)	1223			
Measured At Ring No.				
Deflection (mm)	4			
Percent Deflection	1			
Floor		7	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	40			
Longitudinal Seams		7	7	Riveted seams.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1219, Type: MP)					
Coating		5	6	Minor corrosion at floor.	
Corrosion By Soil (Y/N)	No				
Corrosion By Water (Y/N)	Yes				
Camber POS/ZERO/NEG	ZERO				
Ponding (Y/N)	No				
Fish Passage Adequacy		5	5		
Baffle		X	X		
(Type :)					
Waterway Adequacy		7	7		
Icing (Y/N)	No				
Silting (Y/N)	No				
Drift (Y/N)	No				
Barrel General Rating		7	7		
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 2, Span Type: Secondary Span)					
Direction		S		South end - West pipe.	
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		7	7		
Heaving (mm)	0				
Invert Above/Below Stream Bed					
Above/Below (mm)	0				
Scour Protection		7	7	Grassed over rip rap.	
(Type : RIP RAP)					
(Avg. Rock Size(mm) : 200)					
Scour/Erosion		7	7		
Beavers (Y/N)	No				
Downstream End General Rating		7	7		
Upstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 3, Span Type: Secondary Span)					
Direction		N		East pipe North End.	
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Span Type: Secondary Span)				
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	50			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		6	6	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
Upstream End General Rating		6	6	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 3, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1219, Type: MP)				
Barrel Last Accessible Date	18-Sep-2012			East pipe.
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		6	6	Minor dents at seams.
Measured Rise (mm)	1180			
Measured At Ring No.	4			
Sag (mm)	39			
Percent Sag	4			
Sidewall		7	7	
Measured Span (mm)	1245			
Measured At Ring No.	4			
Deflection (mm)	26			
Percent Deflection	2			
Floor		7	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	50			
Longitudinal Seams		X	7	Riveted seams.
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			

Bridge Culvert Barrel					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 3, Secondary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1219, Type: MP)					
Coating		5	6	Minor corrosion on floor.	
Corrosion By Soil (Y/N)	No				
Corrosion By Water (Y/N)	Yes				
Camber POS/ZERO/NEG	ZERO				
Ponding (Y/N)	No				
Fish Passage Adequacy		5	5		
Baffle		X	X		
(Type :)					
Waterway Adequacy		7	7		
Icing (Y/N)	No				
Silting (Y/N)	No				
Drift (Y/N)	No				
Barrel General Rating		6	6		
Downstream End					
Culvert Component		Last	Now	Explanation of Condition	
(Pipe # : 3, Span Type: Secondary Span)					
Direction		S		East pipe - South End.	
End Treatment (Concrete, Steel, Others, None)	STEEL				
Headwall		X	X		
Collar		X	X		
Wingwalls		X	X		
(Shape :)					
Cutoff Wall		X	X		
Bevel End		7	7		
Heaving (mm)	0				
Invert Above/Below Stream Bed					
Above/Below (mm)	0				
Scour Protection		7	7	Grassed over rip rap.	
(Type : RIP RAP)					
(Avg. Rock Size(mm) : 200)					
Scour/Erosion		7	7		
Beavers (Y/N)	No				
Downstream End General Rating		7	7		
Structure Usage					
		Last	Now	Explanation of Condition	
Channel (U/S and D/S)					
Alignment		5	5	Channel u/s is a ditch-sharp bend into pipe-sharp bend @ d/s end @ RPP. Numerous dams further u/s.	
Bank Stability		7	6		
HWM (m below Top of Culvert)	0.4			No visible HWM.	
Drift (Y/N)	No				

Structure Usage				
		Last	Now	Explanation of Condition
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	Yes			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION	2013	From u/s & d/s grates.					
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION	2013	Re attach u/s beaver gratings.					
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	55.6/55.6	Sufficiency Rating (Last/Now) (%)	52.4/52.3	Est. Repl. Yr	2025	Maint. Req. (Y/N)	Yes
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	18-Jun-2014		Previous Inspection Date	06-Jan-2011			
Inspection Cycle (Default) (months)	21						
Comment							