

Bridge Culvert Inspection			
Bridge File Number	78875 -1 Bridge Culvert	Form Type	CUL1
Year Built	1998	Lot No.	4
Bridge or Town Name	HUSSAR	Inspector Name	Garry Roberts
Located Over	EID - IRRIGATION C, WATERCRS-IC	Inspector Class	BR CLS A
Located On	561:04 C1 31.859	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	26-Jan-2012
Legal Land Location	SE SEC 5 TWP 24 RGE 16 W4M	Data Entry By	Kelsey Roberts
Longitude, Latitude	-112:12:08, 51:00:32	Data Entry Date	04-Feb-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Joel Wozney
Contract Main. Area	CMA23	Review Date	30-Jan-2012
Clear Roadway/Skew	10 / 26 deg. (RHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	140 / 2010 (A)	Dept. Review Date	06-Feb-2012
Road Classification	RLU-209-110	Follow-Up By	
Detour Length (km)	20		

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	3000	MP	31	125X26	2.8,2.8,2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)			
Utility Attachments			
Telephone		Gas	
Power	2W to NE and 1W North of road to North	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		9	8	CANAL SERVICE RD ON BOTH SIDES OF PIPE
Vertical Alignment		9	9	
Roadway Width (m)	10.000			(2:1 over pipe into canal)
Embankment		N	7	
Sideslope ( _ :1)	3.0			
(Height of Cover(m) : <b>0.8</b> )				
Guardrail (Y/N)	No			
<b>Approach Road / Embankment General Rating</b>		<b>9</b>	<b>8</b>	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	600			
Scour Protection		N	8	
(Type : <b>RIP RAP</b> )				
(Avg. Rock Size(mm) : <b>300</b> )				
Scour/Erosion		N	8	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>N</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : <b>1</b> , Primary Span, Location Code: <b>MAIN</b> , Span (mm): , Rise (mm): <b>3000</b> , Type: <b>MP</b> )				
Barrel Last Accessible Date	26-Jan-2012			
<b>Special Features</b>				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		8	8	
Measured Rise (mm)				Estimate
Measured At Ring No.				
Sag (mm)	50			
Percent Sag	1			
Sidewall		8	8	Inward
Measured Span (mm)	2950			
Measured At Ring No.	3			
Deflection (mm)	50			
Percent Deflection	1			
Floor		N	8	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		8	8	
Separation (mm)	30			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		5	5	Soil corrosion- 10mm spots all along ice line No perforation or section loss
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 3000, Type: MP)				
Fish Passage Adequacy		X	7	
Baffle		X	X	
(Type : )				
Waterway Adequacy		8	6	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>8</b>	<b>8</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		N	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		N	8	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>N</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	CURVE D/S
Bank Stability		N	8	
HWM (m below Top of Culvert)	1.2			No visible HWM
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading				
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>8</b>	<b>8</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>88.9/88.9</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>82.4/79.9</b>	Est. Repl. Yr	2033	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Tom Carey		Previous Assistant's Name				
Next Inspection Date	26-Apr-2015		Previous Inspection Date	09-Feb-2010			
Inspection Cycle (Default) (months)	39						
Comment							