

Bridge Culvert Inspection			
Bridge File Number	78900 -1 Bridge Culvert	Form Type	CUL1
Year Built	1977	Lot No.	4
Bridge or Town Name	DONALDA	Inspector Name	Owen Salava
Located Over	TRAIL-ANIMAL, OVER SP	Inspector Class	BR CLS A
Located On	53:10 C1 29.090	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	29-Nov-2012
Legal Land Location	NE SEC 32 TWP 41 RGE 18 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-112:33:11, 52:34:32	Data Entry Date	06-Dec-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA20	Review Date	04-Dec-2012
Clear Roadway/Skew	10 /	Dept. Reviewer Name	Andrew Smikles
AADT/Year	880 / 2011 (A)	Dept. Review Date	10-Dec-2012
Road Classification	RAU-209-110	Follow-Up By	
Detour Length (km)	6		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	2100	MP	23.8	68X13	2.8	ROUND
Special Features								
Special Features Comment								

Posting Information

Required Vert. Clearance Posting (m)												
Posted Vertical Clearance (Y/N)	No											
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)	No	Lane	SB	On Bridge (m)		In Advance (Y/N)	No
Remarks	Not required.											

Utilities (Located at)

Utility Attachments											
Telephone						Gas					
Power	1 line North fenceline.					Municipal					
Others						Problem (Y/N)	No				
Remarks											

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		6	6	No passing, on curve. Blind crest curve to the East. Superelevated.
Vertical Alignment		6	6	
Roadway Width (m)	10.000			
Embankment		7	7	
Sideslope (___:1)	5.0			
(Height of Cover(m) : 1.5)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection (Type : NONE) (Avg. Rock Size(mm) :)		X	N	No flow.
Scour/Erosion		X	X	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2100, Type: MP)				
Barrel Last Accessible Date	29-Nov-2012			
Special Features				
Special Feature (Type :)				
Special Feature (Type :)				
Roof		7	7	Estimated.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	80			
Percent Sag	4			3.8%
Sidewall		7	7	
Measured Span (mm)	2180			
Measured At Ring No.	2			3.8%
Deflection (mm)	80			
Percent Deflection	4			
Floor		N	N	Concrete floor covered with dirt.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	Some material coming through. Seam not sitting evenly.
Separation (mm)	20			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		6	6	Some rust on exposed outside surface.
Corrosion By Soil (Y/N)	Yes			
Corrosion By Water (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2100, Type: MP)				
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		X	N	No flow.
(Type : NONE)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		X	X	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		7	7	Covered with dirt.
Roadway Surface		N	N	
(Type :)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type	None			
Lighting		X	X	
Barrel Leakage (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Drainage		7	7	
Structure In Use (Y/N)	Yes			Gate across North end.
Grade Separation General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	82.8/82.6	Est. Repl. Yr	2050	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date		Estimated Total	0	
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Owen Salava		Previous Assistant's Name				
Next Inspection Date	29-Aug-2014		Previous Inspection Date	09-May-2011			
Inspection Cycle (Default) (months)	21						
Comment							