

Bridge Culvert Inspection				
Bridge File Number	79040 -1 Bridge Culvert		Form Type	CUL1
Year Built	1983		Lot No.	4
Bridge or Town Name	LONGVIEW		Inspector Name	Garry Roberts
Located Over	MARSTON CK, 2.13.27.22, WATERCRS-ST		Inspector Class	BR CLS A
Located On	541:02 C1 10.861		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	11-Mar-2013
Legal Land Location	NE SEC 5 TWP 17 RGE 4 W5M		Data Entry By	Lauren Korte
Longitude, Latitude	-114:30:37, 50:24:25		Data Entry Date	07-Apr-2013
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Ash Morjaria
Contract Main. Area	CMA27		Review Date	21-Mar-2013
Clear Roadway/Skew	11.8 / 34 deg. (RHF)		Dept. Reviewer Name	Tim Davies
AADT/Year	510 / 2011 (A)		Dept. Review Date	08-Apr-2013
Road Classification	RCU-210-110		Follow-Up By	
Detour Length (km)	62			

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	1724	1901	SP	34.8	152X51	3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	North ROW.	Gas	
Power	South ROW.	Municipal	
Others		Problem (Y/N)	No
Remarks			

Approach Road / Embankment

	Last	Now	Explanation of Condition
Horizontal Alignment	6	6	On Curve No passing WB. Crest 150m West Superelevated.
Vertical Alignment	7	7	
Roadway Width (m)	11.700		
Embankment	7	7	1.0 at U/S and 2.0 at D/S.
Sideslope (:1)	3.0		
(Height of Cover(m) : 1.5)			
Guardrail (Y/N)	No		
Approach Road / Embankment General Rating	6	6	

Upstream End

Culvert Component	Last	Now	Explanation of Condition
Direction	N		North.
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape :)			

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	400			
Scour Protection		5	5	Minor scour at East side of bevel end.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 500)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		7	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SP)				
Barrel Last Accessible Date	11-Mar-2013			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	
Measured Rise (mm)	1982			
Measured At Ring No.	9			
Sag (mm)	19			Estimate due to ice.
Percent Sag	1			
Sidewall		7	7	
Measured Span (mm)	1745			
Measured At Ring No.	9			
Deflection (mm)	21			
Percent Deflection	1			
Floor		7	N	Ice. P.R 7.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		6	6	Minor superficial on floor.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): 1724, Rise (mm): 1901, Type: SP)				
Ponding (Y/N)	No			
Fish Passage Adequacy		5	5	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		South.
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		8	8	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 450)				
Scour/Erosion		8	8	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		7	7	
Bank Stability		7	7	
HWM (m below Top of Culvert)				No visible HWM.
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	NONE			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	75.1/73.0	Est. Repl. Yr	2028	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	11-Jun-2016		Previous Inspection Date	04-Oct-2009			
Inspection Cycle (Default) (months)	39						
Comment							