

Bridge Culvert Inspection				
Bridge File Number	79121 -1 Bridge Culvert		Form Type	CUL1
Year Built	1979		Lot No.	4
Bridge or Town Name	BARRHEAD		Inspector Name	Melanie Johnson
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS B
Located On	18:08 C1 4.492		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	27-Aug-2011
Legal Land Location	SE SEC 12 TWP 59 RGE 6 W5M		Data Entry By	Theresa Lacusta
Longitude, Latitude	-114:45:29, 54:04:46		Data Entry Date	19-Sep-2011
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Eric Carcoux
Contract Main. Area	CMA10		Review Date	07-Sep-2011
Clear Roadway/Skew	10.2 / 0 deg.		Dept. Reviewer Name	Brent Herrick
AADT/Year	880 / 2010 (A)		Dept. Review Date	28-Sep-2011
Road Classification	RAU-210-110		Follow-Up By	
Detour Length (km)	3			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	2134	MP	28	75X25	2.8	ROUND
Special Features								
Special Features Comment								

Posting Information											
Required Vert. Clearance Posting (m)											
Posted Vertical Clearance (Y/N)											
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)		In Advance (Y/N)
Remarks											

Utilities (Located at)				
Utility Attachments				
Telephone	South r/w.		Gas	
Power	2 lines North r/w, 2 lines crossing local road & 1 line OH crossing 50m East.		Municipal	
Others			Problem (Y/N)	No
Remarks				

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Local road intersection 40 m east. Blinding crest curve to east. No passing EB.
Vertical Alignment		5	5	
Roadway Width (m)	10.200			
Embankment		6	6	
Sideslope (__:1)	3.0			
(Height of Cover(m) : 1.9)				
Guardrail (Y/N)	Yes			North rail has 2 sections of flexbeam flattened.-still functional.
<b>Approach Road / Embankment General Rating</b>		<b>5</b>	<b>5</b>	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)		NONE		
Headwall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>5</b>	<b>5</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2134, Type: MP)				
Barrel Last Accessible Date	24-Aug-2011			
Special Features				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		5	5	Couldn't measure because of cold mix on floor. Assume sag same as deflection.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)				
Percent Sag				
Sidewall		5	5	
Measured Span (mm)	2280			
Measured At Ring No.	2			
Deflection (mm)	146			
Percent Deflection	7			
Floor		N	N	Covered with cold mix and mud. Only edges are visible.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	75			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2134, Type: MP)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type : )				
Waterway Adequacy		6	6	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
<b>Barrel General Rating</b>		<b>5</b>	<b>5</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 300)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>5</b>	<b>5</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Grade Separation</b>				
Road Alignment		8	8	Mostly under dirt.
Roadway Surface		N	N	
(Type : ACP)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type				

Structure Usage				
		Last	Now	Explanation of Condition
Lighting		X	X	
Barrel Leakage (Y/N)	No			
Drainage		5	5	
Structure In Use (Y/N)	No			
<b>Grade Separation General Rating</b>		<b>5</b>	<b>5</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/55.6</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>58.2/58.3</b>	Est. Repl. Yr	2021	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Melanie Johnson		Previous Assistant's Name				
Next Inspection Date	27-May-2013		Previous Inspection Date	05-Nov-2009			
Inspection Cycle (Default) (months)	21						
Comment							