

Bridge Culvert Inspection											
Bridge File Number	79463 -1 Bridge Culvert				Form Type	CUL1					
Year Built	1981				Lot No.	4					
Bridge or Town Name	CASLAN				Inspector Name	Todd Warshawski					
Located Over	TRAIL-ANIMAL, OVER SP				Inspector Class	BR CLS B					
Located On	663:08 C1 8.722				Assistant Name						
Water Body Cl./Year					Assistant Class						
Navigabil. Cl./Year					Inspection Date	09-Mar-2010					
Legal Land Location	SW SEC 24 TWP 65 RGE 17 W4M				Data Entry By	Theresa Lacusta					
Longitude, Latitude	-112:26:50, 54:37:52				Data Entry Date	24-Mar-2010					
Road Authority	Alberta Transportation (AIT)				Reviewer Name	Arnold Assenheimer					
Contract Main. Area	CMA07				Review Date	11-Mar-2010					
Clear Roadway/Skew	8 /				Dept. Reviewer Name	Brent Herrick					
AADT/Year	840 / 2008 (A)				Dept. Review Date	25-Mar-2010					
Road Classification	RCU-209-110				Follow-Up By						
Detour Length (km)	5										
Bridge Culvert Information											
Number of Culverts	1										
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape			
1	MAIN	-	1800	MP	18.9	125X26	2.8	ROUND			
Special Features											
Special Features Comment	BF tag on top of N. bevel.										
Posting Information											
Required Vert. Clearance Posting (m)											
Posted Vertical Clearance (Y/N)	No										
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)		In Advance (Y/N)
Remarks	not req'd										
Utilities (Located at)											
Utility Attachments											
Telephone	Along South ditch.				Gas						
Power	1 OH 15 m North of c/l.				Municipal						
Others	Supernet N r/w				Problem (Y/N)	No					
Remarks	Power line x's road 50m East of culvert.										
Approach Road / Embankment											
			Last	Now	Explanation of Condition						
Horizontal Alignment			7	7	Curve to west. Residential access to East.						
Vertical Alignment			8	8							
Roadway Width (m)	8.000										
Embankment			N	7							
Sideslope (__:1)	3.0										
(Height of Cover (m) : 0.8)											
Guardrail (Y/N)	No										
Approach Road / Embankment General Rating			7	7							
Upstream End											
Culvert Component			Last	Now	Explanation of Condition						
Direction			N								
End Treatment (Concrete, Steel, Others, None)	STEEL										
Headwall			X	X							

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		X	X	
(Type :)				
(Avg. Rock Size (mm) :)				
Scour/Erosion		N	X	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): -, Rise (mm): 1800, Type: MP)				
Barrel Last Accessible Date	09-Mar-2010			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		8	7	Not measured due to ice/gravel.
Measured Rise (mm)				Est. @ 2%
Measured At Ring No.				
Sag (mm)	0			
Percent Sag				
Sidewall		7	7	
Measured Span (mm)	1783			@ cl
Measured At Ring No.				
Deflection (mm)	17			
Percent Deflection	1			
Floor		N	N	Cold mix on floor.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	60			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): -, Rise (mm): 1800, Type: MP)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	Yes			Drainage blocked at South end.
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	X	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	

Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		S		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls (Shape :)		X	X	
Cutoff Wall		X	X	
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		X	X	
(Type :) (Avg. Rock Size (mm) :)				
Scour/Erosion		N	X	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	

Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		8	8	200mm water/ice in barrel.
Roadway Surface		7	7	
(Type :)				Cold mix/gravel
Icing (Y/N)	No			

Structure Usage				
		Last	Now	Explanation of Condition
Traffic Safety Features		X	X	
Type				
Lighting		X	X	
Barrel Leakage (Y/N)	No			
Drainage		4	4	Soils in inlets block drainage. 200mm water in pipe.
Structure In Use (Y/N)	No			
Grade Separation General Rating		4	4	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	80.8/80.7	Est. Repl. Yr	2035	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Saly		Previous Assistant's Name				
Next Inspection Date	09-Jun-2013		Previous Inspection Date	05-Dec-2006			
Inspection Cycle (Default) (months)	39						
Comment							