

Bridge Culvert Inspection				
Bridge File Number	79541 -1 Bridge Culvert		Form Type	CUL1
Year Built	1982		Lot No.	4
Bridge or Town Name	HUSSAR		Inspector Name	Jon Davies
Located Over	TRAIL-ANIMAL, OVER SP		Inspector Class	BR CLS B
Located On	56:06 C1 38.171		Assistant Name	
Water Body Cl./Year			Assistant Class	
Navigabil. Cl./Year			Inspection Date	29-Nov-2011
Legal Land Location	SE SEC 31 TWP 25 RGE 19 W4M		Data Entry By	Alyssa Boynton
Longitude, Latitude	-112:37:59, 51:10:20		Data Entry Date	04-Jan-2012
Road Authority	Alberta Transportation (AIT)		Reviewer Name	Garry Roberts
Contract Main. Area	CMA30		Review Date	07-Dec-2011
Clear Roadway/Skew	10.4 /		Dept. Reviewer Name	Alvin Gale
AADT/Year	840 / 2010 (A)		Dept. Review Date	12-Jan-2012
Road Classification	RAU-211.8-110		Follow-Up By	
Detour Length (km)	5			

Bridge Culvert Information								
Number of Culverts		1						
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	PI./Slab Thickness	Shape
1	MAIN	-	2200	MP	30	125X26	2.8	ROUND
Special Features								
Special Features Comment								

Posting Information										
Required Vert. Clearance Posting (m)										
Posted Vertical Clearance (Y/N)		No								
Posted:	Lane	NB	On Bridge (m)		In Advance (Y/N)		Lane	SB	On Bridge (m)	In Advance (Y/N)
Remarks	Not required									

Utilities (Located at)			
Utility Attachments			
Telephone	West ditch		Gas
Power	East fence line - 2 wire		Municipal
Others	Bell fibre optic line-E ROW		Problem (Y/N) No
Remarks			

Approach Road / Embankment				
		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	Driveway 15m S of culv limit No passing NB. Limited sight distance to north.
Vertical Alignment		6	6	
Roadway Width (m)	10.400			
Embankment		7	7	
Sideslope (__:1)	3.5			
(Height of Cover(m) : 1.5)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		6	6	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	ABOVE			
Above/Below (mm)	100			
Scour Protection		7	6	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		7	6	
Beavers (Y/N)	No			
Upstream End General Rating		7	6	

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Barrel Last Accessible Date	29-Nov-2011			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		5	5	Minor tear @ roof @ section 1
Measured Rise (mm)	2050			Estimate.
Measured At Ring No.	3			
Sag (mm)	150			
Percent Sag	7			
Sidewall		4	4	Sheet metal Repair @ tear @ south sidewall @ ring 2
Measured Span (mm)	2390			Horizontal change of 8%.
Measured At Ring No.	2			
Deflection (mm)	190			
Percent Deflection	8			
Floor		N	N	dirt covered
Bulge (mm)				
Measured At Ring No.				
Abrasion (Y/N)				
Circumferential Seams		7	7	
Separation (mm)	20			
Longitudinal Seams		X	X	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	Yes			
Longitudinal Stagger (Y/N)	Yes			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP)				
Coating		6	6	MINOR SUPERFICIAL @ SOIL INTERFACE @ W CROWN.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		X	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		4	4	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		E		East end.
End Treatment (Concrete, Steel, Others, None)	NONE			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		X	X	
Heaving (mm)				
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	50			
Scour Protection		6	6	
(Type : NATURAL)				
(Avg. Rock Size(mm) :)				
Scour/Erosion		6	6	
Beavers (Y/N)	No			
Downstream End General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Grade Separation				
Road Alignment		X	X	DIRT
Roadway Surface		7	7	
(Type : SOIL)				
Icing (Y/N)	No			
Traffic Safety Features		X	X	
Type				

Structure Usage				
		Last	Now	Explanation of Condition
Lighting		X	X	
Barrel Leakage (Y/N)	No			
Drainage		7	7	
Structure In Use (Y/N)	Yes			
Grade Separation General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	66.5/59.3	Est. Repl. Yr	2025	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	29-Aug-2013		Previous Inspection Date	13-May-2010			
Inspection Cycle (Default) (months)	21						
Comment							