						0-1-							
					Bridg	e Culve	ert Inspe						
Bridge File Nur		79733 -1 Bridge Culvert				Form Type			CUL1				
Year Built 1983						Lot No.			4				
Bridge or Town Name LONGVIEW						Inspector Name			Garry Roberts				
Located Over TRAIL-ANIMAL, OVER SP						Inspector Class		BR CLS A					
Located On	5	41:02 C	1 20.671				Assista	nt Name					
Water Body Cl	./Year				Assistant Class			nt Class					
Navigabil. Cl./\	'ear					Inspection Date			11-Mar-2013				
Legal Land Loc	cation N	IE SEC	25 TWP 17	RGE 4 W5I	E 4 W5M			ntry By	Lauren Korte				
Longitude, Lati	9, 50:27:59				Data Entry Date		07-Apr-2013	07-Apr-2013					
			Transportation (AIT)				Reviewer Name		Ash Morjaria	Ash Morjaria			
Contract Main.					Review Date		21-Mar-2013	21-Mar-2013					
Contract Main. Area CMA27 Clear Roadway/Skew 11.8 /							Dept. Reviewer Name		me Tim Davies				
AADT/Year	5	10 / 201	I1 (A)				Dept. Review Date		08-Apr-2013				
Road Classifica	ation R	CU-211	I - 110				Follow-Up By						
Detour Length	(km) 2	0											
Bridge Culver	` '	tion											
Number of Cul		1											
Pipe #			Span Rise (or		Dia.) Type			Length	Corr. Profile	PI./Slab Thickness	Shape		
1	MAIN		2400			MP		27	125X26	2.8	ROUND		
Special Feature	es												
Special Feature	es Comme	ent											
					Ро	sting Ir	nformati	on					
Required Vert.													
Posted Vertica			No)									
Posted: Lane	NB	On Br	ridge (m)	In Adv	ance (Y/N)	No La	ane SB	On Bridge (m)	In Advan	ce (Y/N) No		
Remarks	Not requ	uired.											
					Uti	lities (L	_ocated	at)					
Utility Attachme	ents												
Telephone	West R								est ditch 60m.				
Power	East RC	DW.					Municipal						
Others	Fibre op	tics We	st ROW.				Problen	n (Y/N) No)				
Remarks													
				A			d / Emba						
					Last	Now	Explan	Explanation of Condition					
Horizontal Alig	nment				6	6	On long	curve. Far	m entrance 100 So	outh. Superele	vated.		
Vertical Alignm	ent		_		8	8							
Roadway Width (m)		11.800			_								
Embankment				5	5	At East	3:1 at West						
Sideslope (:1)		1.5				0.8 West 1.7 @ East- H		st- HOC.	HOC.				
(Height of Co	ver(m) : 1	.3)											
Guardrail (Y/N)		Yes											
Approach Roa	ad / Emba	nkment	t General Ra	ating	6	6							
						Upstre	am End						
Culvert Comp	onent				Last	Now		ation of Co	ndition				
Direction				W	, , , , , ,	West.							
End Treatment (Concrete, Steel, Others, None)		NONE											
Headwall				Х	Х								

79733 -1 Bridge Culvert

			Upstre	eam End
Culvert Component		Last	Now	Explanation of Condition
Wingwalls		Х	X	
(Shape:)				
Cutoff Wall		X	X	
Bevel End		Х	Х	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		7	7	
(Type: RIP RAP)				
(Avg. Rock Size(mm) : 300)			_	
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
		Bri	dge Cu	Ivert Barrel
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Spa	n (mm	ı):	, Rise (mm): 2400, Type: MP)
Barrel Last Accessible Date	11-Mar-2012			
Special Features				
Special Feature				
(Type:)				
Special Feature				
(Type:)		'		
Roof		7	7	Estimate.
Measured Rise (mm)				
Measured At Ring No.				
Sag (mm)	15			
Percent Sag	0			
Sidewall		8	8	
Measured Span (mm)	2415			
Measured At Ring No.	1			
Deflection (mm)	15			
Percent Deflection	0			
Floor		N	N	300mm dirt floor.
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		7	7	
Separation (mm)	51			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			

79733 -1 Bridge Culvert

		Brid	dge Cu	Ivert Barrel				
Culvert Component								
(Pipe # : 1, Primary Span, Location Code: MAIN, Span			1):	, Rise (mm): 2400, Type: MP)				
Camber POS/ZERO/NEG	ZERO							
Ponding (Y/N) No								
Fish Passage Adequacy			Х					
Baffle		Х	Х					
(Type:)								
Waterway Adequacy		7	7	Ditches drain into pipe. Pipe is lowest point in immediate area.				
Icing (Y/N)	No			Pipe is lowest point in ininediate area.				
Silting (Y/N)	No							
Drift (Y/N)	No							
Barrel General Rating		7	7					
				ream End				
Culvert Component			Now	Explanation of Condition				
Direction Comments Office	NONE	E		East.				
End Treatment (Concrete, Steel, Others, None)	NONE							
Headwall		X	X					
Collar		Х	Х					
Wingwalls		Х	Х					
(Shape:)		1						
Cutoff Wall		X	X					
Bevel End		Х	X					
Heaving (mm)	0							
Invert Above/Below Stream Bed	BELOW							
Above/Below (mm)	400							
Scour Protection		5	5	Slumping into pipe- minor.				
(Type : NATURAL)								
(Avg. Rock Size(mm):)		1	1					
Scour/Erosion		5	5					
Beavers (Y/N)	No							
Downstream End General Ratio	ng	5	5					
		5	Structu	re Usage				
		Last	Now	Explanation of Condition				
Grade Separation								
Road Alignment		X	X					
Roadway Surface		5	5					
				(Collects water, 800mm deep @ this inspection-Sept.12/06).				
(Type : SOIL)								
Icing (Y/N)	No							
		V	V					
Traffic Safety Features	NONE	X	X					
Type	NONE	X	Х					
Lighting		_ ^	_ ^					

Structure Usage								
		Last	Now	Explanation of Condition				
Barrel Leakage (Y/N)	No							
Drainage		5	5					
Structure In Use (Y/N) No			-					
Grade Separation General Rating			5					

		Maintena	nce Recommer	dations					
Inspector Recommendations		Department Con	nments		Target Year	Est. Cost	Cat #		
SHOTCRETE REPAIRS									
PLACE ADDITIONAL RIP RAP									
REMOVE DRIFT ACCUMULATION									
INSTALL CONCRETE/STEEL LINING	3								
INSTALL STRUTS									
INSTALL CONCRETE COLLAR/CUT	OFF								
REPAIR SEAMS									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
OTHER ACTION									
Structural Condition Rating (Last/N (%)	low) 77.8/77	7.8 Sufficiency Rating (%)	(Last/Now)	72.3/72.4	Est. Repl. Yr	2030	Maint. Re	qd. (Y/N)	No
Special Comments for Next Inspection				Department Comments					
Maintenance Reviewed By				Date		E	Estimated Total	0	
Proposed Long-Term Strategy									
On 3-Year Program (Y/N)									
Proposed Action									
Previous Inspector's Name Garry Robe			Previous	s Assistant's Name					
Next Inspection Date	11-Jun-2016		Previous	Inspection Date	06-Oct-2009				
Inspection Cycle (Default) (months)	39								
Comment									