

Bridge Culvert Inspection			
Bridge File Number	80400 -1 Bridge Culvert	Form Type	CUL1
Year Built	1982	Lot No.	4
Bridge or Town Name	MILO	Inspector Name	Jason Rusu
Located Over	TRIBUTARY TO MCGREGOR LAKE, 12.6, WATERCRS-ST	Inspector Class	BR CLS A
Located On	842:06 C1 2.995	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	16-Feb-2012
Legal Land Location	NW SEC 10 TWP 19 RGE 21 W4M	Data Entry By	Alyssa Boynton
Longitude, Latitude	-112:50:39, 50:35:57	Data Entry Date	16-Mar-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA25	Review Date	24-Feb-2012
Clear Roadway/Skew	12 / -25 deg. (LHF)	Dept. Reviewer Name	Tim Davies
AADT/Year	310 / 2010 (A)	Dept. Review Date	22-Mar-2012
Road Classification	RCU-210-110	Follow-Up By	
Detour Length (km)	3		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1829	SP	93.9	152X51	3.0	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments			
Telephone	East ditch	Gas	
Power	50m east	Municipal	
Others		Problem (Y/N)	No
Remarks	power is high voltage steel towers.		

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		7	7	road rises to N & S
Vertical Alignment		6	6	
Roadway Width (m)	10.000			
Embankment		7	7	
Sideslope (_ :1)	2.5			
(Height of Cover(m) : 12.4)				
Guardrail (Y/N)	Yes			
Approach Road / Embankment General Rating		6	6	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction		E		EAST
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		6	6	
Heaving (mm)	300			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	300			
Scour Protection		5	5	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		5	5	
Beavers (Y/N)	No			
Upstream End General Rating		5	5	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 1829 , Type: SP)				
Barrel Last Accessible Date	16-Feb-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		7	7	
Measured Rise (mm)	1734			
Measured At Ring No.	13			
Sag (mm)	95			
Percent Sag	5			
Sidewall		7	7	
Measured Span (mm)	1895			
Measured At Ring No.	13			
Deflection (mm)	66			
Percent Deflection	4			
Floor		N	6	
Bulge (mm)	0			
Measured At Ring No.	13			
Abrasion (Y/N)	No			
Circumferential Seams		8	7	
Separation (mm)	0			
Longitudinal Seams		7	7	
Total No. of Cracked Rings	0			
Total No. of Rings with Two Cracked Seams	0			
Min. Remaining Steel Between Cracks (mm)	0			
Proper Lap (Y/N)	No			
Longitudinal Stagger (Y/N)	No			
Coating		6	6	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1829, Type: SP)				
Fish Passage Adequacy		6	6	
Baffle		X	X	
(Type :)				
Waterway Adequacy		6	6	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		W		WEST
End Treatment (Concrete, Steel, Others, None)		STEEL		
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		6	6	
Heaving (mm)	300			
Invert Above/Below Stream Bed		BELOW		
Above/Below (mm)	350			
Scour Protection		6	6	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 200)				
Scour/Erosion		6	6	
Beavers (Y/N)		No		
Downstream End General Rating		6	6	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		5	5	Channel turns 45 deg S @ u/s end
Bank Stability		7	7	
HWM (m below Top of Culvert)				No HWM visible
Drift (Y/N)		No		
Channel Bottom Degrading/Aggrading		DEGRADING		
Beavers (Y/N)		No		
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		5	5	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	77.8/77.8	Sufficiency Rating (Last/Now) (%)	70.1/70.1	Est. Repl. Yr	2038	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Jason Rusu		Previous Assistant's Name				
Next Inspection Date	16-May-2015		Previous Inspection Date	06-Mar-2010			
Inspection Cycle (Default) (months)	39						
Comment							