

Bridge Culvert Inspection			
Bridge File Number	80415 -1 Bridge Culvert	Form Type	CUL1
Year Built	1982	Lot No.	4
Bridge or Town Name	WARNER	Inspector Name	Jason Rusu
Located Over	TRIBUTARY TO VERDIGRIS COULEE, 1.12.3, WATERCRS-ST	Inspector Class	BR CLS A
Located On	504:02 C1 11.760	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	09-Jun-2012
Legal Land Location	SW SEC 13 TWP 4 RGE 16 W4M	Data Entry By	Erin Roberts
Longitude, Latitude	-112:02:15, 49:17:25	Data Entry Date	19-Jul-2012
Road Authority	Alberta Transportation (AIT)	Reviewer Name	Garry Roberts
Contract Main. Area	CMA24	Review Date	10-Jul-2012
Clear Roadway/Skew	11 /	Dept. Reviewer Name	Tim Davies
AADT/Year	260 / 2011 (A)	Dept. Review Date	30-Jul-2012
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	5		

Bridge Culvert Information

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	1600	MP	26		2.8	ROUND
Special Features								
Special Features Comment								

Utilities (Located at)

Utility Attachments							
Telephone	South ROW.			Gas			
Power				Municipal			
Others				Problem (Y/N)	No		
Remarks							

Approach Road / Embankment

		Last	Now	Explanation of Condition
Horizontal Alignment		9	9	
Vertical Alignment		9	9	
Roadway Width (m)	9.700			
Embankment		7	7	
Sideslope (__:1)	4.0			
(Height of Cover(m) : 1)				
Guardrail (Y/N)	No			
Approach Road / Embankment General Rating		9	9	

Upstream End

Culvert Component		Last	Now	Explanation of Condition
Direction				NORTH
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed				
Above/Below (mm)	0			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 150)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Upstream End General Rating		7	7	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1 , Primary Span, Location Code: MAIN , Span (mm): , Rise (mm): 1600 , Type: MP)				
Barrel Last Accessible Date	09-Jun-2012			
Special Features				
Special Feature				
(Type :)				
Special Feature				
(Type :)				
Roof		4	4	Deflection at R2 only - remainder of pipe has good shape. Reference marks
Measured Rise (mm)	1470			
Measured At Ring No.	2			
Sag (mm)	130			
Percent Sag	8			
Sidewall		6	6	
Measured Span (mm)	1675			
Measured At Ring No.	2			
Deflection (mm)	75			
Percent Deflection	5			
Floor		7	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		6	6	
Separation (mm)	60			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		7	7	
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	No			
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1600, Type: MP)				
Fish Passage Adequacy		X	X	
Baffle		X	X	
(Type :)				
Waterway Adequacy		7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		4	4	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction				South
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape :)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	50			
Scour Protection		7	7	
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 100)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Downstream End General Rating		7	7	
Structure Usage				
		Last	Now	Explanation of Condition
Channel (U/S and D/S)				
Alignment		8	8	PIPE SEEMS TO DRAIN LARGE FIELD NO CHANNEL EVIDENT U/S SMALL CHANNEL D/S.
Bank Stability		7	7	
HWM (m below Top of Culvert)				HWM not visible
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	DEGRADING			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
Channel General Rating		7	7	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
Structural Condition Rating (Last/Now) (%)	44.4/44.4	Sufficiency Rating (Last/Now) (%)	62.4/62.4	Est. Repl. Yr	2050	Maint. Req. (Y/N)	No
Special Comments for Next Inspection			Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy							
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Garry Roberts		Previous Assistant's Name				
Next Inspection Date	09-Sep-2015		Previous Inspection Date	20-Jun-2009			
Inspection Cycle (Default) (months)	39						
Comment							