					Bride	o Cube	ort Inche	oction					
Bridge File Nun	nhor	00470 4 Deleter Oct				Bridge Culvert Inspection			CUL1				
Bridge File Number 80478 -1 Bridge Culvert						Form Type		4					
Year Built 1986 Bridge or Town Name LUNDBRECK					Lot No.			-	<u> </u>				
					Inspector Name Inspector Class			Garry Roberts					
Located Over TRAIL-ANIMAL, OVER				VER SP	SP				BR CLS A				
Located On 22:08 C1 16.782						Assistant Name							
Water Body Cl./Year						Assistant Class							
Navigabil. Cl./Y						Inspection Date				16-Jun-2012			
Legal Land Loc	25 TWP 1	1 RGE 2 W	5M		Data Entry By			Erin Roberts					
Longitude, Latit		41, 49:56:38				ntry Date	17-Jul-2012	17-Jul-2012					
Road Authority	Fransporta	ransportation (AIT)				er Name	Joel Wozney	Joel Wozney					
Contract Main.					Review Date		28-Jun-2012	28-Jun-2012					
Clear Roadway	/Skew	11.8 /					Dept. Reviewer Name		ne Tim Davies	Tim Davies			
AADT/Year		2,210 / 2	2011 (A)				Dept. Review Date		17-Jul-2012				
Road Classifica	ation	RAU-21	1.8-110				Follow-Up By						
Detour Length	(km)	18											
Bridge Culvert	Inform	ation											
Number of Culv	/erts	1	1										
Pipe #	Barrel		Span	Rise (o	r Dia.)	Туре		Length	Corr. Profile	PI./Slab Thickness	Shape		
1	MAIN	5	5100	3200		RPE		35.4	152X51	4.0	ELLIPSE		
Special Feature	es												
Special Feature	es Comr	ment											
					Ро	sting Ir	nformati	on					
Required Vert.	Clearan	ce Postir	ng (m)										
Posted Vertical	Clearar	nce (Y/N)		No									
Posted: Lane	WB	On B	ridge (m)	In Ac	dvance (Y/N)	No La	ane EB	On Bridge (m)	In Adva	nce (Y/N) No		
Remarks	Not Re	equired											
					Uti	ilities (L	Located	at)					
Utility Attachme													
Telephone	East d	litch.					Gas						
Power							Municip	oal Alt	alink @ West fend	nk @ West fenceline.			
Others	Fibre	optics @	East r/w.				Probler	Problem (Y/N) No					
Remarks													
					Approac			nkment					
					Last	Now		Explanation of Condition					
Horizontal Align	nment				7	7	No pas	sing SBL. d 200m Sout	h of 72266				
Vertical Alignm	ent				6	6	Localed	200111 3001	11 01 7 3 3 0 0				
Roadway Width (m)		11.800											
Embankment					7	7							
Sideslope (:1)		3.5											
(Height of Co	· ·	2.2)											
Guardrail (Y/N)		Yes					lamage @ N	E Turndown					
Approach Roa	d / Emb	ankmen	t General	Rating	6	6							
						Unstre	am End						
Culvert Compo	onent				Last	Now		ation of Co	ndition				
Direction				W		West							
End Treatment (Concrete, Steel, Others, None)		, STEEL											
Headwall					X	Х							
Collar				X	X								

80478 -1 Bridge Culvert

Upstream End										
Culvert Component		Last	Now	Explanation of Condition						
Wingwalls		Х	Х							
(Shape:)										
Cutoff Wall		Х	X							
Bevel End		7	7							
Heaving (mm)	0									
Invert Above/Below Stream Bed										
Above/Below (mm) 0										
Scour Protection			7							
(Type: NATURAL)										
(Avg. Rock Size(mm):)			_							
Scour/Erosion		7	7							
Beavers (Y/N)	No									
Upstream End General Rating		7	7							
		Brid	dge Cu	Ivert Barrel						
Culvert Component		Last	Now	Explanation of Condition						
(Pipe # : 1, Primary Span, Loca	tion Code: MAIN, Spa	n (mm): 5100	, Rise (mm): 3200, Type: RPE)						
Barrel Last Accessible Date	16-Jun-2012									
Special Features		<u> </u>								
Special Feature										
(Type:)										
Special Feature										
(Type:)										
Roof		7	7	Slight visible sag in roof.						
Measured Rise (mm)				- Estimate						
Measured At Ring No.										
Sag (mm)	100									
Percent Sag	3									
Sidewall		8	8							
Measured Span (mm)	5171									
Measured At Ring No.	4									
Deflection (mm)	71									
Percent Deflection	1									
Floor		N	N	400mm fill on floor. 200mm water.						
Bulge (mm)				200mm water.						
Measured At Ring No.										
Abrasion (Y/N)										
Circumferential Seams			7							
Separation (mm) 0										
Longitudinal Seams		7	7	West roof seams gap @ rings #1 & 2 - 3mm to 6mm						
Total No. of Cracked Rings 0										
Total No. of Rings with Two Cracked Seams										
Min. Remaining Steel Between Cracks (mm)				3N stagger at roof seams only						
Proper Lap (Y/N) No				,						
Longitudinal Stagger (Y/N)	No									
Coating		7	7							
Corrosion By Soil (Y/N)	No									
Corrosion By Water (Y/N)	No									

		Brid	dge Cu	vert Barrel
Culvert Component		Last	Now	Explanation of Condition
(Pipe #: 1, Primary Span, Loca	tion Code: MAIN, Spa	an (mm): 5100	, Rise (mm): 3200, Type: RPE)
Camber POS/ZERO/NEG	NEG			
Ponding (Y/N)	No			
Fish Passage Adequacy		Х	Х	
Baffle		Х	Х	
(Type:)				
Waterway Adequacy	1	7	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	No			
Barrel General Rating		7	7	
	ĭ			eam End
Culvert Component			Now	Explanation of Condition
Direction	I	E		East
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	Х	
Collar		Х	X	
Wingwalls		X	Х	
(Shape:)				
Cutoff Wall		X	X	
Bevel End		7	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		7	7	
(Type: NATURAL)				
(Avg. Rock Size(mm):)				
Scour/Erosion		7	7	
Beavers (Y/N)	No			
Downstream End General Ratio	ng	7	7	
		5	Structu	re Usage
		Last	Now	Explanation of Condition
Grade Separation		Х		
Road Alignment			X	
Roadway Surface		7	7	
(Type : GRAVEL)				
Icing (Y/N)	No			
Traffic Safety Features		Х	Х	
Туре				
Lighting		Х	Х	
Barrel Leakage (Y/N)	No			

Structure Usage									
		Last	Now	Explanation of Condition					
Drainage		5	5	200mm water in pipe					
Structure In Use (Y/N) Yes									
Grade Separation General Rating			5						

			Maintenand	ce Recommen	dations					
Inspector Recommendations	Yea	ar Inspect	tor Comments		Department Com	ments		Target Year	Est. Cost	Cat #
SHOTCRETE REPAIRS										
PLACE ADDITIONAL RIP RAP										
REMOVE DRIFT ACCUMULATION										
INSTALL CONCRETE/STEEL LINING	3									
INSTALL STRUTS										
INSTALL CONCRETE COLLAR/CUT	OFF									
REPAIR SEAMS										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
OTHER ACTION										
Structural Condition Rating (Last/N (%)	low) 77.8	8/77.8	Sufficiency Rating (I	_ast/Now)	73.0/73.0	Est. Repl. Yr	2042	Maint. Re	qd. (Y/N)	No
Special Comments for Next Inspection					Department Comments					
Maintenance Reviewed By					Date		E	stimated Tota	I 0	
Proposed Long-Term Strategy										
On 3-Year Program (Y/N)										
Proposed Action										
Previous Inspector's Name Garry		erts		Previous	Assistant's Name					
Next Inspection Date	16-Mar-201	14		Previous	Inspection Date	07-Oct-2010				
Inspection Cycle (Default) (months)	21			'						
Comment										