

| Bridge Culvert Inspection |  |                     |                    |
|---------------------------|--|---------------------|--------------------|
| Bridge File Number        | 80541 -1 Bridge Culvert                            | Form Type           | CUL1               |
| Year Built                | 1983   | Lot No.             | 2                  |
| Bridge or Town Name       | HIGH LEVEL   | Inspector Name      | Brian Pientsch     |
| Located Over              | TRIBUTARY TO BUSHE RIVER, 8.10.23.6.2, WATERCRS-ST | Inspector Class     | BR CLS A           |
| Located On                | 58:06 C1 51.417                                    | Assistant Name      | Lisbeth Medina     |
| Water Body Cl./Year       |  | Assistant Class     |                    |
| Navigabil. Cl./Year       |  | Inspection Date     | 25-May-2010        |
| Legal Land Location       | SE SEC 17 TWP 110 RGE 21 W5M                       | Data Entry By       | Theresa Lacusta    |
| Longitude, Latitude       | -117:28:03, 58:33:04                               | Data Entry Date     | 28-Jun-2010        |
| Road Authority            | Alberta Transportation (AIT)                       | Reviewer Name       | Arnold Assenheimer |
| Contract Main. Area       | CMA01  | Review Date         | 23-Jun-2010        |
| Clear Roadway/Skew        | 8.4 /  | Dept. Reviewer Name | Steve Pasquan      |
| AADT/Year                 | 630 / 2009 (A)                                     | Dept. Review Date   | 10-Sep-2010        |
| Road Classification       | RAU-209-110  | Follow-Up By        |                    |
| Detour Length (km)        | 999  |                     |                    |

**Bridge Culvert Information**

|                          |        |      |                |      |        |               |                    |       |
|--------------------------|--------|------|----------------|------|--------|---------------|--------------------|-------|
| Number of Culverts       | 1      |      |                |      |        |               |                    |       |
| Pipe #                   | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1                        | MAIN   | -    | 1800           | MP   | 35     | 125X26        | 2.8                | ROUND |
| Special Features         |        |      |                |      |        |               |                    |       |
| Special Features Comment |        |      |                |      |        |               |                    |       |

**Utilities (Located at)**

|                     |  |               |    |
|---------------------|--|---------------|----|
| Utility Attachments |  |               |    |
| Telephone           |  | Gas           |    |
| Power               |  | Municipal     |    |
| Others              |  | Problem (Y/N) | No |
| Remarks             |  |               |    |

**Approach Road / Embankment**

|  |       | Last     | Now      | Explanation of Condition |
|--|-------|----------|----------|--------------------------|
| Horizontal Alignment                             |       | 8        | 8        |                          |
| Vertical Alignment                               |       | 8        | 8        |                          |
| Roadway Width (m)                                | 8.400 |          |          |                          |
| Embankment                                       |       | 7        | 7        |                          |
| Sideslope ( __:1)                                | 3.0   |          |          |                          |
| (Height of Cover(m) : 3)                         |       |          |          |                          |
| Guardrail (Y/N)                                  | No    |          |          |                          |
| <b>Approach Road / Embankment General Rating</b> |       | <b>8</b> | <b>8</b> |                          |

**Upstream End**

| Culvert Component                             |       | Last | Now | Explanation of Condition            |
|---|-------|------|-----|-------------------------------------|
| Direction                                     |       | N    |     | Water 0.9m deep.                    |
| End Treatment (Concrete, Steel, Others, None) | STEEL |      |     |                                     |
| Headwall                                      |       | X    | X   |                                     |
| Collar  |       | X    | X   |                                     |
| Wingwalls                                     |       | X    | X   |                                     |
| (Shape : )                                    |       |      |     |                                     |
| Cutoff Wall                                   |       | X    | X   | (Rated above waterline. 2003/05/15) |

| Upstream End  |             |          |          |  |
|---|-------------|----------|----------|--|
| Culvert Component   |             | Last     | Now      | Explanation of Condition   |
| Bevel End   |             | N        | 6        | Dent 2/7 o'clock.  |
| Heaving (mm)  | 90          |          |          |  |
| Invert Above/Below Stream Bed   | BELOW       |          |          | End of bevel under water.  |
| Above/Below (mm)  | 200         |          |          |  |
| Scour Protection  |             | N        | 5        |  |
| (Type : <b>NATURAL</b> )  |             |          |          |  |
| (Avg. Rock Size(mm) : )   |             |          |          |  |
| Scour/Erosion   |             | N        | 5        |  |
| Beavers (Y/N)   | No          |          |          |  |
| <b>Upstream End General Rating</b>  |             | <b>6</b> | <b>5</b> |  |
| Bridge Culvert Barrel   |             |          |          |  |
| Culvert Component   |             | Last     | Now      | Explanation of Condition   |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP) |             |          |          |  |
| Barrel Last Accessible Date   | 07-Dec-1999 |          |          | (Too much water, looks good as viewed from the ends. Water 0.9 to 1.1m deep. |
| <b>Special Features</b>   |             |          |          |  |
| Special Feature   |             |          |          |  |
| (Type : )   |             |          |          |  |
| Special Feature   |             |          |          |  |
| (Type : )   |             |          |          |  |
| Roof  |             | N        | N        |  |
| Measured Rise (mm)  |             |          |          |  |
| Measured At Ring No.  |             |          |          |  |
| Sag (mm)  | 120         |          |          |  |
| Percent Sag   | 7           |          |          |  |
| Sidewall  |             | N        | N        |  |
| Measured Span (mm)  |             |          |          |  |
| Measured At Ring No.  |             |          |          |  |
| Deflection (mm)   | 120         |          |          |  |
| Percent Deflection  |             |          |          |  |
| Floor   |             | N        | N        |  |
| Bulge (mm)  |             |          |          |  |
| Measured At Ring No.  |             |          |          |  |
| Abrasion (Y/N)  |             |          |          |  |
| Circumferential Seams   |             | N        | N        |  |
| Separation (mm)   | 65          |          |          |  |
| Longitudinal Seams  |             | X        | X        |  |
| Total No. of Cracked Rings  |             |          |          |  |
| Total No. of Rings with Two Cracked Seams   |             |          |          |  |
| Min. Remaining Steel Between Cracks (mm)  |             |          |          |  |
| Proper Lap (Y/N)  |             |          |          |  |
| Longitudinal Stagger (Y/N)  |             |          |          |  |
| Coating   |             | N        | 4        | (Rusty & pitted above waterline. Viewed from ends.                           |
| Corrosion By Soil (Y/N)   |             |          |          |  |
| Corrosion By Water (Y/N)  | Yes         |          |          |  |
| Camber POS/ZERO/NEG   | NEG         |          |          |  |
| Ponding (Y/N)   | Yes         |          |          | (Ponding 1.2m 2005/03/17)  |

| Bridge Culvert Barrel   |     |          |          |  |
|---|-----|----------|----------|--|
| Culvert Component   |     | Last     | Now      | Explanation of Condition                 |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 1800, Type: MP) |     |          |          |  |
| Fish Passage Adequacy   |     | 7        | 7        |  |
| Baffle  |     | X        | X        |  |
| (Type : )   |     |          |          |  |
| Waterway Adequacy   |     | 7        | 7        |  |
| Icing (Y/N)   | No  |          |          |  |
| Silting (Y/N)   | Yes |          |          |  |
| Drift (Y/N)   | No  |          |          |  |
| <b>Barrel General Rating</b>  |     | <b>5</b> | <b>N</b> | GR 5-07-Dec-1999<br>G.R carried forward. |
| Downstream End  |     |          |          |  |
| Culvert Component   |     | Last     | Now      | Explanation of Condition                 |
| Direction   |     | S        |          |  |
| End Treatment (Concrete, Steel, Others, None)   |     | STEEL    |          |  |
| Headwall  |     | X        | X        | Water below crown 700mm.                 |
| Collar  |     | X        | X        |  |
| Wingwalls   |     | X        | X        |  |
| (Shape : )  |     |          |          |  |
| Cutoff Wall   |     | X        | X        |  |
| Bevel End   |     | N        | 5        |  |
| Heaving (mm)  | 50  |          |          |  |
| Invert Above/Below Stream Bed   |     |          |          | End of bevel under water.                |
| Above/Below (mm)  | 0   |          |          |  |
| Scour Protection  |     | N        | 5        |  |
| (Type : <b>NATURAL</b> )  |     |          |          |  |
| (Avg. Rock Size(mm) : )   |     |          |          |  |
| Scour/Erosion   |     | N        | 5        |  |
| Beavers (Y/N)   |     | No       |          |  |
| <b>Downstream End General Rating</b>  |     | <b>5</b> | <b>5</b> |  |
| Structure Usage   |     |          |          |  |
|   |     | Last     | Now      | Explanation of Condition                 |
| Channel (U/S and D/S)   |     |          |          |  |
| Alignment   |     | 7        | 7        |  |
| Bank Stability  |     | 8        | 7        |  |
| HWM (m below Top of Culvert)  |     |          |          | HWM not visible.                         |
| Drift (Y/N)   |     | No       |          |  |
| Channel Bottom Degrading/Aggrading  |     | NONE     |          | Stable<br>B/D 25m u/s of invert.         |
| Beavers (Y/N)   |     | Yes      |          |  |
| (Fish Compensation Measure 1 : <b>NONE</b> )  |     |          |          |  |
| (Fish Compensation Measure 2 : <b>NONE</b> )  |     |          |          |  |
| <b>Channel General Rating</b>   |     | <b>7</b> | <b>7</b> |  |

| Maintenance Recommendations                       |  |  |                           |               |           |                    |    |
|---|--|--|---------------------------|---------------|-----------|--------------------|----|
| Inspector Recommendations                         | Year   | Inspector Comments                       | Department Comments       | Target Year   | Est. Cost | Cat #              |    |
| SHOTCRETE REPAIRS                                 |  |  |                           |               |           |                    |    |
| PLACE ADDITIONAL RIP RAP                          |  |  |                           |               |           |                    |    |
| REMOVE DRIFT ACCUMULATION                         |  |  |                           |               |           |                    |    |
| INSTALL CONCRETE/STEEL LINING                     |  |  |                           |               |           |                    |    |
| INSTALL STRUTS                                    |  |  |                           |               |           |                    |    |
| INSTALL CONCRETE COLLAR/CUTOFF                    |  |  |                           |               |           |                    |    |
| REPAIR SEAMS                                      |  |  |                           |               |           |                    |    |
| OTHER ACTION                                      |  |  |                           |               |           |                    |    |
| OTHER ACTION                                      |  |  |                           |               |           |                    |    |
| OTHER ACTION                                      |  |  |                           |               |           |                    |    |
| OTHER ACTION                                      |  |  |                           |               |           |                    |    |
| <b>Structural Condition Rating (Last/Now) (%)</b> | <b>55.6/55.6</b>   | <b>Sufficiency Rating (Last/Now) (%)</b> | <b>60.6/59.8</b>          | Est. Repl. Yr | 2033      | Maint. Reqd. (Y/N) | No |
| Special Comments for Next Inspection              | Monitor deflections-13-Oct-2001<br>This barrel has not been accessible for 4 inspections, as per BIM manual, consider a level 2 inspection.<br><br>Since pipe is only 27 yrs old and looks good from ends, a level 2 is not recommended. |  | Department Comments       |               |           |                    |    |
| Maintenance Reviewed By                           |  |  | Date                      |               |           | Estimated Total    | 0  |
| Proposed Long-Term Strategy                       |  |  |                           |               |           |                    |    |
| On 3-Year Program (Y/N)                           |  |  |                           |               |           |                    |    |
| Proposed Action                                   |  |  |                           |               |           |                    |    |
| Previous Inspector's Name                         | Brian Pientsch   |  | Previous Assistant's Name | Tim Miskiman  |           |                    |    |
| Next Inspection Date                              | 25-Feb-2012  |  | Previous Inspection Date  | 28-Nov-2006   |           |                    |    |
| Inspection Cycle (Default) (months)               | 21   |  |                           |               |           |                    |    |
| Comment   |  |  |                           |               |           |                    |    |