

| Bridge Culvert Inspection |                              |  |                     |                |
|---------------------------|------------------------------|--|---------------------|----------------|
| Bridge File Number        | 80749 -1 Bridge Culvert      |  | Form Type           | CUL1           |
| Year Built                | 1984                         |  | Lot No.             | 4              |
| Bridge or Town Name       | HEATH                        |  | Inspector Name      | Jason Saly     |
| Located Over              | TRAIL-ANIMAL, OVER SP        |  | Inspector Class     | BR CLS A       |
| Located On                | 610:02 C1 7.908              |  | Assistant Name      |                |
| Water Body Cl./Year       |                              |  | Assistant Class     |                |
| Navigabil. Cl./Year       |                              |  | Inspection Date     | 30-Nov-2012    |
| Legal Land Location       | SE SEC 12 TWP 44 RGE 5 W4M   |  | Data Entry By       | Marcia Chavez  |
| Longitude, Latitude       | -110:35:47, 52:46:40         |  | Data Entry Date     | 15-Jan-2013    |
| Road Authority            | Alberta Transportation (AIT) |  | Reviewer Name       | John O'Brien   |
| Contract Main. Area       | CMA15                        |  | Review Date         | 14-Dec-2012    |
| Clear Roadway/Skew        | 9 /                          |  | Dept. Reviewer Name | Andrew Smikles |
| AADT/Year                 | 540 / 2011 (A)               |  | Dept. Review Date   | 17-Jan-2013    |
| Road Classification       | RCU-209-110                  |  | Follow-Up By        |                |
| Detour Length (km)        | 5                            |  |                     |                |

**Bridge Culvert Information**

|                          |        |      |                |      |        |               |                    |       |
|--------------------------|--------|------|----------------|------|--------|---------------|--------------------|-------|
| Number of Culverts       | 1      |      |                |      |        |               |                    |       |
| Pipe #                   | Barrel | Span | Rise (or Dia.) | Type | Length | Corr. Profile | Pl./Slab Thickness | Shape |
| 1                        | MAIN   | -    | 2200           | MP   | 25     | 125X26        | 2.8                | ROUND |
| Special Features         |        |      |                |      |        |               |                    |       |
| Special Features Comment |        |      |                |      |        |               |                    |       |

**Posting Information**

|                                      |                           |    |               |  |                  |    |      |    |               |  |                  |    |
|--------------------------------------|---------------------------|----|---------------|--|------------------|----|------|----|---------------|--|------------------|----|
| Required Vert. Clearance Posting (m) |                           |    |               |  |                  |    |      |    |               |  |                  |    |
| Posted Vertical Clearance (Y/N)      | No                        |    |               |  |                  |    |      |    |               |  |                  |    |
| Posted:                              | Lane                      | NB | On Bridge (m) |  | In Advance (Y/N) | No | Lane | SB | On Bridge (m) |  | In Advance (Y/N) | No |
| Remarks                              | Not required, cattlepass. |    |               |  |                  |    |      |    |               |  |                  |    |

**Utilities (Located at)**

|                     |            |  |  |  |  |               |                     |  |  |  |  |  |
|---------------------|------------|--|--|--|--|---------------|---------------------|--|--|--|--|--|
| Utility Attachments |            |  |  |  |  |               |                     |  |  |  |  |  |
| Telephone           | South r/w. |  |  |  |  | Gas           | Crossing 100m West. |  |  |  |  |  |
| Power               |            |  |  |  |  | Municipal     |                     |  |  |  |  |  |
| Others              |            |  |  |  |  | Problem (Y/N) | No                  |  |  |  |  |  |
| Remarks             |            |  |  |  |  |               |                     |  |  |  |  |  |

**Approach Road / Embankment**

|  |       | Last     | Now      | Explanation of Condition   |
|--|-------|----------|----------|--|
| Horizontal Alignment                             |       | 7        | 7        | Located between 2 horizontal curves, immediately West of a "T" intersection. |
| Vertical Alignment                               |       | 7        | 7        |  |
| Roadway Width (m)                                | 9.000 |          |          |  |
| Embankment                                       |       | 8        | N        | Snow covered.  |
| Sideslope (___:1)                                | 4.0   |          |          |  |
| (Height of Cover(m) : 1.2)                       |       |          |          |  |
| Guardrail (Y/N)                                  | Yes   |          |          | 22.4m along North shoulder.  |
| <b>Approach Road / Embankment General Rating</b> |       | <b>7</b> | <b>7</b> |  |

**Upstream End**

| Culvert Component                             |      | Last | Now | Explanation of Condition |
|---|------|------|-----|--------------------------|
| Direction                                     |      | S    |     |                          |
| End Treatment (Concrete, Steel, Others, None) | NONE |      |     |                          |
| Headwall                                      |      | X    | X   |                          |
| Collar  |      | X    | X   |                          |

| Upstream End  |             |          |          |  |
|---|-------------|----------|----------|--|
| Culvert Component   |             | Last     | Now      | Explanation of Condition   |
| Wingwalls<br>(Shape : )   |             | X        | X        |  |
| Cutoff Wall   |             | X        | X        |  |
| Bevel End   |             | X        | X        | Squared end.   |
| Heaving (mm)  | 0           |          |          |  |
| Invert Above/Below Stream Bed   | BELOW       |          |          |  |
| Above/Below (mm)  | 200         |          |          |  |
| Scour Protection<br>(Type : <b>NATURAL</b> )<br>(Avg. Rock Size(mm) : )                 |             | X        | N        | Snow covered.  |
| Scour/Erosion   |             | X        | X        |  |
| Beavers (Y/N)   | No          |          |          |  |
| <b>Upstream End General Rating</b>  |             | <b>7</b> | <b>7</b> |  |
| Bridge Culvert Barrel   |             |          |          |  |
| Culvert Component   |             | Last     | Now      | Explanation of Condition   |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP) |             |          |          |  |
| Barrel Last Accessible Date   | 30-Nov-2012 |          |          |  |
| <b>Special Features</b>   |             |          |          |  |
| Special Feature<br>(Type : )  |             |          |          |  |
| Special Feature<br>(Type : )  |             |          |          |  |
| Roof  |             | 5        | 5        | Hole in roof @ 11:00, R2, from construction near c/l.<br>Mower damage at N end.  |
| Measured Rise (mm)  | 2070        |          |          |  |
| Measured At Ring No.  | 2           |          |          |  |
| Sag (mm)  | 130         |          |          | (5.9%. 26Jan2010).   |
| Percent Sag   | 5           |          |          |  |
| Sidewall  |             | 4        | 4        | E sidewall has collision damage at N end.<br>Span at N end=2224=24mm<br>Span at mid=2337=137mm=6.2%<br>Span at S end=2222=22mm |
| Measured Span (mm)  | 2337        |          |          |  |
| Measured At Ring No.  |             |          |          |  |
| Deflection (mm)   | 137         |          |          | 6.2%   |
| Percent Deflection  | 6           |          |          |  |
| Floor   |             | N        | N        | Covered with dirt.   |
| Bulge (mm)  | 0           |          |          |  |
| Measured At Ring No.  |             |          |          |  |
| Abrasion (Y/N)  | No          |          |          |  |
| Circumferential Seams   |             | 8        | 7        |  |
| Separation (mm)   | 30          |          |          |  |
| Longitudinal Seams  |             | X        | X        |  |
| Total No. of Cracked Rings  |             |          |          |  |
| Total No. of Rings with Two Cracked Seams   |             |          |          |  |
| Min. Remaining Steel Between Cracks (mm)  |             |          |          |  |
| Proper Lap (Y/N)  |             |          |          |  |
| Longitudinal Stagger (Y/N)  |             |          |          |  |
| Coating   |             | 8        | 8        |  |
| Corrosion By Soil (Y/N)   | No          |          |          |  |
| Corrosion By Water (Y/N)  | No          |          |          |  |

| Bridge Culvert Barrel   |      |          |          |                          |
|---|------|----------|----------|--------------------------|
| Culvert Component   |      | Last     | Now      | Explanation of Condition |
| (Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2200, Type: MP) |      |          |          |                          |
| Camber POS/ZERO/NEG   | ZERO |          |          |                          |
| Ponding (Y/N)   | No   |          |          |                          |
| Fish Passage Adequacy   |      | X        | X        |                          |
| Baffle  |      | X        | X        |                          |
| (Type : )   |      |          |          |                          |
| Waterway Adequacy   |      | X        | X        |                          |
| Icing (Y/N)   | No   |          |          |                          |
| Siltng (Y/N)  | No   |          |          |                          |
| Drift (Y/N)   | No   |          |          |                          |
| <b>Barrel General Rating</b>  |      | <b>4</b> | <b>4</b> |                          |

| Downstream End                                |       |          |          |  |
|---|-------|----------|----------|--|
| Culvert Component                             |       | Last     | Now      | Explanation of Condition                 |
| Direction                                     |       | N        |          |  |
| End Treatment (Concrete, Steel, Others, None) | NONE  |          |          |  |
| Headwall                                      |       | X        | X        |  |
| Collar  |       | X        | X        |  |
| Wingwalls                                     |       | X        | X        |  |
| (Shape : )                                    |       |          |          |  |
| Cutoff Wall                                   |       | X        | X        |  |
| Bevel End                                     |       | X        | X        | Accident damage to NE side. Squared end. |
| Heaving (mm)                                  | 0     |          |          |  |
| Invert Above/Below Stream Bed                 | BELOW |          |          |  |
| Above/Below (mm)                              | 300   |          |          |  |
| Scour Protection                              |       | X        | N        | Snow covered.                            |
| (Type : <b>NONE</b> )                         |       |          |          |  |
| (Avg. Rock Size(mm) : )                       |       |          |          |  |
| Scour/Erosion                                 |       | X        | X        | Snow covered.                            |
| Beavers (Y/N)                                 | No    |          |          |  |
| <b>Downstream End General Rating</b>          |       | <b>4</b> | <b>4</b> |  |

| Structure Usage         |    |      |     |                          |
|-------------------------|----|------|-----|--------------------------|
|                         |    | Last | Now | Explanation of Condition |
| <b>Grade Separation</b> |    |      |     |                          |
| Road Alignment          |    | 7    | 7   |                          |
| Roadway Surface         |    | 7    | 7   |                          |
| (Type : <b>GRAVEL</b> ) |    |      |     |                          |
| Icing (Y/N)             | No |      |     |                          |
| Traffic Safety Features |    | X    | X   |                          |
| Type                    |    |      |     |                          |
| Lighting                |    | X    | X   |                          |
| Barrel Leakage (Y/N)    | No |      |     |                          |

| <b>Structure Usage</b>                 |    |             |            |  |
|--|----|-------------|------------|--|
|  |    | <b>Last</b> | <b>Now</b> | <b>Explanation of Condition</b>          |
| Drainage                               |    | 7           | 7          |  |
| Structure In Use (Y/N)                 | No |             |            | Fences taken down @ North. Gate @ South. |
| <b>Grade Separation General Rating</b> |    | <b>7</b>    | <b>7</b>   |  |

| Maintenance Recommendations                       |  |  |                     |               |           |                    |    |
|---|--|--|---------------------|---------------|-----------|--------------------|----|
| Inspector Recommendations                         | Year   | Inspector Comments                       | Department Comments | Target Year   | Est. Cost | Cat #              |    |
| SHOTCRETE REPAIRS                                 |  |  |                     |               |           |                    |    |
| PLACE ADDITIONAL RIP RAP                          |  |  |                     |               |           |                    |    |
| REMOVE DRIFT ACCUMULATION                         |  |  |                     |               |           |                    |    |
| INSTALL CONCRETE/STEEL LINING                     |  |  |                     |               |           |                    |    |
| INSTALL STRUTS                                    |  |  |                     |               |           |                    |    |
| INSTALL CONCRETE COLLAR/CUTOFF                    |  |  |                     |               |           |                    |    |
| REPAIR SEAMS                                      |  |  |                     |               |           |                    |    |
| OTHER ACTION                                      |  |  |                     |               |           |                    |    |
| OTHER ACTION                                      |  |  |                     |               |           |                    |    |
| OTHER ACTION                                      |  |  |                     |               |           |                    |    |
| OTHER ACTION                                      |  |  |                     |               |           |                    |    |
| <b>Structural Condition Rating (Last/Now) (%)</b> | <b>44.4/44.4</b>   | <b>Sufficiency Rating (Last/Now) (%)</b> | <b>65.0/65.1</b>    | Est. Repl. Yr | 2028      | Maint. Reqd. (Y/N) | No |
| Special Comments for Next Inspection              | Cattlepass not in use; do not bother straightening N end until rancher requests it or it sees some use.  |  | Department Comments |               |           |                    |    |
| Maintenance Reviewed By                           |  |  | Date                |               |           | Estimated Total    | 0  |
| Proposed Long-Term Strategy                       |  |  |                     |               |           |                    |    |
| On 3-Year Program (Y/N)                           | Y  |  |                     |               |           |                    |    |
| Proposed Action                                   | 2008.03.30 Review in 2 years for continued usage. Suggest inspection by Bridges for lack of guardrail, sag and culvert damage. Brownlee & Associates |  |                     |               |           |                    |    |
| Previous Inspector's Name                         | Owen Salava  | Previous Assistant's Name                |                     |               |           |                    |    |
| Next Inspection Date                              | 29-Feb-2016  | Previous Inspection Date                 | 26-Jan-2010         |               |           |                    |    |
| Inspection Cycle (Default) (months)               | 39   |  |                     |               |           |                    |    |
| Comment   |  |  |                     |               |           |                    |    |