

Bridge Culvert Inspection			
Bridge File Number	80852 -1 Bridge Culvert	Form Type	CUL1
Year Built	1985	Lot No.	4
Bridge or Town Name	BODO	Inspector Name	Jason Saly
Located Over	TRIBUTARY TO EYEHILL CREEK, 4.2, WATERCRS-ST	Inspector Class	BR CLS A
Located On	899:08 C1 35.115	Assistant Name	
Water Body Cl./Year		Assistant Class	
Navigabil. Cl./Year		Inspection Date	08-Jun-2011
Legal Land Location	SE SEC 17 TWP 37 RGE 1 W4M	Data Entry By	Marcia Chavez
Longitude, Latitude	-110:06:33, 52:10:20	Data Entry Date	28-Jun-2011
Road Authority	Alberta Transportation (AIT)	Reviewer Name	John O'Brien
Contract Main. Area	CMA22	Review Date	18-Jun-2011
Clear Roadway/Skew	12 /	Dept. Reviewer Name	Chris Black
AADT/Year	380 / 2010 (A)	Dept. Review Date	30-Jun-2011
Road Classification	RCU-209-110	Follow-Up By	
Detour Length (km)	5		

**Bridge Culvert Information**

Number of Culverts	1							
Pipe #	Barrel	Span	Rise (or Dia.)	Type	Length	Corr. Profile	Pl./Slab Thickness	Shape
1	MAIN	-	2000	MP	28	125X26	2.8	ROUND
Special Features								
Special Features Comment								

**Utilities (Located at)**

Utility Attachments			
Telephone	South r/w	Gas	
Power	South r/w - 3 wire.	Municipal	
Others		Problem (Y/N)	No
Remarks			

**Approach Road / Embankment**

	Last	Now	Explanation of Condition
Horizontal Alignment	9	7	RR intersection approx. 550m E; land access at SE. (North side measured.) 01-Dec-2004
Vertical Alignment	9	8	
Roadway Width (m)	9.700		
Embankment	N	7	
Sideslope ( __:1)	5.0		
(Height of Cover(m) : )			
Guardrail (Y/N)	No		
<b>Approach Road / Embankment General Rating</b>	<b>9</b>	<b>7</b>	

**Upstream End**

Culvert Component	Last	Now	Explanation of Condition
Direction	S		
End Treatment (Concrete, Steel, Others, None)	STEEL		
Headwall	X	X	
Collar	X	X	
Wingwalls	X	X	
(Shape : )			
Cutoff Wall	X	X	

Upstream End				
Culvert Component		Last	Now	Explanation of Condition
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	100			
Scour Protection		N	7	Some rock.
(Type : <b>NATURAL</b> )				
(Avg. Rock Size(mm) : )				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Upstream End General Rating</b>		<b>8</b>	<b>7</b>	
Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)				
Barrel Last Accessible Date	08-Jun-2011			
Special Features				
Special Feature				
(Type : )				
Special Feature				
(Type : )				
Roof		N	6	Rise at S end=1930=70mm Rise at midpt=1948=52mm Rise at N end=1926=74mm=3.7%
Measured Rise (mm)	1926			
Measured At Ring No.				
Sag (mm)	74			
Percent Sag	4			
Sidewall		N	6	Side has small dent 2nd section from S. Span at S end=2022=22mm Span at midpt=2018=18mm Span at N end=2039=39mm=2.0%
Measured Span (mm)	2039			
Measured At Ring No.				
Deflection (mm)	39			
Percent Deflection	2			
Floor		N	7	
Bulge (mm)	0			
Measured At Ring No.				
Abrasion (Y/N)	No			
Circumferential Seams		N	7	
Separation (mm)	20			
Longitudinal Seams		X	X	
Total No. of Cracked Rings				
Total No. of Rings with Two Cracked Seams				
Min. Remaining Steel Between Cracks (mm)				
Proper Lap (Y/N)				
Longitudinal Stagger (Y/N)				
Coating		N	6	Minor.
Corrosion By Soil (Y/N)	No			
Corrosion By Water (Y/N)	Yes			
Camber POS/ZERO/NEG	ZERO			
Ponding (Y/N)	No			

Bridge Culvert Barrel				
Culvert Component		Last	Now	Explanation of Condition
(Pipe # : 1, Primary Span, Location Code: MAIN, Span (mm): , Rise (mm): 2000, Type: MP)				
Fish Passage Adequacy		X	X	
Baffle		N	X	
(Type : )				
Waterway Adequacy		N	7	
Icing (Y/N)	No			
Silting (Y/N)	No			
Drift (Y/N)	Yes			Few twigs & rocks.
<b>Barrel General Rating</b>		<b>N</b>	<b>6</b>	
Downstream End				
Culvert Component		Last	Now	Explanation of Condition
Direction		N		
End Treatment (Concrete, Steel, Others, None)	STEEL			
Headwall		X	X	
Collar		X	X	
Wingwalls		X	X	
(Shape : )				
Cutoff Wall		X	X	
Bevel End		N	7	
Heaving (mm)	0			
Invert Above/Below Stream Bed	BELOW			
Above/Below (mm)	200			
Scour Protection		N	7	Well vegetated.
(Type : RIP RAP)				
(Avg. Rock Size(mm) : 450)				
Scour/Erosion		N	7	
Beavers (Y/N)	No			
<b>Downstream End General Rating</b>		<b>8</b>	<b>7</b>	
Structure Usage				
		Last	Now	Explanation of Condition
<b>Channel (U/S and D/S)</b>				
Alignment		N	6	80 deg. bend at u/s end. N opens into field.
Bank Stability		N	7	
HWM (m below Top of Culvert)				
Drift (Y/N)	No			
Channel Bottom Degrading/Aggrading	NONE			
Beavers (Y/N)	No			
(Fish Compensation Measure 1 : NONE)				
(Fish Compensation Measure 2 : NONE)				
<b>Channel General Rating</b>		<b>6</b>	<b>6</b>	

Maintenance Recommendations							
Inspector Recommendations	Year	Inspector Comments	Department Comments	Target Year	Est. Cost	Cat #	
SHOTCRETE REPAIRS							
PLACE ADDITIONAL RIP RAP							
REMOVE DRIFT ACCUMULATION							
INSTALL CONCRETE/STEEL LINING							
INSTALL STRUTS							
INSTALL CONCRETE COLLAR/CUTOFF							
REPAIR SEAMS							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
OTHER ACTION							
<b>Structural Condition Rating (Last/Now) (%)</b>	<b>55.6/66.7</b>	<b>Sufficiency Rating (Last/Now) (%)</b>	<b>74.6/71.4</b>	Est. Repl. Yr	2039	Maint. Reqd. (Y/N)	No
Special Comments for Next Inspection	Not being used as a cattlepass. Fencing on N side placed above pipe.		Department Comments				
Maintenance Reviewed By			Date			Estimated Total	0
Proposed Long-Term Strategy	2007.06.11 Bridge Branch should review drainage to ensure that a cattlepass is appropriate. Examine to determine if guardrails are required for safety.						
On 3-Year Program (Y/N)							
Proposed Action							
Previous Inspector's Name	Bryan Wai		Previous Assistant's Name				
Next Inspection Date	08-Sep-2014		Previous Inspection Date	27-Mar-2008			
Inspection Cycle (Default) (months)	39						
Comment							